

PRE-ASSIGN

INS. CASE OWNER

Joel

CC 6 /EQI1801

5655, 4667

LKK

IDAC

Surveyor

marcus

DOI

ASSIGNMENT

26/8/18

Date / Time

26/8/18

Registered in Meritmen

Pre-assign / CCU / FTE



Insured Vehicle No.

GBA 96045

Name of Insured

KYM LEASING WP

Insured Tel No.

HP

Excess Sec II :SS

D.O.A

26/8/18

Is driver the owner?

(YES / NO)

Nature of Accident

If NO, Driver Name / Age

AZMAN SHAM BIN AMAS

Driver Tel No.

(VL: YES / NO)

Claim No.

Policy No.

Make / Model

Place of Accident

001618-00044

Toyota

PERMAYONG AVE 3

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLC 2761E



INSRS:
WSP:
Tel:
Liability:
RMKS:

stytech



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

6/9/18
poklin

SLC 2761E - X

GBA 96045 - 7

Pending Estimate to upload PA ✓
Leasing company, file review, Email to new collision
BOLA 21, send letter to OI

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OI

After call Itr to OI

CH 14/9/18

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

PRELIMINARY ADVICE

Date/Time

Sent By

CPK

FINALIZATION

Date/Time

Confirm with

Confirm by

Repair Cost

SS 6,748.00

(6 days) Reduction

123

%

Email

Call

FINAL SETTLEMENT

Date/Time

Confirm with

Winston

Email

Call

Final Liability

%

00

(Agreed / Assessed)

BOLA S/N No.

27

If NO or B 28, Ass. Lia

Repair Cost

SS 7,149.00

Loss of Rental (LOR)

SS 749.00

(7 days)

24/00.00 + 7/6 GST

Loss of Use (LOU)

SS -

15

x

days

Loss of Income (LOI)

SS -

15

x

days

LOR only

LOU only

LOR + LOI

LOR + LO

(Tick only one)

GIA/LTA Search

SS -

Medical

SS -

Disbursement

SS -

(e.g. Tow / Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format

TP

3) Survey fee

\$400.00

Total

SS 7,918.00

Global Sum SS

FINAL PAYMENT

Date/Time

Confirm with

Email

Call

Payee 1

SS 7,918.00

Name 1

Stytech Auto Pte Ltd

Payee 2 (Strike if N.A.)

SS

Name 2

Payee 3 (Strike if N.A.)

SS

Name 3

Front to rear collision

COPY SENT
11/10/18

OIC
OIC 2/10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI18015655/Ufb3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 28-08-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 9605S	Veh. Inspected	SLC 3361E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/08/2018	Inspection Date	28/08/2018	
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

f

1/5 \$6700

28/8/18 Gd.

not Albert
2 weeks before pay

Vehicle: SLC3361E

Make & Model:

Suzuki Ciaz

Chassis No:

MMSCVC41S00100042

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bumper 624.28			\$ 820.00	D.S. —
2	Rear Bumper Inner Sponge			\$ 160.00	To P.A. ✓
3	Rear Bumper Reflector Lamp	2	\$ 85.00	\$ 170.00	11 X
4	Rear Bumper Clips			\$30 SN	see — S.N
5	Rear Bumper Retainer	2	\$ 48.00	\$ 96.00	see —
6	Rear Bumper Reflector Garnish Cover	2	\$ 95.00	\$ 190.00	q/s Torn l/c
7	Rear Bumper Reflector	2	\$ 88.00	\$ 176.00	11 X
8	Rear Bumper Lower Spoiler Kit 924.35			\$ 985.00	D.S./To. —
9	Rear End Panel 493.70			\$ 820.00	S. 1/200 —
10	Rear End Panel Rubber			\$ 185.00	7m. —
11	Rear End Panel Garnish 171.10			\$ 198.00	7m. —
12	Rear End Panel Garnish Clips			\$30 SN	11 X
13	Rear End Panel Striker			\$ 35.00	11 X
14	Rear Bootlid 1437.50			\$ 1438.00	R. 1/500 —
15	Rear Boot Inner Garnish			\$ 120.00	11 X
16	Rear Boot Lock			\$ 195.00	7m. —
17	Rear Boot Hinge	2	\$ 90.00	\$ 180.00	R X
18	Rear Boot Moulding			\$ 180.00	see/cro —
19	Rear Boot Reflector Lamp	2	\$ 180.00	\$ 360.00	Cue —
20	Rear Boot Spoiler Kit 750			\$ 968.00	w/ 2000/cro —
21	Rear Boot Third Brake Lamp (LED)			\$ 200.00	11 X
22	Rear Boot Number Plate Lamp			\$ 78.00	11 X
23	Rear Boot Number Plate Lamp Garnish			\$ 96.00	7m. —

15%

1	Remove & Refix Rear Windscreen			\$ 120.00	24X
2	Check Wiring			\$ 100.00	30
3	Anti Rust Proofing			\$ 120.00	80
4	Panel Beating			\$ 1,400.00	850
5	Paintwork			\$ 1,200.00	1100
6	Interior Upholstery			\$ 120.00	80

Subo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be insured and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

28/8/18 Gd.

not submit
2 car
to high before pay.

Vehicle: SLC3361E

Make & Model:

Suzuki Ciaz

Chassis No:

MMSCVC41S00100042

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bumper			\$ 820.00	D.S. ✓
2	Rear Bumper Inner Sponge			\$ 160.00	to P.A. ✓
3	Rear Bumper Reflector Lamp	2	\$ 85.00	\$ 170.00	11 X
4	Rear Bumper Clips			\$30 SN	rec ✓
5	Rear Bumper Retainer	2	\$ 48.00	\$ 96.00	5.4 ✓
6	Rear Bumper Reflector Garnish Cover	2	\$ 95.00	\$ 190.00	o/s Torn l/c
7	Rear Bumper Reflector	2	\$ 88.00	\$ 176.00	11 X
8	Rear Bumper Lower Spoiler Kit			\$ 985.00	D.S./to. ✓
9	Rear End Panel			\$ 820.00	5.4 ✓
10	Rear End Panel Rubber			\$ 185.00	7m ✓
11	Rear End Panel Garnish			\$ 198.00	7m ✓
12	Rear End Panel Garnish Clips			\$30 SN	11 X
13	Rear End Panel Striker			\$ 35.00	11 X
14	Rear Bootlid			\$ 1438.00	B. 5.00 ✓
15	Rear Boot Inner Garnish			\$ 120.00	11 X
16	Rear Boot Lock			\$ 195.00	7m ✓
17	Rear Boot Hinge	2	\$ 90.00	\$ 180.00	R X
18	Rear Boot Moulding			\$ 180.00	sub/cro ✓
19	Rear Boot Reflector Lamp	2	\$ 180.00	\$ 360.00	o/s cro l/c
20	Rear Boot Spoiler Kit			\$ 968.00	w/rep/cro ✓
21	Rear Boot Third Brake Lamp (LED)			\$ 200.00	11 X
22	Rear Boot Number Plate Lamp			\$ 78.00	11 X
23	Rear Boot Number Plate Lamp Garnish			\$ 96.00	7m ✓

[illegible]

1	Remove & Refix Rear Windscreen			\$ 120.00	max
2	Check Wiring			\$ 100.00	30
3	Anti Rust Proofing			\$ 120.00	80
4	Panel Beating			\$ 1,400.00	850
5	Paintwork			\$ 1,200.00	1100
6	Interior Upholstery			\$ 120.00	80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Wednesday, 26 September 2018 6:16 PM
To: 'Stytech Auto Pte Ltd'
Subject: RE: Our Ref: CC6/EQ18015655/Ufb3; Your Ref: SAPL/98866/09/18
Attachments: TP LOD SLC 3361E.pdf
Importance: High

Dear Winston,

Attached herewith a copy of your letter of demand for your kind attention.

kindly furnish us a copy of Rental Agreement for payment processing.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Stytech Auto Pte Ltd [mailto:stytechent@singnet.com.sg]
Sent: Wednesday, 26 September 2018 2:29 PM
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Subject: RE: Our Ref: CC6/EQ18015655/Ufb3; Your Ref: SAPL/98866/09/18

Dear Poh Kin,

As spoken in phone earlier.

Please scan the SLC3361E LOD to me, Thank you.

Best Regards

Winston Teo

Stytech Auto Pte Ltd

Email: stytechent@singnet.com.sg | Mobile: +65 9685 8843 | Fax: +65 6445 3310

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 25 September 2018 3:52 PM
To: 'stylechent@singnet.com.sg'
Subject: Our Ref: CC6/EQ18015655/Ufb3; Your Ref: SAPL/98866/09/18
Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/EQ18015655/Ufb3
Your Ref: SAPL/98866/09/18

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE GBA 9605S AND SLC 3361E ON 26/08/2018

We refer to the above matter and your letter of demand dated 7th September 2018.

We hereby confirm settlement as below:

1. Cost of Repair (w/GST)	S\$ 7,169.00
2. Loss of Rental (\$100.00 x 7 days)+7%GST	S\$ 749.00
3. LTA search	S\$ 2.00
	S\$ 7,920.00

Please note that no DV is required and kindly furnish us a copy of Rental Tax Invoice for payment processing.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Saturday, 8 September 2018 2:01 PM
To: 'Joel Goh'
Cc: Admin A; Shu Pei (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving GBA96055 (OI : EQI - TBA) AND SLC3361E (TP : LKK REF -CC6/EQI18015655/Ufb3) on 26.08.2018
Attachments: LKK SURVEY PHOTO.pdf; Preliminary Advice.pdf; TP Estimate-Marked.pdf
Importance: High

Your Ref: **TBA**
LKK REF: CC6/EQI18015655/Ufb3

Dear Joel,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Thursday, 30 August 2018 9:39 AM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-132267

Date of Request: 28/08/2018

Your Ref No.:

Online Purchase

Stytech Auto Pte Ltd
2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autohub
Singapore 417921

Dear Sir/Madam,

Enquiry Date	28/08/2018
Enquiry By	Teo CHoon Kiat Winston
TP Vehicle No.	GBA9605S
Accident Date	28/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBA9605S	EQ Insurance Company Ltd	27/03/2018-26/03/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

 > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	2077G

Vehicle Details

Vehicle No.:	SLC3361E
Vehicle to be Exported:	No
Intended De-registration Date:	29 Aug 2018
Vehicle Make:	SUZUKI
Vehicle Model:	CIAZ 1.4 GLS AT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	K14BS128531
Chassis No.:	MMSCVC41S00100042
Maximum Power Output:	68.0 kW (91 bhp)
Open Market Value:	\$16,745.00
Original Registration Date:	11 May 2016
First Registration Date:	11 May 2016
Transfer Count:	0
Actual ARF Paid:	\$11,745.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 May 2026
PARF Rebate Amount:	\$8,808.00

Intended COE Rebate Details

COE Expiry Date:	10 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$36,403.00
Total Rebate Amount:	\$45,211.00

The information contained herein is correct as at 28 Aug 2018

OK

Shu Pei (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 30 August 2018 9:39 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Poh Kin (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBA9605S (OI : EQI - TBA) AND SLC3361E (TP : LKK REF -CC6/EQI18015655/Ufb3) on 26.08.2018
Attachments: GBA9605S.PDF

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh

Executive Director



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block KINEX Complex, Singapore 069110

did 65 6540 6772 | tel 65 6223 9413 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Crystalline

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

Sent: Thursday, August 30, 2018 9:24 AM

To: Joel Goh

Cc: Admin A; Poh Kin (LKKAUTO)

Subject: Direct Settlement - Accident Involving GBA9605S (OI : EQI - TBA) AND SLC3361E (TP : LKK REF - CC6/EQI18015655/Ufb3) on 26.08.2018

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLC 3361E at M/s Stytech Auto Pte Ltd.

Enclosed for your perusal is:

- TP's GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.



Kindly take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98866/09/18

Date: 7/9/2018

To: M/S EQ Insurance Company Ltd
5 Maxwell Rd #17-00
Tower Block MND Complex
Singapore 069110
Attn: Motor Claim Dept

Dear Sir/Mdm,

Re: Claim of repair cost & loss of use for veh no.SLC 3361-E

<u>No.</u>	<u>Description</u>	<u>Price</u>
1.	Lump Sum Repair Cost for Vehicle No.SLC 3361-E	S\$7,169.00
2.	Loss of use for Rental Bill NR: 32052(100X7Days) (Plus One Sunday)	S\$ 749.00
3.	GIA Search Fee	S\$ 2.00
Total:		<u>S\$7,920.00</u>



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/EQI18015655/Ufb3

8th September 2018

KYM LEASING LLP

3023A Ubi Road 1,
#01-57,
Singapore 408717.

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBA 9605S AND SLC 3361E ALONG SERANGOON AVENUE 3 ON 26.08.2018.

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

Date: 28/08/18

M/S

Car Club Pte Ltd
60, Payohuber Road
#06-43 Payohuber Square
S'pore 419501

To: M/S STYTECH AUTO PTE LTD
2 Kaki Bukit Avenue 2, #02-30
Kaki Bukit Autohub
Singapore 417921

Dear Sir/Mdm,


Repair Cost for Vehicle Number SLC 3361E
Caused by accident dated on 26/08/18 involving vehicle/s number SLC 3361E
X GBA 96058 at Serangoon Ave 2

Our Company / I, Car Club Pte Ltd
vehicle number SLC 3361E hereby authorized you to liaise with the insurance
company and undertake all repairs & any other damages incurred as I am involved in the accident dated
on 26/08/18

All legal & repair costs will be deducted from the proceeds of my claim and be released to M/S STYTECH
AUTO PTE LTD.

Thank you.

Yours Faithfully





STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98866/09/18

Date: 7/9/2018

To: M/S EQ Insurance Company Ltd
5 Maxwell Road #17-00
Tower Block MND Complex
S'pore 069110
Attn: Motor Claim Dept

Dear Sir/Mdm,

Re: Accident on 26/8/2018 involving veh nos: SLC 3361-E & GBA 9605-S Along Serangoon Ave 02.

FINAL BILL FOR VEHICLE NO. SLC 3361-E

<u>DESCRIPTION</u>	<u>PRICE</u>
Lump Sum Repair Cost for Vehicle No. SLC 3361-E	S\$6,700.00
GST 7%	S\$ 469.00
TOTAL:	<u>S\$7,169.00</u>

Yours Faithfully,
STYTECH AUTO PTE LTD

Mr. Winston Teo
9685 8843



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

M/s Car Club Pte Ltd

Att:


INVOICE : 32052
TAX INVOICE

Vehicle No. : SKP9949P
Make : TOYOTA ALTIS 1.6

Date : 05th Sept 2018
Terms :
Yours Ref : SLC3361E

S/No.			Amount
	(SKP9949P) Rental for 7 days 28/08/18 - 04/09/18 Ref:	\$ 100.00	\$ 700.00
		GST 7%	\$ 49.00
			\$ 749.00

All Cheques should be crossed and made payable to STYTECH AUTO PTE LTD


STYTECH AUTO PTE LTD

Thank you for your business !



SLC 3361E

STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
 TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
 GST REG. NO: 201601539K CO. REG. NO: 201601539K

NR No: 32052

Vehicle No: SKP 9949P	Make and Type: TOYOTA ACTIS
Date/Time Out: 28/08/18 9:00am	Date/Time In: 04/09/18 10:10am

Fuel Gauge EXTENSION CHARGES IS \$12.00 PER HOUR (SINGAPORE USE)
 DEPOSIT WILL BE FORFEITED IN ANY ACCIDENT/DAMAGE/FIRE & THEFT
 *NO RETURNING OF VEHICLE AFTER 6 PM & EVE / PUBLIC HOLIDAY

Hirer's Name: Car Club Pte Ltd	KM OUT							KM IN				
Hirer's Address: 60 Paya Lebar Road #06-43	RENTALS CHARGES							AMOUNT				
Paya Lebar Square. S'pore 409501	7	Days at S\$	100/-	per day								\$700.00
Tel: 67881511 I/C:	Week at S\$							per week				
H/P: Age:	Month at S\$							per mth				
Driver's Name: Khao Quek Khing	Insurance fee to cover hired vehicle only											
Driver's Address: BK 123 Sime: S11 #08-404	Delivery/Collection fee											
Tel: I/C: 57129716J	Petrol/Diesel											
Age: 1971	Others											
Driving Licence Date: 16/5/01 Class: 3	Sub-Total											
Additional Driver's Name:	Add GST							7%				\$49.00
Driver's Address:	Total Nett Charges											\$749.00
Tel: I/C:	*Less Total Prepayment/Deposit Received											
Age:	Balance Amount Due/Refundable											
Driving Licence Date: Class:	Add : EXTENSION CHARGES											
Guarantor's Name:												
Guarantor's Address:												
Tel: I/C:												
Occupation: Age:												

IMPORTANT NOTES

- * This vehicle is restricted to SINGAPORE only.
- * No refund will be given for early return or fuel left in vehicle.
- * Hirer is liable to pay all parking fees, traffic summons & other claims.
- * Hirer who carries the number of passengers or load exceeding the MPC label will have to take their own responsibilities & LTA summons.
- * In the event of vehicle breakdown due to no fuel, hirer is liable to pay \$50 service charge plus cost of fuel/diesel.
- * No replacement of vehicle in any accident, damage or loss.
- * Hirer is responsible for the first \$1500/- excess for collision/damage/ fire or theft to first party (i.e. STYTECH AUTO PTE LTD) vehicle (including windscreen) and also first \$1500/- excess for collision/damage/fire & theft to third party's vehicle for each and every accident & damage.

METHOD OF PAYMENT

☐ Cash ☐ Cheque No: ☐ Visa ☐ Bill Co.

Refund Received \$ _____ By Hirer x _____

* In the event of the rental vehicle is not return on the date due & no contact is made to inform our company of any changes & payment after one week due. Our Company will take action & repossess the vehicle & a service charge of \$120.00 are subject to the Hirer inclusive of the overdue charges with an additional interest of 3% per month.

I/We have read the terms and conditions of the rental agreement and agree thereto:-

Hirer's Signature

Guarantor's Signature

STYTECH AUTO PTE LTD
Signed By



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 24/10/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBA 9605S (Insd Veh)	Your Ref. No. : DMCFHQ18-000044
	SLC 3361E (TP Veh)	Our Ref. No. : CC6/EQI18015655/Ufb3q2
Date of Accident	26/8/2018	

Liability	100%	
Final Repair Cost	: \$ 7,169.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 749.00	7 days
Others:	: \$	
	: \$	
	7,918.00	
Final Settlement Sum	: \$ 7,918.00	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	STYTECH AUTO PTE LTD	: \$ 7,918.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ18015655/Ufb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 24-10-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBA 9605S	Veh. Inspected	SLC 3361E
Policy No.	DMCFHQ18-000044	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/08/2018
2. Vehicle Particulars & Condition			
Make & Model	SUZUKI CIAZ (A)	c.c	1373
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MMSCVC41S00100042	Colour	SILVER
Odometer	41159	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	FALKEN	8 mm
L/H Front Tyre	195/55 R15	FALKEN	8 mm
R/H Rear Tyre	195/55 R15	FALKEN	8 mm
L/H Rear Tyre	195/55 R15	FALKEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/08/2018	Inspection Date	28/08/2018
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 3361E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	820.00	624.25
1	REAR BUMPER INNER SPONGE	TORN	160.00	160.00
2	REAR BUMPER REFLECTOR LAMP @\$85.00	NOT NECESSARY	170.00	-
2	REAR BUMPER RETAINER @\$48.00	BENT	96.00	96.00
2	REAR BUMPER REFLECTOR GARNISH COVER @\$95.00	O/S TORN	190.00	95.00
2	REAR BUMPER REFLECTOR @\$88.00	NOT NECESSARY	176.00	-
1	REAR BUMPER LOWER SPOILER KIT	DISTORTED / TORN	985.00	924.35
1	REAR END PANEL	BADLY DENTED	820.00	493.70
1	REAR END PANEL RUBBER	TWISTED	185.00	185.00
1	REAR END PANEL GARNISH	TWISTED	198.00	171.10
1	REAR END PANEL STRIKER	NOT NECESSARY	35.00	-
1	REAR BOOTLID	BADLY DENTED	1,438.00	1,437.50
1	REAR BOOT INNER GARNISH	NOT NECESSARY	120.00	-
1	REAR BOOT LOCK	TWISTED	195.00	195.00
2	REAR BOOT HINGE @\$90.00	TO REPAIR SEE LABOUR	180.00	-
1	REAR BOOT MOULDING	BENT / CRACKED	180.00	180.00
2	REAR BOOT REFLECTOR LAMP @\$180.00	CRACKED	360.00	360.00
1	REAR BOOT SPOILER KIT	WARPED / CRACKED	968.00	750.00
1	REAR BOOT THIRD BRAKE LAMP (LED)	NOT NECESSARY	200.00	-
1	REAR BOOT NUMBER PLATE LAMP	NOT NECESSARY	78.00	-
1	REAR BOOT NUMBER PLATE LAMP GARNISH	TWISTED	96.00	96.00
2	REAR TAIL LAMP @\$320.00	O/S CRACKED	640.00	295.00
4	REAR TAIL LAMP STOPPER @\$15.00	NOT NECESSARY	60.00	-
1	REAR BOOT 'SUZUKI' PLATE	NECESSARY	58.00	58.00
1	REAR BOOT 'S' PLATE	NECESSARY	42.00	35.00
1	REAR BOOT 'CIAZ' PLATE	NECESSARY	55.00	35.00
1	REAR BOOT 'RS' PLATE	NECESSARY	50.00	38.00
1	REAR END PANEL SENSOR	SHORTED	195.00	195.00
1	REAR SPARE TYRE BOOT SPONGE TRAY	TORN	180.00	180.00

Report Ref No. CC6/EQ118015655/Ufb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE BOOT CARDBOARD	NOT NECESSARY	280.00	-
1	RIGHT REAR TAIL LAMP PANEL	TO REPAIR SEE LABOUR	450.00	-
	LESS 15% DISCOUNT		-	-990.59
			9,660.00	5,613.31
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR END PANEL GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT CARCLUB STICKER (SN)	NECESSARY	20.00	20.00
1	SET REVERSE CAMERA (SN)	SHORTED	280.00	280.00
1	REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REAR PANEL JOINT SEALANT (SN)	NECESSARY	60.00	50.00
1	REAR NUMBER PLATE WITH CASING (SN)	BENT	50.00	40.00
			720.00	620.00
	LABOUR			
	REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	CHECK WIRING .		100.00	30.00
	ANTI RUST PROOFING .		120.00	80.00
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE AND RIGHT REAR TAIL LAMP PANEL .		1,400.00	850.00
	PAINTWORK.		1,200.00	1,100.00
	INTERIOR UPHOLSTERY .		120.00	80.00
			3,060.00	2,140.00
	GRAND TOTAL		13,440.00	8,373.31
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,700.00

Report Ref No. CC6/EQ18015655/Ufb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.