

28/8/18 Gd.

not Albert
2 high school party.

Vehicle: SLC3361E

Make & Model:

Suzuki Ciaz

Chassis No:

MMSCVC41S00100042

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bumper			\$ 820.00	D.S. ✓
2	Rear Bumper Inner Sponge			\$ 160.00	To P.A. ✓
3	Rear Bumper Reflector Lamp	2	\$ 85.00	\$ 170.00	11 X
4	Rear Bumper Clips			\$30 SN	ner ✓
5	Rear Bumper Retainer	2	\$ 48.00	\$ 96.00	Sub ✓
6	Rear Bumper Reflector Garnish Cover	2	\$ 95.00	\$ 190.00	o/s Tori l/c
7	Rear Bumper Reflector	2	\$ 88.00	\$ 176.00	11 X
8	Rear Bumper Lower Spoiler Kit			\$ 985.00	D.S./To. ✓
9	Rear End Panel			\$ 820.00	Sub ✓
10	Rear End Panel Rubber			\$ 185.00	Two ✓
11	Rear End Panel Garnish			\$ 198.00	Two ✓
12	Rear End Panel Garnish Clips			\$30 SN	11 X
13	Rear End Panel Striker			\$ 35.00	11 X
14	Rear Bootlid			\$ 1438.00	Sub ✓
15	Rear Boot Inner Garnish			\$ 120.00	11 X
16	Rear Boot Lock			\$ 195.00	Two ✓
17	Rear Boot Hinge	2	\$ 90.00	\$ 180.00	R X
18	Rear Boot Moulding			\$ 180.00	Sub/cnc ✓
19	Rear Boot Reflector Lamp	2	\$ 180.00	\$ 360.00	o/s cnc l/c
20	Rear Boot Spoiler Kit			\$ 968.00	Warpal/cnc ✓
21	Rear Boot Third Brake Lamp (LED)			\$ 200.00	11 X
22	Rear Boot Number Plate Lamp			\$ 78.00	11 X
23	Rear Boot Number Plate Lamp Garnish			\$ 96.00	Two ✓

24	Rear Tail Lamp	2	\$ 320.00	\$ 640.00	o/gene loc
25	Rear Tail Lamp Stopper	4	\$ 15.00	\$ 60.00	11X
26	Rear Boot "Suzuki" Plate			\$ 58.00	nr /
27	Rear Boot "S" Plate			\$ 42.00	nr /
28	Rear Boot "Ciaz" Plate			\$ 55.00	nr /
29	Rear Boot "RS" Plate			\$ 50.00	nr /
30	Rear Boot Carclub Sticker			\$20 SN	nr /
31	Reverse Camera			\$280 SN	shld ✓
32	Rear Fender Inner Shield Clips			\$50 SN	11X
33	Reverse Sensor	(157)		\$200 SN	shld ✓
34	Rear Panel Joint Sealant			\$60 SN	nr 505N
35	Rear End Panel Sensor			\$ 195.00	shld ✓
36	Rear Spare Tyre Boot Sponge Tray			\$ 180.00	To.1 /
37	Rear Spare Tyre Boot Cardboard			\$ 280.00	11X
38	Right Rear Tail Lamp Panel			\$ 450.00	R X
39	Rear Number Plate with Cosig			\$ 50.00 SN	shld / cos. N
Labour					

1	Remove & Refix Rear Windscreen			\$ 120.00	no X
2	Check Wiring			\$ 100.00	30
3	Anti Rust Proofing			\$ 120.00	80
4	Panel Beating			\$ 1,400.00	850
5	Paintwork			\$ 1,200.00	1100
6	Interior Upholstery			\$ 120.00	80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: