

INS. CASE OWNER:

CC 4, 16 180 15663, Clear

LKK:

IDAC:


Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S\$

D.O.A.:

Place of Accident :

Is driver the owner? ( YES / NO )

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date / Time

STAD 3620A - CS / PA 180 15348 / UFD : DUA 20/8/18  
 - CS / PA 117 007688 / H1232 : DUA 16/4/19  
 SKQ6411M - X

| STAGE                                    | DATE / PIC               |
|------------------------------------------|--------------------------|
| Non-Reporting ltr (1st):                 |                          |
| Non-Reporting ltr (2nd):                 |                          |
| Non-Reporting ltr (Final):               |                          |
| Notification ltr (if non-pickup):        |                          |
| Call OI:                                 |                          |
| After call ltr to OI:                    |                          |
| Documentation Check List: Handler Typist |                          |
| Notification ltr (if non-pickup)         | <input type="checkbox"/> |
| After call ltr to OI:                    | <input type="checkbox"/> |
| Authorisation To Act:                    | <input type="checkbox"/> |
| Release Voucher:                         | <input type="checkbox"/> |
| Final Repair Bill:                       | <input type="checkbox"/> |
| Car Rental Invoice:                      | <input type="checkbox"/> |
| Towing Invoice                           | <input type="checkbox"/> |
| LTA / GIA :                              | <input type="checkbox"/> |
| Medical Bill:                            | <input type="checkbox"/> |
| PIR:                                     | <input type="checkbox"/> |
| Mandate/Reject Instruction:              | <input type="checkbox"/> |
| LOD                                      | <input type="checkbox"/> |
| Payment Breakdown Form:                  | <input type="checkbox"/> |
| Post-Repair Photos:                      | <input type="checkbox"/> |
| Others:                                  | <input type="checkbox"/> |

## PRELIMINARY ADVICE

Date/Time:

Sent By:

## FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ ( days) Reduction: % Email ☐ Call ☐

## FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost: S\$

Loss of Rental (LOR): S\$ ( days)

Loss of Use (LOU): S\$ (\$ x days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost S\$

Total: S\$

Global Sum S\$:

## FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$

Name 1:

Payee 2: (Strike if N.A.) S\$

Name 2:

Payee 3: (Strike if N.A.) S\$

Name 3:

Surveyor

Kaluh

REF: ICS

# ASSIGNMENT

From: Date: 28082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 3620A

at Workshop m/s Comfort Delgro

of 59 Loyang Way

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHD3620A Yr Regn: 14 Sep / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 285537 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: J70KB3FY403530467

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65R15 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Wierlke.

Front Rear R/Bal. 7 mm L/Bal. 7 mm

D.O.A. 17/8/18 D.O.I. 28/8/18

Survey held at (PhE (Lym))

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation: S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

# COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

### Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

220 Ubi Road 3 Singapore 408603

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 27.08.2018 15:01

Page : 1

Team: ARC Repair TP(CLSO)1

## JOB CARD

Sales Order:

JC NO.: 305204888

OMER

IS

OMER NO.

IESS

(R)

(P)

COMFORT TRANSPORTATION PTE LTD

7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

OUNT CARD NO.

REGN NO.:

SHD3620A

MILEAGE

MAKE :

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)27.08.2018 11:15

DATE/TIME IN

YR OF MANU

14.09.2016

TARGET DATE

CHASSIS CODE

JTDKB3FU403530467

COMPLETION DATE/TIME:

## JOB DESCRIPTION

Accident Date: 17.08.2018


NATURE: 3P 17.08.18

S/NO

LABOR CODE

DESCRIPTION

FRONT



REAR

LEFT SIDE

RIGHT SIDE

BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.:

SHD3620A

LIMITS

Vehicle No.:

SHD3620A

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

## Outlook

Search Mail and People

New | Delete | Archive | Junk | Sweep | Move to | Categories | ...

## Folders

^ Favorites

Deleted Items

^ Lim Tien Siong

Inbox 1

Drafts 4

Sent Items

Deleted Items

Archive

Conversation His

Junk Email

v Migrated\_Emails

Notes

Unfiled

v Groups

## Accident involving SHD3620A &amp; your insured SKQ6411M dated 17.08.18

M

motorsurvey &lt;motorsurvey@ecics.com.sg&gt;

Mon 27/8/2018 5:55 PM

To: v Lim Tien Siong; assignments &lt;assignments@lkkauto.com&gt;

Cc: motorsurvey &lt;motorsurvey@ecics.com.sg&gt;

img-827163845-0001.pdf   
192 KB

Download Save to OneDrive - ComfortDelGro Corporation Limited



Action Items

Without Prejudice

Hi Tien Siong

Thank you for your email.  
We will appoint LKK for the PRS.

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. T understanding.\*\****

Getting too much email from motorsurvey <motorsurvey@ecics.com.sg>? You can unsubscribe

...

LS

Lim Tien Siong

Officer in charge. Best Regards, Lim Tien Siong Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd Off:62148398 / Fax:65468156

## REPAIR ESTIMATE

VEHICLE NO : SHD 3620A

27/8/2018

MAKE :

LKK - Kalvin

1650

MODEL : TOYOTA PRIUS

| PARTS DESCRIPTION                                 | QTY | UNIT PRICE | AMOUNT      |
|---------------------------------------------------|-----|------------|-------------|
| GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <del>✓</del> |     |            | \$ 889.70   |
| REAR TRUNK LID LOGO(PRIUS) ✓                      |     |            | \$ 60.80    |
| REAR TRUNK LID LOGO(HYBRID) ✓                     |     |            | \$ 52.40    |
| REAR TRUNK LID LOGO(TOYOTA STAR) ✓                |     |            | \$ 52.90    |
| REAR BUMPER ✓                                     |     |            | \$ 458.60   |
| REAR BUMPER RE-INFORCEMENT ?                      |     |            | \$ 322.30   |
| REAR BUMPER UNDER COVER ✓                         |     |            | \$ 552.60   |
| REAR BUMPER SPONGE ?                              |     |            | \$ 143.40   |
| REAR BUMPER UNDER SIDE COVER (LH) ?               |     |            | \$ 232.00   |
| REAR BUMPER CLIPS ✓                               |     |            | \$ 22.00    |
| ARM SUB-ASSY, REAR BUMPER, LH ?                   |     |            | \$ 139.60   |
| RETAINER, REAR BUMPER, SIDE, LH ?                 |     |            | \$ 94.80    |
| SEAL, REAR BUMPER SIDE, LH ✓                      |     |            | \$ 148.40   |
| TAIL LAMP ASSY (UPPER) (LH) ✓                     |     |            | \$ 557.90   |
| TAIL LAMP ASSY (LOWER) (LH) ✓                     |     |            | \$ 548.40   |
| SUB TOTAL                                         |     |            | \$ 4,275.80 |
| LESS 25%                                          |     |            | \$ 1,068.95 |
| DISCOUNTED TOTAL                                  |     |            | \$ 3,206.85 |
| REAR TRUNK LID APPS STICKER                       |     |            | \$ 40.00    |
| REAR TRUNK LID COMFORT & TEL NO. STICKER          |     |            | \$ 60.00    |
| REAR BUMPER REVERSE SENSOR                        |     |            | \$ 135.70   |
| REAR BUMPER RUBBER MAT                            |     |            | \$ 50.00    |
|                                                   |     |            | \$ 285.70   |
| LABOUR CHARGE                                     |     |            |             |
| Panel Beating                                     |     |            | \$ 400      |
| Spray Painting Charge                             |     |            | \$ 400      |
| Wiring Charge                                     |     |            | \$ 20       |
| Tuff Kote                                         |     |            | \$ 50.00    |
| Remove/Refix Reverse Sensor                       |     |            | \$ 120.00   |
| TOTAL LABOUR                                      |     |            | \$ 1,170.00 |
| ESTIMATE TOTAL                                    |     |            | \$ 4,662.55 |

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin H. H.

28/8/18 1030 L.

3 1/2

P/P

Before

Part photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305204888

Date : 30/08/18

### FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHD3620A

Date of Accident : 17-Aug-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: ECICS Limited --- SKQ6411M

2. The finalized amount shall be:

(a) Spare Parts after List discount \$2,743.48

(b) Labour Charges \$900.00

**Total for Part-By-Part Repair Cost \$3,643.48**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%


**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : KALVIN

Tel : 62148398

Date : 30/8/18

Fax : 65468156

### For Official Use Only

| Item                                                 | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        | NO                          |                        |         |
| 3. Survey Fees                                       | -----  |                             |                        |         |
| 4. LTA Search Fee                                    | \$7.49 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun                                           |        |                             |                        |         |

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305204888  
 REGN NO : SHD3620A  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 14.09.2016  
 DATE/TIME IN : 27.08.2018 11:15  
 ACCIDENT DATE : 17.08.2018

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|      |                   |                         |    |        |       |        |
|------|-------------------|-------------------------|----|--------|-------|--------|
| 0001 | 04-01-0302-2346-G | BOOTLID GARNISH         | 1  | 889.70 | 25.00 | 667.27 |
| 0002 | 04-01-0302-2269-G | BOOTLID (TOYOTA STAR)   | 1  | 52.90  | 25.00 | 39.67  |
| 0003 | 04-01-0302-2270-G | BOOTLID (HYBRID)        | 1  | 52.40  | 25.00 | 39.30  |
| 0004 | 04-01-0302-2271-G | BOOTLID (PRIUS)         | 1  | 60.80  | 25.00 | 45.60  |
| 0005 | 28-01-0302-0006-A | BOOTLID 65521111        | 1  | 30.00  |       | 30.00  |
| 0006 | 28-01-0302-2013-A | BOOTLID APPS STICKER    | 1  | 40.00  |       | 40.00  |
| 0007 | 28-01-0302-2015-A | BOOTLID COMFORTDELGRO   | 1  | 30.00  |       | 30.00  |
| 0008 | 04-01-0302-2282-G | REAR BUMPER             | 1  | 458.60 | 25.00 | 343.95 |
| 0009 | 04-01-0302-2287-G | REAR BUMPER UNDER COVER | 1  | 552.60 | 25.00 | 414.45 |
| 0010 | 04-01-0302-2267-G | REAR BUMPER CLIPS       | 10 | 22.00  | 25.00 | 16.50  |
| 0011 | 04-01-0302-0581-G | TAILLAMP UPR LH         | 1  | 557.90 | 25.00 | 418.42 |
| 0012 | 04-01-0302-0796-G | TAILLAMP LWR LH         | 1  | 548.40 | 25.00 | 411.30 |
| 0013 | 09-01-0302-2005-A | REVERSE SENSOR          | 1  | 135.70 |       | 135.70 |

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305204888  
REGN NO : SHD3620A  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 14.09.2016  
DATE/TIME IN : 27.08.2018 11:15  
ACCIDENT DATE : 17.08.2018

| JOB / PARTS DESCRIPTION                         | QTY | IND    | UNIT-PRICE | DISC% | AMOUNT |
|-------------------------------------------------|-----|--------|------------|-------|--------|
| 0014 04-01-0302-2865-G REAR BUMPER EXTENSION LH | 1   | 148.40 | 25.00      |       | 111.30 |

SUB-TOTAL : 2,743.46

JOB NATURE

|             |                             |        |
|-------------|-----------------------------|--------|
| 0000 L      | PANEL BEATING               | 400.00 |
| 0001 23-502 | SPRAYPAINT ON AFFECTED AREA | 400.00 |
| 0002 17-01  | CHECK ALL LIGHTING          | 20.00  |
| 0003 L      | R/I REVERSE SENSOR          | 30.00  |
| 0004 20-05  | REAR BUMPER MAT             | 50.00  |

SUB-TOTAL : 900.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 29.08.2018

Time: 18:10:59

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305204888  
REGN NO : SHD3620A  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 14.09.2016  
DATE/TIME IN : 27.08.2018 11:15  
ACCIDENT DATE : 17.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,643.46

  
\_\_\_\_\_  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :  
AUTHORISED : YES / NO