

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SGX2862G

Not Airborne
11 Sep 8?
Resony After Paint

6 days

No.	Qty	List Items			
1	1	Rear bumper	Bumper\$	682.95	✓
2	1	Rear bumper tow cover	\$	19.50	X
3	2	Rear bumper side retainer	\$	50.80	X
4	2	Rear bumper lower bracket	\$	44.00	?
5	1 set	Rear bumper clips	\$	30.00	✓
6	2	Taillamp	\$	838.60	✓
7	1	Rear tailgate	\$	984.80	✓
8	1	Rear tailgate outer handle garnish	\$	204.80	X
9	1	Rear tailgate outer handle garnish "H" logo	\$	29.30	X
10	1	Rear tailgate "STREAM" emblem	\$	44.90	✓
11	1 set	Rear tailgate windscreen moulding	\$	87.00	✓
12	1	Rear tailgate inner trim board	\$	214.50	X
13	1 set	Rear tailgate inner trim board clips	\$	50.00	X
14	1	Rear tailgate inner trim board lower pulling handle	\$	35.20	X
15	1	Rear tailgate top lock	\$	165.80	✓
16	1	Rear tailgate lower lock catch	\$	24.70	X
17	2	Rear tailgate damper	\$	215.20	X
18	1	Rear tailgate weatherstrip	\$	146.30	50/1m
19	1	Rear end panel	\$	452.00	?
20	1	Rear end panel top garnish	\$	136.50	?
21	1 set	Rear end panel top garnish clips	\$	30.00	?
22	2	Rear floor panel top board	\$	229.20	X
23	1	Rear lower spare tyre carrier	\$	186.30	?
24	1	Rear exhaust silencer	\$	685.60	?
25	2	Rear exhaust silencer mounting	\$	64.00	?
			\$	5,651.95	
			Less 20%	\$	1,130.39
			Total :	\$	4,521.56

<u>Special Nett Items</u>					
26	1 set	Rear bumper reverse camera	\$	550.00	3 cam
27	1 set	Rear tailgate reverse camera	\$	550.00	X
28	1	Rear number plate	\$	45.00	X
29	1 set	Rear windscreen sealant	\$	50.00	40cm
30	1 set	Rear end panel sealant	\$	50.00	?
			Total :	\$	1,245.00

<u>Labour</u>					
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.		\$	1,000.00	?
2	To putty and spray Spray Paintings charges.		\$	1,000.00	750l
3	To remove, refit rear windscreen.		\$	150.00	120l
4	To check wirings and lightings.		\$	40.00	20l
6	To remove, refit both reverse cameras.		\$	120.00	60l

7	To remove, refit rear upholstery and attachments.	\$	120.00	602
8	To remove, refit rear lower exhaust silencer.	\$	80.00	601
9	To supply and apply anti rust treatment	\$	80.00	601
Total :		\$	2,590.00	

Total Parts and Labour : \$ 8,356.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: