

QUOTATION FOR VEHICLE SLV 9078 J

PARTS				
1	1	REAR BUMPER	\$ CM 996.72	✓
2	1	REAR BUMPER CENTRE GRILLE	\$ R 199.63	✓
3	1	REAR BUMPER REINFORCEMENT	\$ 605.22	?
4	2	REAR BUMPER REINFORCEMENT BRACKET (RH/LH)	\$ 360.00	?
5	2	REAR BUMPER SIDE REFLECTOR (RED) (LH)	\$ BR 38.40	✓
6	2	REAR BUMPER SIDE REFLECTOR CHROME (LH)	\$ CM 16.20	✓
7	1	REAR LAMP (LH)	\$ R 533.48	X
8	1	REAR PANEL	\$ 1,151.95	?
9	1	REAR FENDER SHIELD (LH)	\$ R 197.28	X
10	1	REAR BOOTLID	\$ B 1,672.61	✓
11	1	REAR WINDSCREEN MOULDING	\$ R 98.51	✓
		SUB TOTAL	\$ 5,870.00	
		LESS 10%	\$ 587.00	
		DISCOUNTED SUB TOTAL	\$ 5,283.00	

S/NETT				
1	2	REAR PARKING SENSOR	\$ CRA 210.62	✓
2	1	REAR WINDSCREEN GUM	\$ R 40.00	✓
		SUB TOTAL	\$ 250.62	

LABOUR				
1		PANEL BEATING	\$ 700.00	?
2		SPRAYPAINTING CHARGES	\$ 700.00	600
3		WIRING CHARGES	\$ 40.00	20
4		TUFF KOTE	\$ 80.00	?
5		REMOVE/REFIX REAR PARKING SENSOR	\$ 100.00	60
6		REMOVE/REFIX REAR WINDSCREEN GLASS	\$ 150.00	120
		SUB TOTAL	\$ 1,770.00	
		GRAND TOTAL	\$ 7,303.62	

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE.
THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS
REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF
REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE
NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE
SUBJECT TO CHANGE WITHOUT NOTICE.

SOON HOCK MOTOR PTE LTD
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK Autopoint
Singapore 568047
6483 6016 (3 Lines) Fax: 6483 6016
Reg. No. 199804869H

Not Notified
Repair by Repair
3-4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: