SOON HOCK MOTOR PTE LTD

27/08/18

QUOTATION FOR VEHICLE SLV 9078 J

1 2 3 4 5 6 7 8 9 10 11	1 1 2 2 2 1 1 1 1 1	PARTS REAR BUMPER REAR BUMPER CENTRE GRILLE REAR BUMPER REINFORCEMEN' REAR BUMPER SIDE REFLECTOR REAR BUMPER SIDE REFLECTOR REAR LAMP (LH) REAR PANEL REAR FENDER SHIELD (LH) REAR BOOTLID REAR WINDSCREEN MOULDING	T BRACKET (RH/LH) R (RED) (LH)	R _t	\$ 1996.72 \$ 199.63 \$ 605.22 \$ 360.00 \$ 38.40 \$ 16.20 \$ 533.48 \$ 1.151.95 \$ 1.672.61 \$ 1.672.61 \$ 98.51 \$ 5.870.00 \$ 5.870.00 \$ 5.283.00	[] * * *)]
1 2	2	S/NETT REAR PARKING SENSOR REAR WINSCREEN GUM	SUB TOTAL		210.62 5 Ac 40.00 250.62	_
1 2 3 4 5 6		LABOUR PANEL BEATING SPRAYPAINTING CHARGES WIRING CHARGES TUFF KOTE REMOVE/REFIX REAR PARKING S REMOVE/REFIX REAR WINDSCRE			\$ 700.00 \$ 700.00 \$ 40.00 \$ 80.00 \$ 100.00 \$ 150.00 \$ 1,770.00	201 800 1201

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE

SOON HOCK MOTOR PTE LTD Balling and the second process as # I - NAME AND ADDRESSOR

Mos Avshare 839006 Burny Stepany 839006

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/effer spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and as subject to liner approval from insurance Company

Acknowledged by Repairer

Signature

Date: