

ASS. REC. BY:

REF CS3/AIG/8015683/A24d301

Special Instruction:

SUI VENT
MUMEN

Adnan

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

28/8/18 @ 10:18am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 32492

Insured:

SLH 2872C

at Workshop m/s

SBL Motor

Tel:

9008 8387

of

Blk 3023A #01-65 Ubr Rd 1

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/08/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

11:43am @ 28/8/18

Person Contacted:

Mr. chuan

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKE 32492 - X

SLH 2872C - CCA/LeR17C05295/Kha342 DOA: 15/03/17

21/8/18

After Repair

Repair days 4

TGM Lin

7/9/18

08/11/13) wef

ASS. REC. BY:

REF:

AlG

PRS

ASSIGNMENT

From:

Date:

28/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKE 3249Z

at Workshop m/s

SBL Motor

of

81K3023A # 01-65 ubi Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Mr. Chua @ 90088387

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKE3249Z

Yr Regn:

2007, Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Estima

c.c

2362

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

168523

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ACR500048334

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

215/55R17

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

28/08/18

Survey held at

SBL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AlG PRS.

COE Expiry: 25/09/27

6/9/18 Submitting data report

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$)

180

20

200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 28/8/2018 10:18:52 AM
Attachments:  SLH2872C.tif  SKE3249Z.tif

Hi LKK,

Kindly assist to survey, vehicle is in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SBL MOTOR SERVICES PTE LTD

BLK 3023A #01-65 UBI ROAD 1 SINGAPORE 408717 TEL: 6744-3514
Company Reg No. 199506752G

27th Aug 2018.

The Claims Executive,
AIG Asia Pacific Ins. Pte Ltd,
7B Shenton Way, #07-16
Shore 079120

Dear Sirs. Re: Third Party Claim Against Your Insured
SLH 2872 C Accid with SKF 2249Z
On 24/08/18 Along Holland Road at
about 14.05 pm

Reference to the above, please kindly arrange for your
surveyor to survey/inspect the necessary
damage parts before we proceed to repair
accordingly.
Thank you.

Yours faithfully,


Ross Stewart,
Manager,
95088388.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015683/Az4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 28-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLH 2872C	Veh. Inspected	SKE 3249Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	28/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/08/2018	Inspection Date	28/08/2018
Survey held at	SBL MOTOR SERVICES PL BLK 3023A UBI ROAD 1 #01-65 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SBL MOTOR SERVICES PTE LTD

BLK 3023A #01-65 UBI ROAD 1 SINGAPORE 408717 TEL: 6744-3514
Company Reg No. 199506752G

27th Aug 2018.

The Claims Executive,
AIG Asia Pacific Ins. Pte Ltd,
78 Shenton Way, #07-16
Shore 079120

Dear Sirs. Re: Third Party Claim Against Your Insured
SLH 2872 C Accdt with SKE 3249Z
On 24/08/18 Along Holland Road at
About 14.05 PM

Reference to the above, please kindly arrange for your
surveyor to survey/inspect the necessary
damage parts before we proceed to repair
accordingly.

Thank you.

Yours faithfully,

Boyen Chua,
Manager.
90088387.

Adrian Lim,
28/08/18
sl/s.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/08/2018 17:29
Date Of Accident	24/08/2018 14:05
Exact Location Of Accident	HOLLAND ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE3249Z
Insured/Policyholder	
Name Of Registered Owner	LIM BOON CHYE
NRIC No	S1636464I
Email Address	SEBASTIAN@RIVERCARGOINTL.COM.SG
Mobile Phone No	(LOCAL) +65-96915688
Alternative Phone No	OFFICE-96915688

Vehicle Particulars	
Manufacturer	TOYOTA
Model	ESTIMA-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5077533731-01
Cover Note Number	

Driver	
Name of Driver	LIM BOON CHYE
NRIC No	S1636464I
Date Of Birth	08/07/1964
Occupation	INDOOR
Date Of Driving Pass	24/08/1988
Driving Experience	30 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96915688
Fax Number	
Contact Number	OFFICE-96915688
Email Address	SEBASTIAN@RIVERCARGOINTL.COM.SG

Address	BLK 321 SERANGOON AVENUE 2 #11-368
Postcode	550321
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance,	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH2872C
Vehicle Make/Model/Colour	TOYOTA SILVER
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	CHNG SOON HWEE
NRIC/Passport Number	
Contact Number	92395091
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:



SKETCH PLAN

Holland Road



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was out in my lane and there ~~the~~
 it comes in very fast As you can see
 the picture on the slow sign on the right
 He suddenly hit my rear of my car

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 24/8/18

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	MIS	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	2
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEC	✓	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector RH	CRA	✓	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	SR	R	
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SKE 3249Z

NAC	INC	Item	CON	AC	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	DD	R	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: _____ Assessor: _____

Torlim
7/1/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2018 Edit Reg		28 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

LCRF Pte Ltd, Co. Reg. No.: NA

Main Claimant:

-

Vehicle Reg. No.:

SKE3249Z

Claim Type:

TP / 3010251194SG

Vehicle Reg. No. (Insured):

SLH2872C

Repairster:

SBL MOTOR SERVICES PTE LTD (HQ) 68 POH HUAT CRESCENT, POH HUAT GARDEN, 546901 Ubi - Tel: 67443514

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/09/2018]

Date of Loss:

24/08/2018 00:00 - :59
[130 Months and 29 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

0999994755 (Comprehensive)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (29/08/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKE3249Z (3010251194SG)**

[SLH2872C]


































TP

-

Aug 24 2018 12:00AM

[LCRF Pte Ltd]

SBL MOTOR SERVICES PTE LTD

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Assessment Reports										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail		Print	
1	29/08/18 10:52	Accident Statement From:SC - Reg. No: SLH2872C, Claimant: LCRF PTE LTD								 Load HTM			
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
2	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
3	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
4	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
5	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
6	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
7	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
8	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
9	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
10	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
11	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
12	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
13	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
14	29/08/18 10:49	General View								 Load JPG		<input checked="" type="checkbox"/>	
15	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
16	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
17	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
18	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
19	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
20	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
21	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
22	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
23	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
24	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
25	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
26	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
27	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
28	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
29	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
30	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
31	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	
32	10/09/18 19:56	Photo After Spray								 Load JPG		<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015683/AZ4D3E2

Date: 12/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994755
Claimant Vehicle No : SKE3249Z **Insured Vehicle No :** SLH2872C
 Date of Loss: 24/08/2018 Nature of Claim: TP Claim No: 3010251194SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE3249Z**
 Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A) Engine No: 2AZF070389
 Reg. Date: 26/09/2007 (Man. Year: 2007) Chassis No: ACR500048334
 Colour: Red Odometer: 168523 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/08/2018
 Date Inspected: 28/08/2018 Inspected At: SBL MOTOR SERVICES PTE LTD (HQ)
 BLK 3023A UBI ROAD 1 #01-65 .
 SINGAPORE 408717
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Missing	0.00 F	*- F
2	2		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REFLECTOR RH	Cracked	0.00 F	*- F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1		*REAR END PANEL	Dented	0.00 F	*- F
7	1		*TAILGATE	Repair	0.00 F	*- F
8	1		*REAR RH FENDER	Repair	0.00 F	*- F
F=Franchise part.				Total Parts (\$\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >