

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (LH) mounting broken			\$ 1,388.00
	Wiper Container deformed			\$ 61.90
	SUB TOTAL			\$ 1,449.90
	LESS 20%			\$ 289.98
	DISCOUNTED TOTAL			\$ 1,159.92
	01/19/2018 Rya 24k Auto 			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.