

22/03/2002

ASS. REC. BY:

REF: CS/FCI/8015696/T1td3e2

Special Instruction:

Surveyor:

taufikah

ASSIGNMENT (Office)

From (Person):

CWS

Lurene jaw

of

FCI

Date/Time:

28/8/18 @ 4-10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 7931M

Insured:

SHB 3646L

at Workshop m/s

Mora Automotive

Tel:

85425119

of

Bk 1008 Bkt Meruh Lane 3 # 01-04

Policy No:

Claim No:

D18006385MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/08/18

CA / REV / REP. / REV 24 HRS

(DS)

29/8/18 @ Insp: 15 Fan Yoney Rd

H.O.D. Endorsement:

Date/Time:

5:43pm @ 28/8/18

Person Contacted:

Nithan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJB 7931M - X

SHB 3646L - CS/FCI/3000432/Uvu2

DOA: 2/01/2013

11/9/18 @ 9:28am Revert via email preli advise


Tanfer

REF:

FCI

CoE 2023 Jan

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 432K.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Billy

Veh No: SJB7931M Yr Regn: 2008 Jan
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Stream C.C. 1799
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 184298 T/Radio: Insured / Std / NI / NA
 Eng/No: JHMRN 684085201375
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/65R15 R: 7-7
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Fuller
 Front: R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. D.O.I. 30/8/18
 Survey held at: MOVIA Fanyang
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Repair Unit \$8K.

Lump Sum \$2500 (Red: 5173.64 : 370%)

RECEIVED 18 OCT 2018

Date/Time: File Pass to? ☐ : Preli. Report

1) 12/10 Typist ☒ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Workshop (\$)

Survey Fee
 Transportation
 1) 3-500 \$
 2) 500-1000 \$
 3) 1000-2000 \$
 4) 2000-5000 \$
 5) 5000-10000 \$
 6) 10000-20000 \$
 7) 20000-50000 \$
 8) 50000-100000 \$
 9) 100000-200000 \$
 10) 200000-500000 \$
 11) 500000-1000000 \$
 12) 1000000-2000000 \$
 13) 2000000-5000000 \$
 14) 5000000-10000000 \$
 15) 10000000-20000000 \$
 16) 20000000-50000000 \$
 17) 50000000-100000000 \$
 18) 100000000-200000000 \$
 19) 200000000-500000000 \$
 20) 500000000-1000000000 \$
 21) 1000000000-2000000000 \$
 22) 2000000000-5000000000 \$
 23) 5000000000-10000000000 \$
 24) 10000000000-20000000000 \$
 25) 20000000000-50000000000 \$
 26) 50000000000-100000000000 \$
 27) 100000000000-200000000000 \$
 28) 200000000000-500000000000 \$
 29) 500000000000-1000000000000 \$
 30) 1000000000000-2000000000000 \$
 31) 2000000000000-5000000000000 \$
 32) 5000000000000-10000000000000 \$
 33) 10000000000000-20000000000000 \$
 34) 20000000000000-50000000000000 \$
 35) 50000000000000-100000000000000 \$
 36) 100000000000000-200000000000000 \$
 37) 200000000000000-500000000000000 \$
 38) 500000000000000-1000000000000000 \$
 39) 1000000000000000-2000000000000000 \$
 40) 2000000000000000-5000000000000000 \$
 41) 5000000000000000-10000000000000000 \$
 42) 10000000000000000-20000000000000000 \$
 43) 20000000000000000-50000000000000000 \$
 44) 50000000000000000-100000000000000000 \$
 45) 100000000000000000-200000000000000000 \$
 46) 200000000000000000-500000000000000000 \$
 47) 500000000000000000-1000000000000000000 \$
 48) 1000000000000000000-2000000000000000000 \$
 49) 2000000000000000000-5000000000000000000 \$
 50) 5000000000000000000-10000000000000000000 \$
 51) 10000000000000000000-20000000000000000000 \$
 52) 20000000000000000000-50000000000000000000 \$
 53) 50000000000000000000-100000000000000000000 \$
 54) 100000000000000000000-200000000000000000000 \$
 55) 200000000000000000000-500000000000000000000 \$
 56) 500000000000000000000-1000000000000000000000 \$
 57) 1000000000000000000000-2000000000000000000000 \$
 58) 2000000000000000000000-5000000000000000000000 \$
 59) 5000000000000000000000-10000000000000000000000 \$
 60) 10000000000000000000000-20000000000000000000000 \$
 61) 20000000000000000000000-50000000000000000000000 \$
 62) 50000000000000000000000-100000000000000000000000 \$
 63) 100000000000000000000000-200000000000000000000000 \$
 64) 200000000000000000000000-500000000000000000000000 \$
 65) 500000000000000000000000-1000000000000000000000000 \$
 66) 1000000000000000000000000-2000000000000000000000000 \$
 67) 2000000000000000000000000-5000000000000000000000000 \$
 68) 5000000000000000000000000-10000000000000000000000000 \$
 69) 10000000000000000000000000-20000000000000000000000000 \$
 70) 20000000000000000000000000-50000000000000000000000000 \$
 71) 50000000000000000000000000-100000000000000000000000000 \$
 72) 100000000000000000000000000-200000000000000000000000000 \$
 73) 200000000000000000000000000-500000000000000000000000000 \$
 74) 500000000000000000000000000-1000000000000000000000000000 \$
 75) 1000000000000000000000000000-2000000000000000000000000000 \$
 76) 2000000000000000000000000000-5000000000000000000000000000 \$
 77) 5000000000000000000000000000-10000000000000000000000000000 \$
 78) 10000000000000000000000000000-20000000000000000000000000000 \$
 79) 20000000000000000000000000000-50000000000000000000000000000 \$
 80) 50000000000000000000000000000-100000000000000000000000000000 \$
 81) 100000000000000000000000000000-200000000000000000000000000000 \$
 82) 200000000000000000000000000000-500000000000000000000000000000 \$
 83) 500000000000000000000000000000-1000000000000000000000000000000 \$
 84) 1000000000000000000000000000000-2000000000000000000000000000000 \$
 85) 2000000000000000000000000000000-5000000000000000000000000000000 \$
 86) 5000000000000000000000000000000-10000000000000000000000000000000 \$
 87) 10000000000000000000000000000000-20000000000000000000000000000000 \$
 88) 20000000000000000000000000000000-50000000000000000000000000000000 \$
 89) 50000000000000000000000000000000-100000000000000000000000000000000 \$
 90) 100000000000000000000000000000000-200000000000000000000000000000000 \$
 91) 200000000000000000000000000000000-500000000000000000000000000000000 \$
 92) 500000000000000000000000000000000-1000000000000000000000000000000000 \$
 93) 1000000000000000000000000000000000-2000000000000000000000000000000000 \$
 94) 2000000000000000000000000000000000-5000000000000000000000000000000000 \$
 95) 5000000000000000000000000000000000-10000000000000000000000000000000000 \$
 96) 10000000000000000000000000000000000-20000000000000000000000000000000000 \$
 97) 20000000000000000000000000000000000-50000000000000000000000000000000000 \$
 98) 50000000000000000000000000000000000-100000000000000000000000000000000000 \$
 99) 100000000000000000000000000000000000-200000000000000000000000000000000000 \$
 100) 200000000000000000000000000000000000-500000000000000000000000000000000000 \$

Report Format: TP

Lump Sum / LB \$ 85007

3x15=45
170+45
50
120
385

MOTOR SURVEY ASSIGNMENT

Date	27-08-2018	Our Ref No. D18006385MFSH
Accident Date	25-08-2018	Claim Type. Third Party
Insured Vehicle	SHB3646L	Third Party Vehicle. SJB7931M
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006385MFSH

Date: 11/9/2018

Our Ref: CS/FCI18015696/T1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJB 7931M

Please be informed that we had conducted the inspection of the abovementioned vehicle 30/8/2018 at the premises of M/s Mova Automotive and have the following to report: -

Workshop Estimate Amount	: S\$ <u>13,673.64</u>
Revised Estimate Amount	: S\$ <u>3,818.88</u>
"Check" Items Amount	: S\$ <u>656.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
Front and rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Naz

Automotive Assessor

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 11 September 2018 9:28 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006385MFSH/1
Attachments: PRELI ADVISED SJB 7931M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJB 7931M**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 28 August 2018 4:25 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006385MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer arrange survey on 29/08/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 28 August 2018 4:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006385MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Shiau Chan (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 14 September 2018 4:06 PM
To: Billy; Taufikh (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); SUR; 'Jia Yu'
Subject: RE: Re:SJB7931M

Dear Billy,

Let me check with Taufikh and get back to you

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Billy <billy@nova.com.sg>
Sent: Friday, 14 September 2018 3:28 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; SUR <sur@lkkauto.com>; 'Jia Yu' <jiaYu@nova.com.sg>
Subject: FW: Re:SJB7931M

Hi Sir,

Can we close at Lump Sum Repair \$9000.00. Thank You.

Best Regard's
Billy Liaw

From: Billy [<mailto:billy@nova.com.sg>]
Sent: 04 September 2018 14:37
To: 'Taufikh (LKK Auto)'
Subject: FW: Re:SJB7931M

Hi Sir,

Attach with Finalization Report, Please advice. Thank you.

Best Regard's
Billy Liaw

NOVA Automotive Pte Ltd

Tel: +65 6272 3892

Fax: +65 6270 8314



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1565I

Vehicle Details

Vehicle No.: SJB7931M
Vehicle to be Exported: Yes
Intended De-registration Date: 25 Aug 2018
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8L A
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: R18A12801324
Chassis No.: JHMRN68408S201375
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$20,549.00
Original Registration Date: 24 Jan 2008
First Registration Date: 24 Jan 2008
Transfer Count: 0
Actual ARF Paid: \$22,604.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Jan 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$26,136.00
COE Rebate Amount: \$23,058.00
Total Rebate Amount: \$23,058.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Aug 2018

OK

MARKET VALUE \$32K.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/08/2018 14:05
Date Of Accident	25/08/2018 12:35
Exact Location Of Accident	PIE TWDS CHANGI
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJB7931M
Insured/Policyholder	
Name Of Registered Owner	LEOW CHENG GEOK
NRIC No	S0791565I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96158491
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	HONDA
Model	STREAM 1.8L A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA012170
Cover Note Number	
Driver	
Name of Driver	NG YISHENG, IBSEN
NRIC No	S8844939H
Date Of Birth	20/10/1988
Occupation	INDOOR
Date Of Driving Pass	07/04/2008
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92290223
Fax Number	
Contact Number	
EMail Address	IBSENNG@GMAIL.COM

Address	APT BLK 91 COMMONWEALTH DRIVE #04-706
Postcode	140091
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - GRANDCHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB3646L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	NG CHOON BENG
NRIC/Passport Number	S7809872D
Contact Number	90041332
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLP8269M
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver FADZIL

NRIC/Passport Number

Contact Number 93847047

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLJ1643T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number 96917075

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25/08/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SJB 7931M	ACCIDENT DATE & TIME: 25/08/2018 APPROX 12.35PM
CONTACT NUMBER: 92290223	E-MAIL ADDRESS: p35ENNG@GMAIL.COM
LOCATION: PIE TOWARDS CHANGI BEFORE LORNE ROAD JOBS EXIT LANE 1	
WHILE TRAVELING TOWARDS PIE CHANGI AIRPORT LANE ONE, THE CAR IN FRONT OF ME JAMMED BRAKE. I PROCEED TO BRAKE AND COME TO A STOP, SUBSEQUENTLY THE CAR (TAXI) BEHIND ME COLLIDED WITH ME AND PUSHED MY CAR FORWARD AND CAUSED ANOTHER COLLISION FOR ME & THE CAR IN FRONT.	
* IT WAS A CHAIN COLLISION INVOLVING 4 VEHICLES	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25/08/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

27/08/2018

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SJB7931M

Veh Model :- HONDA STREAM

Estimate# :- CK417886

Claim # :-

ACC. Date :- 25/08/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	TAILGATE	1 PC	903.00	903.00
2.	TAILGATE GLASS MOULDING	1 PC	65.00	65.00
3.	TAILGATE GARNISH	1 PC	162.00	162.00
4.	TAILGATE 'H' LOGO	1 PC	21.90	21.90
5.	TAILGATE EMBLEM - STREAM	1 PC	31.60	31.60
6.	TAILGATE LOCK	1 PC	109.40	109.40
7.	TAILGATE LOCK STICKER	1 PC	27.50	27.50
8.	TAILGATE WEATHERSTRIP	1 PC	121.60	121.60
9.	TAILGATE INNER TRIM - CHECK	1 PC		
10.	TAILLAMP ASSY RH & LH - CHECK	2 PC		
11.	REAR END PANEL	1 PC	306.70	306.70
12.	REAR END PANEL TOP COVER - CHECK	1 PC		
13.	REAR FENDER INNER TRIM RH & LH - CHECK	2 PC		
14.	REAR BUMPER	1 PC	588.90	588.90
15.	REAR BUMPER BRACKET RH & LH	2 PC	10.00	20.00
16.	REAR BUMPER RETAINER RH & LH	2 PC	19.40	38.80
17.	REAR BUMPER CLIPS	10 PC	3.90	39.00
18.	REAR TOW COVER	1 PC	13.90	13.90
19.	BONNET	1 PC	638.90	638.90
20.	BONNET HINGE RH & LH	2 PC	38.90	77.80
21.	BONNET INSULATOR	1 PC	87.60	87.60
22.	BONNET RUBBER - FRONT	1 PC	15.00	15.00
23.	BONNET RUBBER - CENTER	1 PC	18.50	18.50
24.	BONNET LOCK	1 PC	85.10	85.10
25.	BONNET CABLE	1 PC	42.10	42.10
26.	RADIATOR GRILLE	1 PC	202.10	202.10
27.	RADIATOR GRILLE LOGO	1 PC	23.40	23.40
28.	RADIATOR GRILLE TOP COVER	1 PC	48.60	48.60
29.	RADIATOR GRILLE TOP COVER CLIPS	10 PC	3.90	39.00
30.	HEADLAMP ASSY RH & LH	2 PC	603.00	1,206.00
31.	HEADLAMP LOWER BRACKET RH & LH	2 PC	36.50	73.00
32.	FRONT BUMPER	1 PC	635.60	635.60
33.	FRONT BUMPER REINFORCEMENT	1 PC	218.80	218.80
34.	FRONT BUMPER LOWER GRILLE - CENTRE	1 PC	85.10	85.10
35.	FRONT BUMPER RETAINER RH & LH	2 PC	12.40	24.80
36.	FRONT BUMPER CLIPS	10 PC	3.90	39.00
37.	SUPPORT PANEL	1 PC	466.20	466.20
38.	FRONT FENDER RH	1 PC	486.20	486.20
39.	FRONT FENDER TOP COVER RH & LH	2 PC	36.50	73.00
40.	FRONT FENDER TOP CLIPS	20 PC	3.50	70.00
41.	FRONT FENDER COWLING RH	1 PC	82.70	82.70
42.	FRONT FENDER COWLING CLIPS	10 PC	3.50	35.00
43.	A/C CONDENSER	1 PC	840.10	840.10
44.	A/C CONDENSER TOP BRACKET RH & LH	12 PC	12.00	144.00
45.	A/C CONDENSER RUSH	2 PC	10.50	21.00
46.	A/C ALUMINUM PIPE	1 PC	170.20	170.20
47.	A/C DISCHARGE PIPE	1 PC	235.90	235.90
48.	A/C FAN COWLING	1 PC	85.10	85.10
49.	A/C FAN MOTOR	1 PC	308.80	308.80
50.	A/C FAN BLADE	1 PC	48.60	48.60
51.	RADIATOR ASSY	1 PC	1,507.30	1,507.30

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

27/08/2018

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01 City House

Singapore 068877.

Page # :- 1 132416

Veh # :- SJB7931M

Veh Model :- HONDA STREAM

Estimate# :- CK417886

Claim # :-

ACC. Date :- 25/08/18

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
52.	RADIATOR FAN COWLING	1 PC	109.40	109.40
53.	RADIATOR FAN MOTOR	1 PC	316.00	316.00
54.	RADIATOR FAN BLADE	1 PC	58.40	58.40
55.	RADIATOR SPARE TANK	1 PC	58.40	58.40
56.	RADIATOR TOP HOSE	1 PC	29.10	29.10
57.	RADIATOR BOTTOM HOSE	1 PC	31.60	31.60
58.	RADIATOR TOP BRACKET RH & LH	2 PC	15.00	30.00
59.	RADIATOR BUSH RH & LH	2 PC	10.00	20.00
60.	RADIATOR SIDE GARNISH RH & LH - CHECK	2 PC		
61.	RADIATOR COOLANT	1 PC	48.60	48.60
62.	AIR CLEANER EXTENSION HOSE	1 PC	195.00	195.00
63.	AIR CLEANER DUCT	1 PC	168.00	168.00
LIST TOTAL S\$				11,648.30
20% DISCOUNT S\$				-2,329.66
				9,318.64
SPECIAL NET ITEMS :				
1.	TAILGATE GLASS SEALANT	1 PC	40.00	40.00
2.	REVERSE SENSOR	1 SET	300.00	300.00
3.	REAR NUMBER PLATE	1 PC	35.00	35.00
4.	FRONT NUMBER PLATE	1 PC	40.00	40.00
SPECIAL NET TOTAL S\$				415.00
LABOUR :				
TO CUT/ WELD SUPPORT PANEL, REAR END PANEL. KNOCK AND STRAIGHTEN FRONT & REAR BODY MEMBER. REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION				1,600.00
SPRAY PAINT BONNET, SUPPORT PANEL, FRONT BUMPER, FRONT FENDERS, TAILGATE, REAR END PANEL, REAR BUMPER, REAR FENDERS				1,700.00
REMOVE & REPLACE A/C CONDENSER, PIPE, HOSE AND RECHARGE A/C GAS				120.00
REMOVE & REPLACE TAILGATE GLASS & CHECK WATER LEAKAGE				120.00
REMOVE & REPLACE TAILGATE TRIM COVER, MECHANISM AND CHECK LOCKING SYSTEM				60.00
REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING				60.00
REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION				50.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

27/08/2018

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 132416

Veh # :- SJB7931M

Veh Model :- HONDA STREAM

Estimate# :- CK417886

Claim # :-

ACC. Date :- 25/08/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TO APPLY SEAL ON WELDING JOINTS		40	80.00
	RUST PROOF AFFECTED AREAS		100	150.00
	LABOUR TOTAL S\$			3,940.00

E. & O.E



NON-TAX AMOUNT S

AMOUNT S\$ 13,673.64

GST @ 7 % 957.15

AMOUNT DUE S\$ 14,630.79

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanglin 97445749
'wp'

Lumpsum
Resurvey after repair
sur@lkkauto.com

10 days

30/8/18 1415



Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 64763333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 6314

Co. Reg. 198904033G
GST Reg. M2-0088854-2

Estimate

27/08/2018

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01 City House

Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SJB7931M

Veh Model :- HONDA STREAM

Estimate# :- CK417886

Claim # :-

ACC. Date :- 25/08/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	TAILGATE	1 PC	903.00	903.00
2.	TAILGATE GLASS MOULDING	1 PC	65.00	65.00
3.	TAILGATE GARNISH	1 PC	162.00	162.00
4.	TAILGATE 'H' LOGO	1 PC	21.90	21.90
5.	TAILGATE EMBLEM - STREAM	1 PC	31.60	31.60
6.	TAILGATE LOCK	1 PC	109.40	109.40
7.	TAILGATE LOCK STICKER	1 PC	27.50	27.50
8.	TAILGATE WEATHERSTRIP	1 PC	121.60	121.60
9.	TAILGATE INNER TRIM - CHECK	1 PC		
10.	TAILLAMP ASSY RH & LH - CHECK	2 PC		
11.	REAR END PANEL	1 PC	306.70	306.70
12.	REAR END PANEL TOP COVER - CHECK	1 PC		
13.	REAR FENDER INNER TRIM RH & LH - CHECK	2 PC		
14.	REAR BUMPER	1 PC	588.90	588.90
15.	REAR BUMPER BRACKET RH & LH	2 PC	10.00	20.00
16.	REAR BUMPER RETAINER RH & LH	2 PC	19.40	38.80
17.	REAR BUMPER CLIPS	10 PC	3.90	39.00
18.	REAR TOW COVER	1 PC	13.90	13.90
19.	BONNET	1 PC	638.90	638.90
20.	BONNET HINGE RH & LH	2 PC	38.90	77.80
21.	BONNET INSULATOR	1 PC	87.60	87.60
22.	BONNET RUBBER - FRONT	1 PC	15.00	15.00
23.	BONNET RUBBER - CENTER	1 PC	18.50	18.50
24.	BONNET LOCK	1 PC	85.10	85.10
25.	BONNET CABLE	1 PC	42.10	42.10
26.	RADIATOR GRILLE	1 PC	202.10	202.10
27.	RADIATOR GRILLE LOGO	1 PC	23.40	23.40
28.	RADIATOR GRILLE TOP COVER	1 PC	48.60	48.60
29.	RADIATOR GRILLE TOP COVER CLIPS	10 PC	3.90	39.00
30.	HEADLAMP ASSY RH & LH	2 PC	603.00	1,206.00
31.	HEADLAMP LOWER BRACKET RH & LH	2 PC	36.50	73.00
32.	FRONT BUMPER	1 PC	635.60	635.60
33.	FRONT BUMPER REINFORCEMENT	1 PC	218.80	218.80
34.	FRONT BUMPER LOWER GRILLE - CENTRE	1 PC	85.10	85.10
35.	FRONT BUMPER RETAINER RH & LH	2 PC	12.40	24.80
36.	FRONT BUMPER CLIPS	10 PC	3.90	39.00
37.	SUPPORT PANEL	1 PC	466.20	466.20
38.	FRONT FENDER RH	1 PC	486.20	486.20
39.	FRONT FENDER TOP COVER RH & LH	2 PC	36.50	73.00
40.	FRONT FENDER TOP CLIPS	20 PC	3.50	70.00
41.	FRONT FENDER COWLING RH	1 PC	82.70	82.70
42.	FRONT FENDER COWLING CLIPS	10 PC	3.50	35.00
43.	A/C CONDENSER	1 PC	840.10	840.10
44.	A/C CONDENSER TOP BRACKET RH & LH	12 PC	12.00	144.00
45.	A/C CONDENSER RUSH	2 PC	10.50	21.00
46.	A/C ALUMINUM PIPE	1 PC	170.20	170.20
47.	A/C DISCHARGE PIPE	1 PC	235.90	235.90
48.	A/C FAN COWLING	1 PC	85.10	85.10
49.	A/C FAN MOTOR	1 PC	308.80	308.80
50.	A/C FAN BLADE	1 PC	48.60	48.60
51.	RADIATOR ASSY	1 PC	1,507.30	1,507.30

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

27/08/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 132416

Veh # :- SJB7931M

Veh Model :- HONDA STREAM

Estimate# :- CK417886

Claim # :-

ACC. Date :- 25/08/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
52.	RADIATOR FAN COWLING	1 PC	109.40	109.40
53.	RADIATOR FAN MOTOR	1 PC	316.00	316.00
54.	RADIATOR FAN BLADE	1 PC	58.40	58.40
55.	RADIATOR SPARE TANK	1 PC	58.40	58.40
56.	RADIATOR TOP HOSE	1 PC	29.10	29.10
57.	RADIATOR BOTTOM HOSE	1 PC	31.60	31.60
58.	RADIATOR TOP BRACKET RH & LH	2 PC	15.00	30.00
59.	RADIATOR BUSH RH & LH	2 PC	10.00	20.00
60.	RADIATOR SIDE GARNISH RH & LH - CHECK	2 PC		
61.	RADIATOR COOLANT	1 PC	48.60	48.60
62.	AIR CLEANER EXTENSION HOSE	1 PC	195.00	195.00
63.	AIR CLEANER DUCT	1 PC	168.00	168.00
LIST TOTAL S\$				9495.10 11,548.30
20% DISCOUNT S\$				1899.02 -2,329.66
				7596.08 9,318.64

SPECIAL NET ITEMS :

1.	TAILGATE GLASS SEALANT	1 PC	40.00	40.00
2.	REVERSE SENSOR	1 SET	300.00	300.00
3.	REAR NUMBER PLATE	1 PC	35.00	35.00
4.	FRONT NUMBER PLATE	1 PC	40.00	40.00

SPECIAL NET TOTAL S\$

300.00 415.00

LABOUR :

TO CUT/ WELD SUPPORT PANEL, REAR END PANEL.
KNOCK AND STRAIGHTEN FRONT & REAR BODY
MEMBER. REMOVE & REPLACE ACCIDENT DAMAGED
PARTS. REALIGN ALL CONNECTION

1400
1,600.00

SPRAY PAINT BONNET, SUPPORT PANEL, FRONT
BUMPER, FRONT FENDERS, TAILGATE, REAR END
PANEL, REAR BUMPER, REAR FENDERS

1400/500
1,700.00

REMOVE & REPLACE A/C CONDENSER, PIPE, HOSE
AND RECHARGE A/C GAS

100
120.00

REMOVE & REPLACE TAILGATE GLASS & CHECK WATER
LEAKAGE

120.00

REMOVE & REPLACE TAILGATE TRIM COVER,
MECHANISM AND CHECK LOCKING SYSTEM

40.
60.00

REMOVE & REPLACE LUGGAGE COMPARTMENT
INNER TRIM, GARNISH, COVERING

40.
60.00

REMOVE & REPLACE REVERSE SENSOR & CHECK
FUNCTION

30
50.00

Estimate

27/08/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 132416

Veh # :- SJB7931M

Veh Model :- HONDA STREAM

Estimate# :- CK417886

Claim # :-

ACC. Date :- 25/08/18

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	TO APPLY SEAL ON WELDING JOINTS		40	80.00
	RUST PROOF AFFECTED AREAS		100	150.00
	LABOUR TOTAL S\$		3370.00	3,940.00

E. & O.E

[Signature]

NON-TAX AMOUNT S

AMOUNT S\$ 13,673.64

GST @ 7 % 957.15

AMOUNT DUE S\$ 14,630.79

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

1) PARTS 7596.08
2) RENT 300.00
3) LABOUR 3370.00

11266.08
- 2253.22 less 20%
9012.86

154 8500

Less Sum @ 9000.00

Please advice. Thank You

But UAW.

Tanji 97495749
'wp'

Insurance
Repair after repair
sur@khauto.com

10 days


30/8/18 1415

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015696/T1td3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3646L	Veh. Inspected	SJB 7931M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006385MFSH	Excess (\$)	0.00	
Assign From	LURENE JAW	Assign Date	28/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMRN68408S201375	Colour	SILVER	
Odometer	184298	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	FALKEN	6 mm	
L/H Front Tyre	205/65 R15	FALKEN	6 mm	
R/H Rear Tyre	205/65 R15	FALKEN	6 mm	
L/H Rear Tyre	205/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/08/2018	Inspection Date	30/08/2018	
Survey held at	15 FAN YONG ROAD			
Repairer	MOVA AUTOMOTIVE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 7931M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	903.00	903.00
1	TAILGATE GLASS MOULDING	NECESSARY	65.00	65.00
1	TAILGATE GARNISH	CRACKED	162.00	162.00
1	TAILGATE 'H' LOGO	NECESSARY	21.90	21.90
1	TAILGATE EMBLEM - STREAM	NECESSARY	31.60	31.60
1	TAILGATE LOCK	DEFORMED	109.40	109.40
1	TAILGATE LOCK STICKER	NOT NECESSARY	27.50	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	121.60	-
1	TAILGATE INNER TRIM (NPA)	NOT NECESSARY	-	-
2	TAILGATE ASSY RH & LH (NPA)	NOT NECESSARY	-	-
1	REAR END PANEL	BENT	306.70	306.70
1	REAR END PANEL TOP COVER (NPA)	NOT NECESSARY	-	-
2	REAR FENDER INNER TRIM RH & LH (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER	DEFORMED	588.90	588.90
2	REAR BUMPER BRACKET RH & LH @\$10.00	NECESSARY	20.00	20.00
2	REAR BUMPER RETAINER RH & LH @\$19.40	NECESSARY	38.80	38.80
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	REAR TOW COVER	MISSING	13.90	13.90
1	BONNET	BENT	638.90	638.90
2	BONNET HINGE RH & LH @\$38.90	TO REPAIR SEE LABOUR	77.80	-
1	BONNET INSULATOR	DEFORMED	87.60	87.60
1	BONNET LOCK	BENT	85.10	85.10
1	BONNET CABLE	NOT NECESSARY	42.10	-
1	RADIATOR GRILLE	CRACKED	202.10	202.10
1	RADIATOR GRILLE LOGO	NECESSARY	23.40	23.40
1	RADIATOR GRILLE TOP COVER	DEFORMED	48.60	48.60
10	RADIATOR GRILLE TOP COVER CLIPS @\$3.90	NECESSARY	39.00	39.00
2	HEADLAMP ASSY RH & LH @\$603.00	CRACKED	1,206.00	1,206.00
2	HEADLAMP LOWER BRACKET RH & LH @\$36.50	CRACKED	73.00	73.00
1	FRONT BUMPER	DEFORMED	635.60	635.60

Report Ref No. CS/FCI18015696/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER REINFORCEMENT	BENT	218.80	218.80
1	FRONT BUMPER LOWER GRILLE - CENTRE	DEFORMED	85.10	85.10
2	FRONT BUMPER RETAINER RH & LH @\$12.40	NECESSARY	24.80	24.80
10	FRONT BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	SUPPORT PANEL	BENT	466.20	466.20
1	FRONT FENDER RH	BENT	486.20	486.20
2	FRONT FENDER TOP COVER RH & LH @\$36.50	DEFORMED	73.00	73.00
20	FRONT FENDER TOP CLIPS @\$3.50	NECESSARY	70.00	70.00
1	FRONT FENDER COWLING RH	NOT NECESSARY	82.70	-
10	FRONT FENDER COWLING CLIPS @\$3.50	NOT NECESSARY	35.00	-
1	A/C CONDENSER	BENT	840.10	840.10
12	A/C CONDENSER TOP BRACKET RH & LH @\$12.00	BENT	144.00	144.00
2	A/C CONDENSER RUSH @\$10.50	NOT NECESSARY	21.00	-
1	A/C ALUMINIUM PIPE	NOT NECESSARY	170.20	-
1	A/C DISCHARGE PIPE	NOT NECESSARY	235.90	-
1	A/C FAN COWLING	NOT NECESSARY	85.10	-
1	A/C FAN MOTOR	NOT NECESSARY	308.80	-
1	A/C FAN BLADE	NOT NECESSARY	48.60	-
1	RADIATOR ASSY	CRACKED	1,507.30	1,507.30
1	RADIATOR FAN COWLING	NOT NECESSARY	109.40	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	316.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	58.40	-
1	RADIATOR SPARE TANK	DEFORMED	58.40	58.40
1	RADIATOR TOP HOSE	TWISTED	29.10	29.10
1	RADIATOR BOTTOM HOSE	NOT NECESSARY	31.60	-
2	RADIATOR TOP BRACKET RH & LH @\$15.00	BENT	30.00	30.00
2	RADIATOR BUSH RH & LH @\$10.00	DEFORMED	20.00	20.00
2	RADIATOR SIDE GARNISH RH & LH (NPA)	NOT NECESSARY	-	-
1	RADIATOR COOLANT	NECESSARY	48.60	48.60
1	AIR CLEANER EXTENSION HOSE	NOT NECESSARY	195.00	-
1	AIR CLEANER DUCT	NOT NECESSARY	168.00	-
1	BONNET RUBBER - FRONT	DEFORMED	15.00	15.00
1	BONNET RUBBER - CENTER	NOT NECESSARY	18.50	-

Report Ref No. CS/FCI18015696/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,329.66	-1,899.02
			9,318.64	7,596.08
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	300.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	35.00	30.00
1	FRONT NUMBER PLATE (SN)	BENT	40.00	30.00
			415.00	300.00
	<u>LABOUR</u>			
	TO CUT/WELD SUPPORT PANEL, REAR END PANEL, KNOCK AND STRAIGHTEN FRONT & REAR BODY MEMBER. REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION. INCLUSIVE OF THE REPAIR OF BONNET HINGE RH & LH		1,600.00	1,400.00
	SPRAY PAINT BONNET, SUPPORT PANEL, FRONT BUMPER, FRONT FENDERS, TAILGATE, REAR END PANEL, REAR BUMPER, REAR FENDERS.		1,700.00	1,500.00
	REMOVE & REPLACE A/C CONDENSER, PIPE, HOSE AND RECHARGE A/C GAS.		120.00	100.00
	REMOVE & REPLACE TAILGATE GLASS & CHECK WATER LEAKAGE.		120.00	120.00
	REMOVE & REPLACE TAILGATE TRIM COVER, MECHANISM AND CHECK LOCKING SYSTEM.		60.00	40.00
	REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING.		60.00	40.00
	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION.		50.00	30.00
	TO APPLY SEAL ON WELDING JOINTS.		80.00	40.00
	RUST PROOF AFFECTED AREAS.		150.00	100.00
			-	-
			-	-
			3,940.00	3,370.00
GRAND TOTAL			13,673.64	11,266.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,500.00

Report Ref No. CS/FCI18015696/T1td3e2



Report Ref No. CS/FCI18015696/T1td3e2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.