

ASS. REC. BY:

REF:

CS/FCI 18015698/ Utd3 12

Special Instruction:

Surveyor

CWS

MARUS

ASSIGNMENT (Office)

From (Person):

Lorene juw

of

FCI

Date/Time: 28/8/18 4pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 8291E

Insured:

SHA 8024D

at Workshop m/s:

Imperium Automotive

Tel:

97489940

of

25 kekik Rd 4 # 01-49

Policy No:

Claim No:

D18006384MFS#

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/08/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

5:40pm 28/8/18

Person Contacted:

Shawn

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKL 8291E - X

SHA 8024D-CC4/AXA18005591/K/m3 DOA: 6/5/18

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL8291E

at Workshop m/s raym

of \_\_\_\_\_

Insured: SH/A8024D

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A6 426

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKL8291E Yr Regn: 1213

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota roll fire c.c. 2362

Colour: 3/gck A/C: Insured / Std / NI / NA

Sp. Reading: 56602 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ANH208293154

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 235/50 R18  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front	Rear
R/Bal. <u>3</u> mm	R/Bal. <u>3</u> mm
L/Bal. <u>3</u> mm	L/Bal. <u>3</u> mm

D.O.A. 2x18/18 D.O.I. 11/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: 12/9/18 Action / Instruction: cond 2/5 & 4800 m/s shown. (Red: 8225.28; 63%)

RECEIVED 14 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 14/9 Typist

☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

3x15 = 45

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) S + RS, SI

☐ : Interview (\$ \_\_\_\_\_) Photos

☐ : Tech. Invs (\$ \_\_\_\_\_) Others

☐ : Weekend (\$ \_\_\_\_\_)

Report Format: TP

Lump Sum / I.B.I. (\$ 4800 / - )

Survey Fee:

Transportation:

Photos

Others

TOTAL

170 + 45
50
75
340



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015698/Utd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-08-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8024D	Veh. Inspected	SKL 8291E
Policy No.		Coverage (\$)	0.00
Claim No.	D18006384MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	28/08/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	24/08/2018	Inspection Date	11/09/2018
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	27-08-2018	<b>Our Ref No.</b> D18006384MFSH
<b>Accident Date</b>	24-08-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA8024D	<b>Third Party Vehicle.</b> SKL8291E
<b>Survey Location</b>	25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB	
<b>Contact Person.</b>	SHAWN TAN	
<b>Contact No.</b>	97489940/ 97489940	<b>Fax No.</b> 63467213
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	IMPERIUM AUTOMOTIVE	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	JUSEQUITY LAW CORPORATION	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	LURENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6919I
<b>Vehicle Details</b>	
Vehicle No.:	SKL8291E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.4Z GOLDEN EYES A
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	2AZG233519
Chassis No.:	ANH208293154
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$38,860.00
Original Registration Date:	27 Dec 2013
First Registration Date:	27 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$46,404.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2023
PARF Rebate Amount:	\$34,803.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Dec 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$87,001.00
COE Rebate Amount:	\$45,623.00
<b>Total Rebate Amount:</b>	<b>\$80,426.00</b>

The information contained herein is correct as at 11 Sep 2018

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Mercedes Benz S350L (COE till 02/2027). WellKept



Full Maintenance By Cycle & Carriage. Low Mileage Done. New Road Tax Till Feb 2019  
Shine Connect StarAd

**PRIME MOTOR & LEASING**  
JONGHONG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES  
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Toyota Vellfire

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Vellfire	Any	Any	2013	Any	Any	Any	Available
	Toyota Vellfire 2.4A Z	\$99,800	\$14,310 /yr	20-Sep-2013	2,362 cc	61,000 km	MPV	Available
Beautiful Grey Vellfire For Sale With High Current Paper Value Of \$85400. Definitely One Of The Best Condition, Cheapest In Market. Most Popular MPV In Town, Spacious Cabin, Foldable Rear Seats, Immac...								
Lay Auto Pte Ltd								
Posted: 07-Sep-2018 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota								
	Toyota Vellfire 2.4A Z G-Edition	\$98,800	\$14,660 /yr	04-Oct-2013	2,362 cc	90,000 km	MPV	Available
1 Owner. The Most Popular And Elegant People Carrier Available In The Market! Experience The Luxurious New Compact MPV. Spacious, Comfortable And Quietness From The Suppressing Of Engine And Vibration...								
TS Wheeler Capital Pte Ltd								
Posted: 02-Sep-2018 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota								
	Toyota Vellfire 2.4A Z G-Edition	\$99,000	\$14,640 /yr	03-Oct-2013	2,362 cc	90,000 km	MPV	Available
Number Retenti On So Buy Er Get The Chance To Bid For New Car Plate Number Of His Choice. Well Maintained And Serviced By Owner, Twin Sunroof, LED Screen Display, V-Cool, High COE And ARF.								
Posted: 15-Aug-2018 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota								
	Toyota Vellfire 3.5A Z G-Edition	\$125,833	\$21,180 /yr	12-Apr-2013	3,456 cc	59,000 km	MPV	Available
Luxurious White Exterior Paintwork Maintained In Pristine Condition! Regularly Maintained And Polished With Zymol Products. Twin Sunroofs. Twin Electric Doors. Interior Mood Lights. Call Now To Enquir...								
Posted: 02-Aug-2018 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota								
Car Buying	Car Selling	Car Ownership						
Car Aftermarket	On The Move	Lifestyle						
	Toyota Vellfire 2.4A X Hybrid	\$93,900	\$15,460 /yr	13-Mar-2013	2,362 cc	-	MPV	Available
<b>Fuel Type:</b> Petrol-Electric								
Elegant White MPV, Low Fuel Consumption With Hybrid, High ARF Value "48661" Very Well Maintained, Flexible In-house Loan Packages Available.								
Prime Motor & Leasing								
Posted: 30-Jul-2018 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads  
Compare

20 results/page

# IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

27 August 2018

Vehicle No.: SKL 8291 E

Model: Toyota Vellfire

## QTY

## DESCRIPTION

## AMT S\$

### List Items

1	Rear windscreen inner seal	11	\$	85.00	X
1	Rear tailgate	1	\$	1,593.90	X
1	Rear tailgate lock	shock	\$	350.90	✓
1	Rear tailgate rubber	11	\$	300.40	X
1	Rear tailgate "Vellfire" emblem	rec	\$	75.70	✓
2	Rear taillamps	11	\$	1,560.20	X
1	Rear end panel	10	\$	755.60	✓
1	Rear end panel inner garnish	1m	\$	265.90	✓
1	Rear bumper	10/De	\$	1,575.80	✓
2	Rear bumpers -side	20/10.1	\$	1,370.00	✓
2	Rear bumper side brackets	berf	\$	240.20	✓
2	Rear bumper reflectors	11	\$	171.40	X
4	Rear bumper PDC sensors 266 x 2.532	shock	\$	2,081.20	2 pcs
1	Rear bumper sensor buzzer	rayed	\$	185.00	✓
1	Rear bumper tow hook cover	11	\$	45.00	X
1	Rear smart keyless keyless sensor	shock	\$	235.00	✓
1	Rear exhaust silencer	12	\$	625.70	X
2	Rear exhaust mountings	11	\$	71.80	X
1	Rear exhaust chrome tail pipe	11	\$	125.00	X
			\$	11,713.70	
			Less 25%	\$	2,928.43
				\$	8,785.28

Not Authorised  
HAR  
4800/-  
a/s  
HAR

11/9/18  
Take photo after repair

5586.1  
25%  
4189.57

### Special Nett Items

- |   |                          |
|---|--------------------------|
| 1 | Rear windscreen sealant  |
| 1 | Rear bumper clip (1 set) |

11	\$	80.00	X
11	\$	50.00	/
	\$	130.00	

### S/N. Labour Charges

- |   |  |
|---|--|
| 1 | To remove, replaced damaged lamps and check up rear wiring.  |
| 2 | To remove and refit inner garnishes.                         |
| 3 | To remove and refit rear reverse sensor.                     |
| 4 | To transfer rear tailgate mechanism and wiring assembly.     |
| 5 | To remove and refit rear windscreen glass.                   |
| 6 | To remove, refit and replace exhaust silencer and mountings. |
| 7 | To apply tuff kote.  |
| 8 | Panel beating.   |
| 9 | To respray painting on the affected areas.                   |

\$ 20	80.00
\$ 60	150.00
\$ 50	150.00
\$ 11	120.00 X
\$ 11	180.00 X
\$ 11	150.00 X
\$ 50	180.00
650	1,600.00
950	\$ 1,500.00
	\$ 4,110.00

1830  
6019.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Grand Total : \$ 13,025.28






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015698/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-09-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 8024D	Veh. Inspected	SKL 8291E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006384MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	28/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VELLFIRE (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	ANH208293154	Colour	BLACK	
Odometer	56602	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	PIRELLI	7 mm	
L/H Front Tyre	235/50 R18	PIRELLI	7 mm	
R/H Rear Tyre	235/50 R18	PIRELLI	7 mm	
L/H Rear Tyre	235/50 R18	PIRELLI	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/08/2018	Inspection Date	11/09/2018	
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 8291E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR WINDSCREEN INNER SEAL	NOT NECESSARY	85.00	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,593.90	-
1	REAR TAILGATE LOCK	SHORTED	350.90	350.90
1	REAR TAILGATE RUBBER	NOT NECESSARY	300.40	-
1	REAR TAILGATE "VELLFIRE" EMBLEM	NECESSARY	75.70	75.70
2	REAR TAILLAMPS	NOT NECESSARY	1,560.20	-
1	REAR END PANEL	DENTED	755.60	755.60
1	REAR END PANEL INNER GARNISH	TWISTED	265.90	265.90
1	REAR BUMPER	DENTED / DEFORMED	1,575.80	1,575.80
2	REAR BUMPER-SIDE	DEFORMED / TORN	1,370.00	1,370.00
2	REAR BUMPER SIDE BRACKETS	BENT / NECESSARY	240.20	240.20
2	REAR BUMPER REFLECTORS	NOT NECESSARY	171.40	-
4	REAR BUMPER PDC SENSORS	SHORTED (2 PCS ONLY)	2,081.20	532.00
1	REAR BUMPER SENSOR BUZZER	DAMAGED	185.00	185.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	45.00	-
1	REAR SMART KEYLESS KEYLESS SENSOR	SHORTED	235.00	235.00
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	625.70	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	71.80	-
1	REAR EXHAUST CHROME TAIL PIPE	NOT NECESSARY	125.00	-
	LESS 25% DISCOUNT		-2,928.42	-1,396.53
			8,785.28	4,189.57
<b>SPECIAL NETT ITEMS</b>				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
			130.00	50.00

Report Ref No. CS/FCI18015698/Utd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	20.00
	TO REMOVE AND REFIT INNER GARNISHES.		150.00	60.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	-
	TO APPLY TUFF KOTE.		180.00	50.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR EXHAUST SILENCER.		1,600.00	650.00
	TO RESPRAY PAINTING ON THE AFFECTED AREAS.		1,500.00	950.00
			4,110.00	1,780.00
	<b>GRAND TOTAL</b>		<b>13,025.28</b>	<b>6,019.57</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,800.00</b>

Report Ref No. CS/FCI18015698/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.