

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986

Not Authorized
1.B.1
Henry Bepain

ACCIDENT REPAIR ON : SLZ5222P

MODEL : HYUNDAI ELANTRA 1.6

POLICY NO : P213595857

CHASSIS NO : KMHD841CMJU685380

MANUFACTURING YEAR : 2018

DATE / TIME OF ACCIDENT: 25/08/2018 Time: 1615Hrs ALONG PIE TWDS TOA PAYOH LOR 6

THIRD PARTY VEHICLE NO : SDQ8898L

Date: 20/06/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Bootlid	1	1621.00		1,621.00 ✓
2	Bootlid Hinge LH	1	95.00		95.00 X
3	Bootlid Hinge RH	1	95.00		95.00 X
4	Bootlid Emblem	1	30.00		30.00 ✓
5	Bootlid Lettering "Elantra"	1	50.00		50.00 ✓
6	Bootlid Lettering/Badge "S"	1			- ✓
7	Bootlid Weatherstrip	1	93.00		93.00 X
8	Bootlid Lock Assy	1	117.00		117.00 X
9	Bootlid Lamp LH	1	285.00		285.00 X
10	Bootlid Lamp RH	1	285.00		285.00 X
11	Rear Bumper	1	460.00		460.00 ✓
12	Rear Bumper Side Retainer LH	1	45.00		45.00 ?
13	Rear Bumper Side Retainer RH	1	45.00		45.00 ?
14	Rear Bumper Lower Garnish	1	251.00		251.00 ✓
15	Rear Bumper Reflector LH	1	33.00		33.00 X
16	Rear Bumper Reflector RH	1	33.00		33.00 ?
17	Smart Key Antenna	1	45.00		45.00 ?
18	Rear Fender LH	1	1769.00		1,769.00 X
19	Rear Fender RH	1	1769.00		1,769.00 X
20	Rear Fender Shield Front LH	1	62.00		62.00 X
21	Rear Fender Shield Rear LH	1	62.00		62.00 X
22	Rear Fender Shield Front RH	1	56.00		56.00 X
23	Rear Fender Shield Rear RH	1	56.00		56.00 X
24	Tail Lamp LH	1	365.00		365.00 X
25	Tail Lamp RH	1	365.00		365.00 ?
26	Rear Bumper Reinforcement	1	295.00		295.00 ?
27	Rear End Panel	1	380.00		380.00 ?
28	Rear End Panel Top Garnish	1	60.00		60.00 X
29	Spare Tyre Panel	1			-
Sub-Total:					8,822.00
Less Discount 20%					1,764.40
Total Parts:					7,057.60

Special Nett Items

1	Anti-rust coating	4	80.00		320.00	?
2	Rear Bumper Clips	10	2.00	na	20.00	✓
3	Rear Fender Shield Clips	20	2.00	na	40.00	X
4	Rear Bumper Sensor	1	250.00	nd	250.00	200.00
5	Rear End Panel Top Garnish Clips	10	2.00	na	20.00	X
6	Rear Number Plate	1	50.00	na	50.00	X
Total Parts:					700.00	

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,500.00	?
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,500.00	860
3	Provide skill labour to disconnect and check electrical wiring	30.00	20
4	Remove and refit rear end panel lining and garnish to facilitate repair	80.00	60
5	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and/or upholstery to facilitate repairs	150.00	
6	Remove and replace bumper sensors	80.00	50
Total Labour:		3,340.00	

Total Parts & Labour: 11,097.60
GST 7% 776.83
Grand Total: 11,874.43

Estimate Repair Duration10 days

3-5 days

ACCIDENT VEHICLE OF : SLZ5222P

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

Name : Kennerth
 Company : LKK
 Date : 29/8/18
 Time : 10.15am
 Contact No: 96910663
 Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____