

Sheet1

SM SPRAY PAINTING

BLOCK 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KB Singapore 417800

HP: 92712214 Fax: (65) 69664526

Email :chris_chanbebe@hotmail.com

SEE BENG HWEE

Bk 25 Kaki Bukit Rd 4

08-30 SYNERGY @KB

Singapore 417800

TP China.

Joy

28th August 2018Accident date: 27th August 2018

Estimated repair cost for vehicle no: SKE6824T MERCEDES BENZ E 250 CGI '10

S/n	Qty	Items/Nett	U/price	Amount	
1	1	Rear boot lid <i>Bulledd</i>		\$2,035.00	✓
2	1	Rear boot lid Emble logo <i>new</i>		\$68.00	✓
3	3	Rear boot lid Emble logo clips <i>new</i>	\$5.00	\$15.00	5
4	1	Rear boot lid center moulding <i>new</i>		\$185.00	x
5	1	Rear boot lid inner rubber <i>new</i>		\$188.00	+
6	1	Rear boot lid inner lock <i>new</i>		\$282.00	+
7	1	Rear boot lid outer lock handle <i>new</i>		\$155.00	x
8	1	boot lid inner lock motor <i>new</i>		\$380.00	x
9	1	Rear boot lid inner lock cover <i>new</i>		\$145.00	+
10	1	Rear boot lid number plate		\$50.00	+
11	2	Rear Boot lid number plate lamp <i>new</i>	\$25.00	\$50.00	+
12	1	Rear boot lid number plate cover		\$120.00	+
13	2	Rear boot lid side reflector <i>RT cut</i>	\$385.00	\$770.00	385
14	1	Rear boot lid inner trim board		\$486.00	+
15	10	Rear boot lid inner trim board clips <i>new</i>	\$5.00	\$50.00	+
16	4	Rear number plate clips	\$5.00	\$20.00	+
17	2	Rear tail lamp <i>RT canceled</i>	\$695.00	\$1,390.00	695
18	4	Rear tail lamp clips <i>new</i>	\$5.00	\$20.00	10
19	2	Rear tail lamp lower bracket <i>RT canceled</i>	\$65.00	\$130.00	65
20	2	Rear tail lamp panel <i>Repair</i>	\$280.00	\$560.00	x
21	1	Rear bumper <i>Dehanded</i>		\$1,578.00	✓
22	2	Rear bumper side bracket <i>new</i>	\$68.00	\$136.00	✓
23	4	Rear bumper reverse sensor <i>1 piece damaged</i>	\$241.00	\$964.00	241
24	1	Rear bumper lower garnish <i>ut</i>		\$457.00	✓
25	8	Rear bumper clips <i>new</i>	\$5.00	\$40.00	✓
26	1	Rear bumper towing cover <i>Dehanded</i>		\$65.00	✓

Sheet1

27	1	Rear Bumper reinforcement <i>Best</i>		\$676.00	✓
28	2	Rear Bumper reinforcement bracket <i>NE ne</i>	\$88.00	\$176.00	+
29	1	Rear end panel <i>Repairs</i>		\$1,046.00	X
30	1	Rear End Panel Top Garnish <i>NE ne</i>		\$205.00	X
31	1	Rear end panel inner lock <i>NE ne</i>		\$175.00	+
32	2	Rear fender-RH <i>NE ne</i>		\$1,899.00	+
33	1	Rear fender side moulding-RH <i>NE ne</i>		\$112.00	+

6456

Subtotal :- \$14,628.00

581040

Labour charges

To remove & re-fix cushion

~~\$180.00~~ 50

To repair RH rear fender

\$350.00 X

To remove & re-fix reverse sensor

~~\$100.00~~ 60

To remove & re-fix computer wiring

~~\$180.00~~ 100

To Check Wiring System

1440

~~\$80.00~~ 30

Tuff kote

\$150.00 X

Panel beating

~~\$1,200.00~~ 600

Spray painting

~~\$1,200.00~~ 600

Subtotal :- \$3,440.00

Total:- \$18,068.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

total: 7250.40
w/s: 5.8K ✓
050mgs