



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No: 270818

Date: 27.08.2018

Wee Ming Hong

Blk 210 Pasir Ris St. 21 #03-328,
Singapore 510210.

BMW 528i

Estimated Repair Cost for Vehicle Reg. No: SKE 3302 C

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Rear Bumper <i>Dented</i>	1,408.00	✓
1 Pc. Rear Bumper Centre Garnish <i>broken</i>	259.00	✓
1 Pc. Rear Bumper Reinforcement <i>Brk</i>	645.00	✓
1 Pc. Rear Bumper Bracket <i>broken</i>	98.00	✓
20 Pcs. Rear Bumper Clips @ 5.80 <i>Nec</i>	116.00	✓
1 Pc. Rear Bumper Towing Cover <i>dented</i>	58.00	✓
4 Pcs. Rear Bumper Reverse Sensor 3pc @ 238.00 <i>Daw</i>	952.00	✓
1 Pc. Rear Bumper Reverse Sensor Wire <i>torn</i>	499.00	✓
1 Pc. Rear Exhaust Assy. <i>bt</i>	3,890.00	✓
2 Pcs. Rear Exhaust Pipe Chrome @ 118.00 <i>Nec</i>	236.00	✓
2 Pcs. Rear Bumper Reflector @ 62.00 <i>01/5/2018 N/S NH</i>	124.00	✓
1 Pc. Rear Bumper Bottom Garnish <i>broken</i>	185.00	✓
2 Pcs. Rear Bumper Side Holder @ 150.00 <i>broken</i>	300.00	✓
1 Pc. Rear Bumper Side Garnish (RH) <i>NH</i>	190.00	X
1 Pc. Rear Bumper Centre Garnish <i>NH</i>	150.00	X
1 Pc. Rear Boot <i>Dented</i>	1,750.00	✓
2 Pcs. Rear Boot Absorber @ 205.00 <i>SVL</i>	410.00	X
2 Pcs. Rear Boot Hinger @ 198.00 <i>bt</i>	396.00	✓
1 Pc. Rear Boot Lock Assy. <i>Daw</i>	499.00	✓
1 Pc. Rear Boot Lock Sensor <i>short</i>	268.00	✓
1 Pc. Rear Boot Garnish <i>NH</i>	289.00	X
10 Pcs. Rear Boot Garnish Clips @ 5.00 <i>SVL</i>	50.00	X
1 Pc. Rear Boot Logo <i>Hue</i>	148.00	✓
1 Pc. 528i Emblem <i>Hue</i>	135.00	✓
2 Pcs. Rear Boot Lamp Assy. <i>cut / shorted</i> @ 415.00	830.00	✓
2 Pcs. Rear Boot No. Plate Lamp @ 95.00 <i>NH</i>	190.00	X
1 Pc. Rear Support Panel <i>Dented</i>	998.00	✓

~~2pc Fender Corner Garnish 198 396.00~~

~~4pc Exhaust mounting 48X4 198.00~~

~~1pc Rear RH under Garnish 299.00~~



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
 Email: alfredauto@hotmail.com

Tyre &
Sports Rim



1 Pc. Rear Support Panel Garnish (Bottom)	monty crake	268.00	✓
1 Pc. Rear Support Lock Catch	rev	140.00	X
10 Pcs. Rear Support Panel Garnish Clips @ 5.00	new	50.00	✓
2 Pcs. Rear Lamp Assy.	@ 655.00 cut / scratched	1,310.00	✓
1 Pc. Rear Spare Panel Board	BT	899.00	✓
1 Pc. Rear Weather Strip	delivered	368.00	✓
1 Pc. Rear No. Plate & Frame (Alloy)	NH	120.00	X
2 Pcs. Engine Mounting	@ 598.00 NH	1,196.00	X
1 Pc. Gearbox Mounting	NH	490.00	X
2 Pcs. Fender Corner Garnish	@ 198.00 crake monty	396.00	✓
4 Pcs. Exhaust Mounting	@ 48.00 SVC	192.00	X
1 Pc. Rear RH Under Garnish	broken	299.00	✓
2 Pcs. Head Rest RH/LH	NH @ 599.00	1,192.00	X
1 Pc. SRS Control Unit	NH	1,860.00	X
4 Pcs. Safety Belt Sensor	NH @ 288.00	1,152.00	X

Total (Panels / Parts): **25,005.00 (SGD)**

, 10% disc.

LABOR CHARGES

To remove & refit exhaust system.	480.00 100/-
To check wiring & resetting SRS & coding & Air-bag.	900.00 450/-
To remove & refit interior garnish, carpet & all Affected area.	280.00 120/-
To knock, straighten, repair & renew all accident Affected area.	1,800.00 1400/-
To respray painting on all accident affected area.	1,800.00 1200/-
To rust proof all accident affected area.	120.00 80/-
To remove & refit both engine and gearbox mounting.	580.00 NH
To remove, refit & renew Head Rest.	400.00 NH



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Total (Labor Charges): 6,360.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS	25,005.00
LABOR CHARGES	6,360.00

Grand Total: 31,365.00 (SGD)

28/08/2012 e 1300m
HKA Antenna
L/Sun


LKK Antenna
