



Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948
GST Reg. No: 201606560M
Reg No. 201606560M

Date: 27.08.2018

FWD Singapore Pte Ltd
6 Temasek Blvd #18-01
Suntec Tower Four
Singapore 038986

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLH8806E HONDA VEZEL

To Supply

1)	1pc	rear bumper with garnish	\$	870.00	DE ✓
2)	1pc	rear bumper clip	\$	30.00	RE ✓
3)	1pc	rear bumper left reflector	\$	152.00	CRA ✓
4)	1pc	left rear bumper	\$	200.00	DE ✓
5)	1pc	left rear bumper side retainer	\$	35.00	RE ✓
6)	1pc	left fender garnish	\$	160.00	DE ✓
7)	1set	left fender garnish clip	\$	20.00	RE ✓
8)	1pc	rear end panel	\$	530.00	RA ✓
9)	1pc	rear tailgate	\$	1,100.00	TH ✓
10)	1pc	rear tailgate "H" emblem	\$	30.00	RE ✓
11)	1pc	rear tailgate "Vezel" emblem	\$	60.00	RE ✓
12)	1pc	rear tailgate weatherstrip	\$	140.00	RE ✓
13)	1set	rear glass moulding (4pcs)	\$	200.00	RE ✓
14)	1pc	Cargo box	\$	220.00	X
15)	1pc	rear floor under cover 74646-T7A-000/010	\$	118.30	DE ✓
16)	1pc	rear floor panel	\$	1,130.00	repair ✓
17)	1pc	front bumper facial	\$	730.00	DE ✓
18)	1set	front bumper clip	\$	30.00	RE ✓
19)	1pc	front bumper left retainer	\$	25.00	RE ✓

Sub total Parts	\$	5,780.30
Less: 20% discount	\$	(1,445.07)
	\$	4,335.23

or 55 ?

To supply S.Nett Parts

- | | | |
|------------------------------|----|----------|
| 1) 1tube rear glass sealant | \$ | 45.00 ✓ |
| 2) 1set reverse sensor | \$ | 180.00 ✓ |

Sub total S.Nett Parts \$ 225.00

L/charges

- | | | |
|--|----|-------------------------|
| 1) To tuff kote | \$ | 120.00 60 |
| 2) To transfer rear tailgate trim board, handle, mechanism parts & etc | \$ | 100.00 60 |
| 3) To remove & refit rear glass | \$ | 120.00 ✓ |
| 4) To remove & replace reverse sensor | \$ | 60.00 ✓ |
| 5) To remove rear bumper, rear tailgate, cut/welding rear end panel, floor panel, left rear bumper, replace rear bumper, tailgate, floor panel, end panel & etc | \$ | 1,100.00 700 |
| 6) To putty & respray painting tailgate inlet & outer, rear end, floor panel, left rear bumper | \$ | 900.00 700 |
| 7) To remove front bumper, knock, adjust & align support panel, replace front bumper & align front bonnet | \$ | 300.00 200 |
| 8) To putty, respray painting front bumper & support panel | \$ | 480.00 300 |

Sub total L/charges \$ 3,180.00
 Estimated Total \$ 7,740.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Ream
 H# 90010068
 7 days
 P/P
 28/08/18 P1020
 Reey 54 paint