



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 27.08.2018

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01/02

AXA Tower

Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2318E TOYOTA VELLFIRE (2013)

To Supply

1)	1set	left side mirror assy	\$	726.40 <i>bro</i>
2)	1pc	left side mirror outer cover	\$	85.60 <i>ms</i>
3)	1pc	left front triangle glass	\$	290.00 <i>bro</i>
4)	1pc	left front door	\$	1,747.20 <i>repair</i>
5)	1pc	left front door protector	\$	536.00 <i>sch</i>
6)	1pc	left front fender	\$	420.00 <i>repair</i>
7)	1pc	left front fender "Hybrid" emblem	\$	69.00 <i>ren</i>
8)	1pc	front bumper	\$	1,785.00 <i>DE</i>
9)	1pc	front bumper left side retainer	\$	92.40 <i>ren</i>
10)	1set	front bumper clip	\$	30.00 <i>ren</i>
11)	1pc	left head lamp	\$	920.00 <i>sup</i>

Sub total parts	\$	6,701.60
Less: 25% discount	\$	(1,675.40)
	\$	5,026.20

To supply S.Nett Parts

1)	1pc	Prime Royal Limousine' sticker	\$	80.00 <i>ren</i>
2)	1tube	glass sealant	\$	35.00 <i>ren</i>
			\$	115.00

L/charges

- | | | |
|---|----|-----------------------------------|
| 1) Towing charges (use king trolley) | \$ | 85.00 85.00 |
| 2) To remove left front door glass, weatherstrip & mechanism parts | \$ | 120.00 120.00 60 |
| 3) To tuff kote | \$ | 100.00 100.00 60 |
| 4) To remove & replace left front fender, left front door, front bumper, knock & repair left rear fender & rear bumper | \$ | 1,200.00 1,200.00 700 |
| 5) To putty, respray painting left front fender, left front door inlet & outer, left rear fender, left rear tail lamp lower panel & rear bumper in pearl white | \$ | 1,800.00 1,800.00 1000 |

Sub total L/charges	\$	3,305.00
Estimated grand total	\$	8,446.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Form


Hp 90010068

7 days

L/D

28/08/18 @ 10/10

Reay after repair



24
HOURS

HOTLINE: 9182 8211

ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@gmail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1191028

Date: 26/8/18

M/S: Prime rental

Vehicle No: SHD 2318 E Model: Toyota Velfire

From: ECP (haysshore) Time Start:

To: 6 Penae PL Time End: 17:40

Remarks:

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☒ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$

80/-

GST S\$

5.60

TOTAL S\$

85.60

COPY

bizSAFE₃

Received By

Important Note:

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.