

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9738E**AAD1807-223***Not Wharfed
21 Sep @ 9000*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9738E

VF1ABL15AUC276143

RENAULT

LATITUDE

20.7.2018

EQ

PART		LIST	
1	BUMPER COVER FRT	\$	<i>SL</i> 1,259.42
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
1	BUMPER BEAM FRT	\$	<i>SL</i> 914.08
1	HEADLAMP RH	\$	<i>SL</i> 1,184.43
1	HEADLAMP PANEL FRT RH	\$	<i>SL</i> 152.15
1	FENDER PANEL FRT RH	\$	<i>SL</i> 783.83
1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>SL</i> 2,844.66
1	DOOR MIRROR ASSY RH	\$	<i>SL</i> 1,483.40

TOTAL	\$	10,845.37
10%	\$	1,084.54
	\$	9,760.84

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>SL</i> 66.00 X
1	BUMPER BRACKET CLIP FRT RH	\$	<i>SL</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>SL</i> 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>SL</i> 69.00 X

Trans-cab Auto Services Pte Ltd

AAD1807-223

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9738E

TOTAL	\$	157.50
--------------	-----------	---------------

TOTAL PARTS	\$	9,918.34
--------------------	-----------	-----------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	200l
Putty and spray painting of the affected portion.	\$	2,400.00	220l
To rust-proofing of the affected areas.	\$	170.00	30l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	✓
To check steering geometry and computer wheel alignment	\$	220.00	✓
To transfer of tire, rim and on wheel balancing.	\$	170.00	✓
To Check Electrical Lighting Concerned.	\$	170.00	✓
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	✓
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	✓
To vacuum, replace, refix and recharge air condenser	\$	380.00	✓
To replace, refix and top up coolant for radiator	\$	170.00	✓
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	✓

Trans-cab Auto Services Pte Ltd**AAD1807-223**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9738E

To transfer of front windscreen fittings and
conduct water seepage test

\$ *nn* 170.00 *X*

TOTAL	\$	7,990.00
--------------	-----------	-----------------

Over All Total	\$	17,908.34
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: