

15/02/16

INS. CASE OWNER:

CC 4/III1801

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: wong tuck kwan

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/8/18
JY.

SH 70020

SH 70020 - 15/08/18 14:46 / 15/08/2018 14:46

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NIL

Repair Cost:

SS

3,210

Loss of Rental (LOR):

SS

321

(

3

days)

100

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

3,591

Global Sum SS:

3,500

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3,500

Name 1:

HUI YANG MOTOR PRE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

VIDEO GREEN L.

FOR TP - 11/1/19

09/11/13 wof
ASS. REC. BY:

REF: III

ASSIGNMENT

From: Date: 03/09/18

Estimated Cost

On: ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLQ 8195L
at Workshop m/s: Hui Yang
of: 81K176 Sin Ming Drive #04-02

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

After 11 am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

hup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLQ 8195L Yr Regn: 07, 17

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1800

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 87829 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: Ru 3 . 1252250

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 28/8/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 3/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/9 File pass to Catherine

\$ 3K

R (\$ 2,500.54 / 45%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III18015737/jb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 29-08-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7003D		Veh. Inspected	SLQ 8195L
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	29/08/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/08/2018		Inspection Date	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

28/08/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLQ8195L

1pc front RH headlamp 1460.30
1pc front RH headlamp lower bracket
1pc front RH headlamp top bracket
1pc front centre grille base
1pc front centre grille outer garnish
1pc front centre grille "HONDA" logo
1pc front bumper 801.70
1pc front bumper RH side retainer
1pc front bumper lower lid 321.40
15pcs front bumper clip @\$5.00
1pc front bumper reinforcement
1pc front bumper RH fog lamp
1pc front bumper RH fog lamp base
1pc front bumper RH fog lamp cover

less 20%

wiring
tuffkote
spray painting
labour charges
Total

Cur \$ 1,759.40 ✓
\$ M 35.00 ✓
In \$ 28.85 X
Mfg M \$ 542.20 ✓
Cur \$ 385.00 ✓
Mke \$ 58.85 ✓
Bu \$ 927.50 ✓
DII \$ 21.70 ✓
Add M \$ 381.50 ✓
M \$ 75.00 ✓
M \$ 321.50 ✓
In \$ 285.85 X
In \$ 80.25 X
In \$ 85.58 X

\$ 4,988.18

\$ 997.64

\$ 3,990.54

\$ 80.00 201
M \$ 80.00 X
\$ 600.00 2501
\$ 750.00 3001
\$ 5,500.54



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Trilio (LKK)
Kunth
07/09/18 (mon)
after claim

Not Authorised
L1 Rep @ 3000
Resurvey After Paint
3 days

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 29 August 2018 9:43 AM
To: Hui Yang Motor; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: RE: TP Claim for SLQ8195L against SH7003D / DOA: 28/08/2018
Attachments: SKM_C28718082815260.pdf

10:05am 29/8/18
person @ Belle
vehicle not in

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLQ8195L and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: 28 August, 2018 5:24 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: TP Claim for SLQ8195L against SH7003D / DOA: 28/08/2018
Importance: High

Hi Gabriel,

Our choice is LKK Auto Consultants Pte Ltd

Thank you & Regards,
Bel

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, August 28, 2018 5:04 PM
To: Hui Yang Motor
Subject: RE: TP Claim for SLQ8195L against SH7003D / DOA: 28/08/2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]

Sent: 28 August, 2018 3:20 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: TP Claim for SLQ8195L against SH7003D / DOA: 28/08/2018

Importance: High

Dear Sir / Mdm,

Please refer to attached Document,

Kindly advise us on the arrangement Dates & Timing of the surveyor so to liaise with our customer vehicle's SLQ8195L to be at our premises for surveying.

Thank you & Regards,

Marcus Loh

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SLQ8195L (MCT18080806)**
[SH7003D]

TP

SKYWAY MOTOR PTE LTD

Aug 28 2018 8:00AM

[COMFORT TRANSPORTATION PTE LTD]

Hui Yang Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/01/2019 15:21 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3531.00) - SLQ8195L - Claim Handler: Sundari Nagarajan

Approved:3531.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2018 Edit Reg		29 Aug 2018 00:00 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Vehicle Reg. No.:	SLQ8195L	Date of Loss:	28/08/2018 08:00 - :59 [13 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18080806	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SH7003D	Policy No. (Claimant):	A28795104MCX
		Excess:	
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (11/01/2019): Alert - Adj Mandate Approved (S\$3531.00) - SLQ8195L - Claim Handler: Sundari Nag...
- III_SG (06/09/2018): Alert - Adj Mandate Maintained - SLQ8195L - Claim Handler: Sundari Nagarajan

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLQ8195L (MCT18080806)**
[SH7003D]
TP
SKYWAY MOTOR PTE LTD
Aug 28 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/01/19 15:15	Video - Accident-TP	Load MP4	
2	11/01/19 15:15	Video - Accident	Load MP4	
3	11/01/19 15:19	Video - Accident-IV	Load MP4	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
2	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
3	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
11	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
12	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
13	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
14	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
15	11/01/19 13:14	General View	Load JPG	<input checked="" type="checkbox"/>
16	11/02/19 14:23	Reinspection Photo	Load PDF	
17	11/02/19 14:23	Reinspection Photo	Load PDF	

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/18 14:39	EMAIL FROM III DD 29082018	Load PDF	
2	29/08/18 14:39	TP EST & GIA REPORT	Load PDF	
3	04/09/18 19:13	TP ESTIMATE- MARKED	Load PDF	
4	28/12/18 16:58	AUTHORISATION TO ACT	Load PDF	
5	28/12/18 16:58	LOD	Load PDF	
6	28/12/18 16:58	RENTAL RECEIPT	Load PDF	
7	28/12/18 16:58	WORKSHOP INVOICE	Load PDF	
8	11/02/19 14:18	DISCHARGE VOUCHER	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	30/08/18 09:01	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18015737/KJB3S2
Date: 11/02/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLQ8195L	Insured Vehicle No :	SH7003D
Date of Loss:	28/08/2018	Nature of Claim:	TP
		Claim No:	MCT18080806

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8195L	Engine No:	LEB5952269
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31252250
Reg. Date:	24/07/2017 (Man. Year: 2016)	Odometer:	87929 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,990.54	3,217.80	772.74	19.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	570.00	940.00	62.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,500.54	3,787.80	1,712.74	31.14
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	5,500.54	3,000.00	2,500.54	45.46
+ GST 7.00/7.00% (S\$)	385.04	210.00	175.04	45.46
Nett Amount (S\$)	5,885.58	3,210.00	2,675.58	45.46
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		3,531.00		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment:	29/08/2018		
Date Inspected:	03/09/2018	Inspected At:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ8195L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH HEADLAMP	Cut	1,759.40 FL	*1,460.30 FL
2	1		*FRONT RH HEADLAMP LOWER BRACKET	Cracked	35.00 FL	*35.00 FL
3	1		*FRONT RH HEADLAMP TOP BRACKET	Serviceable	28.85 FL	*- FL
4	1		*FRONT CENTRE GRILLE BASE	Mtg Cracked	542.20 FL	*542.20 FL
5	1		*FRONT CENTRE GRILLE OUTER GARNISH	Cut	385.00 FL	*385.00 FL
6	1		*FRONT CENTRE GRILLE HONDA LOGO	Necessary	58.85 FL	*58.85 FL
7	1		*FRONT BUMPER	Buckled	927.50 FL	*801.70 FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	21.70 FL	*21.70 FL
9	1		*FRONT BUMPER LOWER LID	Dented / Cut	381.50 FL	*321.00 FL
10	15		*FRONT BUMPER CLIP	Necessary	75.00 FL	*75.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	321.50 FL	*321.50 FL
12	1		*FRONT BUMPER RH FOG LAMP	Serviceable	285.85 FL	*- FL
13	1		*FRONT BUMPER RH FOG LAMP BASE	Serviceable	80.25 FL	*- FL
14	1		*FRONT BUMPER RH FOG LAMP COVER	Serviceable	85.58 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,988.18	4,022.25
- List Item Discount on L Items 20.00/20.00% (\$\$)	997.64	804.45
Total Parts (\$\$)	3,990.54	3,217.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING.	New	80.00	20.00
2	TUFFKOTE.	New	80.00	0.00
3	SPRAY PAINTING.	New	600.00	250.00
4	LABOUR CHARGES.	New	750.00	300.00
Gross Labour Cost (S\$)			1,510.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >