

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

28/08/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLQ8195L

1pc	front RH headlamp	Cur	\$ 1,759.40	✓
1pc	front RH headlamp lower bracket		\$ 35.00	?
1pc	front RH headlamp top bracket	h	\$ 28.85	X
1pc	front centre grille base		\$ 542.20	?
1pc	front centre grille outer garnish	Cur	\$ 385.00	✓
1pc	front centre grille "HONDA" logo	Mke	\$ 58.85	✓
1pc	front bumper	Bu	\$ 927.50	✓
1pc	front bumper RH side retainer	111	\$ 21.70	✓
1pc	front bumper lower lid	Adlka	\$ 381.50	✓
15pcs	front bumper clip @\$5.00	na	\$ 75.00	✓
1pc	front bumper reinforcement		\$ 321.50	?
1pc	front bumper RH fog lamp		\$ 285.85	?
1pc	front bumper RH fog lamp base		\$ 80.25	?
1pc	front bumper RH fog lamp cover		\$ 85.58	?
			\$ 4,988.18	
less 20%			\$ 997.64	
			\$ 3,990.54	

wiring
tuffkote
spray painting
labour charges
Total

	\$ 80.00	201
na	\$ 80.00	X
	\$ 600.00	2501
	\$ 750.00	3001
	\$ 5,500.54	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ironia
(LKK)
Kinuth
03/09/18 (mon)
attn: Nam

Not Authorized
L1 Rep &?
Resurvey After Paint
3 days