



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

### **SMRT Accident Vehicle Repair Estimates**

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHC4865J

Ref. No

TAX/08/18/2079

Reg. Date

19/12/2017

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS4

Name of Driver

TAN GEE UEI

Type of Accident

HEAD TO REAR

Date / Time of Accident

22/08/2018 09:30:00 PM

Accident Reported Date / Time :

23/08/2018 12:00:00 AM

Surveyor is Required?

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024097633

Special Instruction to ARC, if any :

SGM4539K - AIG (LKK)

Prepared Date

23/08/2018 09:39:01 AM



NAZ LKK 24/8/18 1140 2 DAy ]

BEFORE PAINT & LKK Auto Consultants hence notify

the Repairer of the following:

- · To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKB3FU403580379

Mileage

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

**Total Labout Charges** 

676.00

0.00

**Total Spray Painting Charges** 

738.00

0.00

**Total Material Charges** 

1,848.42

1,848.42

Other Charges

460.00

0.00

TOTAL **Lum Sum Total**  3,722.42

4.00 2

0.00

No. of Repair Days

0.00

0.00

Prepared / Adjusted By

0.00

Arc / Surveyor Sing Off Date

: 23/08/2018 07:55:47 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 23/08/2018 07:55:47 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

#### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	676.00	0.00
Total Labour	676.00 200	0.00

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPSRAY REAR BUMPER	378.00 200	0.00		
TO RESPRAY FILLER RR BUMPER LH	180.00 100 pag /	0.00		
TO RESPRAY FILLER RR BUMPER RH	180.00 FG m 2	0.00		
Total Spray Painting & Panel Beating	738.00	0.00		

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 20	0.00			
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 × 00	0.00			
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00 20	0.00			
TO REPLACE SUNDRY PARTS	100.00 × 00	0.00			
TO WASH AND VACUUM	60.00 ≯↑ ∩	0.00			
Total Other Costs	460.00	0.00			

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No/cr
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No P
52576470 40			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	Norsyl
52575470 40			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No X SV
52462470 30			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace	No D/N
52462470 20			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace	No Pi
52462470 10			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace	No a
52566479 00			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace	No 2
52565479 00			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace	No ?
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No XSUC
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No XUVC
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No /rei
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No 3
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	Noxsve
TOTAL MATERIALS								1,668.45		20-0-
		TOTAL	MATERIALS(Discount	ted)				1,848.42	1.848.42	

# Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									Oncor

TAX/08/18/2079