

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1906A
Ref. No : TAX/08/18/2081
Reg. Date : 06/08/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : GOH CHWIN BOON
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 21/08/2018 09:45:00 PM
Accident Reported Date / Time : 23/08/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 22/08/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097639
Special Instruction to ARC,if any :
TOWED \$60 / SKW282B - CHINA (LKK)
Prepared Date : 23/08/2018 10:50:34 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605747434

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	676.00	0.00
Total Spray Painting Charges	:	558.00	0.00
Total Material Charges	:	1,993.90	1,993.90
Other Charges	:	564.00	0.00
TOTAL	:	3,791.90	0.00
Lum Sum Total	:	3,800.00	0.00
No. of Repair Days	:	5.00 5.00 2.00	0.00
Prepared / Adjusted By	:		

Arc / Surveyor Sign Off Date : 23/08/2018 01:05:56 PM

01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/08/2018 01:04:52 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	676.00 200	0.00
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 200	0.00
TO RESPRAY BUMPER BEAM	180.00 ?	0.00
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00 40	0.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 20	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00 20	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00 20	0.00
TO REPLACE SUNDRY PARTS	100.00 x 11	0.00
TO WASH AND VACUUM	60.00 x 11	0.00
Total Other Costs	564.00	0.00

NA2 LKR
24/8/18 1100
LIS
2 DAY
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>CCA</i>
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No <i>nel</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No ?
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No ?
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No ?
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No ?
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No ?
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No ?
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No ?
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>not us</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>nel</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No ?
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ?
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No ?
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No ?
TOTAL MATERIALS								2,492.41	2,492.38	
TOTAL MATERIALS(Discounted)							1,993.90	1,993.90		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									