



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32925

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

DATE : 18/08/2018
CLAIM NO. : 11178
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

VEHICLE NO. : FBK8381R
MAKE/MODEL : YAM / YBR125

*Not Actual
above
telephone Mtn
up
307.
28/8/18*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561		1.00	\$350.00	350.00 X
2	BAR HANDLE P/N: 42062	REPLACE	1.00	\$68.00	68.00 X
3	COWLING FRONT (BLACK) P/N: 57992	REPLACE	1.00	\$282.00	282.00 60
4	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00 X
5	GRIP HANDLE SET (GPR) F2 P/N: 45347	REPLACE	1.00	\$15.00	15.00 X
6	LABOUR P/N: 06766	Supply/Install	3.00	\$35.00	105.00
7	PROTECTOR EXHAUST P/N: 50024	REPLACE	1.00	\$119.00	119.00 n/c X
8	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00	56.00 n/c X
9	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00 n/c X
10	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00 10
11	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00 ✓
12	VISOR P/N: 42004	REPLACE	1.00	\$67.00	67.00 ✓

SUB TOTAL
GST @ 7 %

\$1,318.00
\$92.26



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL					\$1,410.26

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

