



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG SZE ENG(HUANG SIRONG) BLK 17 TECK WHYE LANE #09-155 SINGAPORE 680017 Contact No	Cust No/Name	LCV05132/Ng Sze Eng (Huang Sirong)
	Reg No/Reg Date	SLX5352H / 29/03/201
	Date In/Mileage	/ 0
	Chassis No	KNAPH81BSJ5411620
	Engine No	D4HBHH347448
	Make/Model	KIA/SORENTO 2.2 A D GT SR 4WDD82
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV05132	CRDVCH	28/08/2019/ 13:13	TLC	442 / CocoLu	56865

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR FRT BUMPER, RENEW FRT LOWER COVER				550.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				420 500.00
M SUNDRY Sundry				20.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80 100.00
M SKID PLATE-FR BUMPER	1.00	111.00	00.00	111.00

SURVEYOR NAME: Rasul - Hf 20010065

SURVEYOR SIGNATURE: [Signature]

DATE: 16/09/19 @ 1345

REMARKS: 3 days

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	1,481.00
7% GST on	1481.00	103.67
Total Payable		1,584.67

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.