

Ceciliz



AXA - TP CLAIM
LKK
Rasul

VEHICLE NO : SLX 5352 H

MODEL : KIA/ SORENTO 2.2 A D

WIP : 56865

Material	:	\$	<u>111.00</u>
Labour	:	\$	<u>1,270.00</u>
Sub-Total	:	\$	<u>1,381.00</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>1,381.00</u>
GST 7%	:	\$	<u>96.67</u>
Grand Total	:	\$	<u>1,477.67</u>
Finalise By/Date : <u>Army on 25/09/19</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS

* TP vehicle no: SLX6638C (AXA)
* claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Ng Blk 17 Teck Whye Lane #09-155 Singapore 680017 Contact No *Mobile: 97125570 16/09/	Cust No/Name LCV05132/Ng Sze Eng (Huang Sirong) Reg No/Reg Date SLX5352H / 29/03/2018 Date In/Mileage 16/09/2019/ 0 Chassis/Package KNAPH81BSJ541162C /FS317 Engine No D4HBHH347448 Make/Model KIA/SORENTO 2.2 A D GT SR 4WDD82 Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	25/09/2019/ 20:43	TLC	884 / Lauro Songcuan	56865

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR FRONT BUMPER, RENEW FRONT LOWER COVER				550.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER				420.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80.00 ✓
X SKID PLATE-FR BUMPER	1.00	111.00	00.00	111.00 ✓
Z TEXT TP CLAIM AXA - SLX6638C DOA: 21.08.2018 SURVEYOR RASUL (LKK) 16.09.19 03 DAYS				
<i>Cycle & Carriage celebrates 120 years.</i> <i>Visit www.cyclecarriage.com/120 for more info!</i>				

Parts	111.00	Nett	1,381.00
Labour	1,250.00	7% GST on	96.67
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	1,477.67
Sundry/Others	20.00		
Total(w/o GST)	1,381.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
NG SZE ENG (HUANG SIRONG)	Cust No/Name LCV05132/Ng Sze Eng (Huang Sirong)
BLK 17 TECK WHYE LANE	Reg No/Reg Date SLX5352H / 29/03/201
#09-155	Date In/Mileage / 0
SINGAPORE 680017	Chassis No KNAPH81BSJ5411620
Contact No	Engine No D4HBHH347448
	Make/Model KIA/SORENTO 2.2 A D GT SR 4WDD82
	Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV05132	CRDVCH	28/08/2019/ 13:13	TLC	442 / CocoLu	56865		
Description of Goods/Services					Qty	Unit Price / Disc%	Amount
E PNT88000							550.00
REPAIR FRT BUMPER, RENEW FRT LOWER COVER							
E PNT98000							420 500.00
SPRAY PAINT FOR FRT BUMPER							
M SUNDRY							20.00
Sundry							
A 10028901							200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
E PNT88000							80 100.00
REMOVE & INSTALL PARKING SENSOR							
M SKID PLATE-FR BUMPER					1.00	111.00 00.00	111.00

Estimate

Resue - Hp 20010066

PA

16/09/19 @ 1545

3 days

REMARKS:

Resurvey before paint

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Unilegal modification to a vehicle
- Supplied by another manufacturer is subject to final approval

Acknowledged by: _____
 Signature: _____
 Date: _____

Estimate

Customer Name: Rasul - Hy 20010066

Surveyor Signature: [Signature]

DATE: 16/09/19 @ 1345

REMARKS: 3 days

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Unilateral modification of the estimate is not allowed
- Supplementary documents and information is subject to final approval

Acknowledged by Repairer
Signature: _____
Date: _____

Confirm & accepted by

	Nett	1,481.00
7% GST on	1481.00	103.67
Total Payable		1,584.67

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.