

## Shu Pei (LKKAUTO)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Thursday, 30 August 2018 10:07 AM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** Asher Sng (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving SMA1356H (OI : EQI - TBA) AND SHF615A (TP : LKK REF - CC3/EQI18015759/Keb3) on 25.08.2018  
**Attachments:** SMA1356H.PDF

Dear Shu Pei

Attached please find our insured's accident report for your attention.

Dear Asher

Please inform the surveyor to keep a look out for the front of SHF615A.

Check if there are any damages to the front of the vehicle as third party vehicle, SLR8168K alleged that SHF615A had contact with SJP2182S.

Best Regards,

**Joel Goh**  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Thursday, August 30, 2018 9:11 AM  
**To:** Joel Goh  
**Cc:** Asher Sng (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving SMA1356H (OI : EQI - TBA) AND SHF615A (TP : LKK REF - CC3/EQI18015759/Keb3) on 25.08.2018

**WITHOUT PREJUDICE**

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHF 615A at M/s Trans-cab Auto Services Pte Ltd.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)