

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A**AAD1808-216***Not Authorised
61 Sng 840506*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 615A

VF1ABL15AUC278494

RENAULT

LATITUDE

25.8.2018

EQ

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>ndidit</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>Bu</i> 1,471.77 ✓
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56 X
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70
19	1 BOOT REAR	\$	<i>R</i> 2,872.68
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36
25	1 BOOT BADGE	\$	<i>nn</i> 225.36
26	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84

Trans-cab Auto Services Pte Ltd**AAD1808-216**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

30	1 BOOT INNER TRIM	\$	586.45 X
31	1 BOOT SWITCH	\$	168.13 X
32	1 BOOT LOCK	\$	202.67 X
33	1 BOOT LOCK CATCH	\$	74.40 X
		\$	16,046.87
		10% \$	1,604.69
		\$	14,442.19

Special Nett

1	1SET PARKING AID	\$	700.00 X
2	1SET REAR BUMPER CLIP	\$	66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00 X
5	1SET BUMPER RETAINER RH CLIP RR	\$	20.00 X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00 X
7	1SET BUMPER RETAINER CLIP LH RR	\$	20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	17.82 X
11	2 REAR WINDSCREEN SELANT	\$	80.00 X
12	1 WINDSCREEN MOULDING	\$	100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00 X

TOTAL \$ 1,244.82**TOTAL PARTS \$ 15,687.01****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 440/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 600/
To Rust-Proofing Of The Affected Areas.	\$	170.00 30/

Trans-cab Auto Services Pte Ltd**AAD1808-216**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

TOTAL \$ 7,410.00**Over All Total \$ 23,097.01****(LUMP SUM)****Repair Days**~~10 DAYS~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: