

28/08/2018

1st



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : SLF8352HMake & Model : HONDA VEZEL 1.5X CVTYear of Manufacture : 2016Chassis No. : RU11116976Ins Company : AIG

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 8/24/2018

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimates**Case Owner : ROHANI

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 3,888.60Contact No  
63838115 - William 63837466 - PatrickPlus/Less 20% \$ 777.72Total of Cost / List \$ 3,110.8863837890 - Rohani(b) Nett Price Items \$ -

Less \_\_\_\_\_

63837362 - Andrew 63837656 - Ngo

Total of Nett Item \_\_\_\_\_

63837730 - Brenda(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,110.88Labour (Appendix B) \$ 1,520.00Total Repair Cost \$ 4,630.88

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
 Company : CLIC  
 Survey conducted on : 7/19/18 at \_\_\_\_\_

Remarks By Surveyor(a) The repair of this vehicle is not authorized / is not authorized until further notice.(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 7/19/18

## Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62815767

### Spare Parts

Vehicle No : SLF8352H Case Owner : ROHANI

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11116976 Engine No : 0

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRT BUMPER <i>Am</i>	1		\$ 801.80			✓
2	FRT RH FENDER	1	<i>11</i>	\$ 415.90			X
3	FRT RH BUMPER SIDE RETAINER	1	<i>0.1</i>	\$ 18.90			✓
4	FRT RH FENDER WHEEL ARCH	1	<i>61</i>	\$ 171.10			✓
5	FRT RH RIM 16"	1	<i>121</i>	\$ 765.80			✓
6	RH HEADLAMP	1		\$ 1,715.10			?
7	0	1					
8	0	1					
9	0	1					
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29		0					
30		0					

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Year of Manufacture : 2016

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*