

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax:62844284,62815767

**Spare Parts**

Vehicle No : SLG2230K Case Owner : Andrew

Make & Model : HONDA SHUTTLE 1.5 HYI Year Manufacture : 2016

Chassis No : GP71040385 Engine No : 0

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing <i>Sm</i>	1				\$ 45.00	X
2	Rear bumper <i>Bm</i>	1		1150.60			✓
3	Rear bumper side retainer LH <i>Sm</i>	1					X
4	Rear bumper side retainer RH <i>Sm</i>	1					X
5	Rear bumper clips <i>Nm</i>	1		39.00			✓
6	Rear bumper reflector LH <i>Sm</i>	1					X
7	Rear bumper reflector RH <i>Sm</i>	1					X
8	Tailgate <i>Bm</i>	1		1193.00			✓
9	Tailgate glass moulding upper <i>SLA</i>	1					+
10	Tailgate glass moulding lower <i>Nm</i>	1		65.20			+
11	Tailgate glass moulding LH <i>SVC Nm</i>	1					+
12	Tailgate glass moulding RH <i>SVC Nm</i>	1					+
13	Tailgate glass inner seal <i>Nm</i>	1				30.00	+
14	Tailgate glass sealant <i>Nm</i>	1				40.00	+
15	Tailgate weatherstrip <i>SL</i>	1					X
16	Tailgate emblem logo H <i>Nm</i>	1		27.10			+
17	Tailgate emblem SHUTTLE <i>Nm</i>	1		55.00			+
18	Tailgate emblem HYBRID <i>Nm</i>	1		80.10			+
19	Tailgate chrome moulding <i>Sm</i>	1					X
20	Tailgate chrome moulding clips <i>Nm</i>	4					X
21	Reverse sensor <i>SL</i>	1					X
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

**L&K Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_

Note: If any of the quoted parts are recommended to be repaired, ~~labor~~ an additional labour charge will be charged accordingly under supplementary.

