



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 29/8/2018

TO: AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

Vivian

Attn : Motor Claims Department
Fax : 6224 7478

- LKKA** Consultants hence notify the Repairer of the following:
- To resurvey 1 hour after spray painting
 - To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on "Without Prejudice" basis
 - No illegal modifications is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Koh Heok Kian

Vehicle No : SFK829P SKF829P

Date:

Model : Toyota Camry 2.5 Auto

Manufacture Year : 2012

Date of Accident : 24/8/2018

Total Estimate Repair Days : 5

Total Pages : 1

Re: Repair Estimate For Third Party Claim against SKM4665G

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>del</i>	1	\$589.60	\$589.60	✓
2	Rear bumper side retainer RH <i>2nd</i>	1	\$70.40	\$70.40	✓
3	Rear bumper side retainer LH <i>2nd</i>	1	\$70.40	\$70.40	✓
4	Rear bumper reinforcement <i>new</i>	1	\$391.80	\$391.80	✓
5	Reverse sensor <i>new</i>	2	\$250.00	\$500.00	200 (B2)
	Total			\$1,622.20	
	<i>589.60 SN. 200</i>		Less 25%	\$405.55	
	<i>442.20</i>		Sub Total 1	\$1,216.65	
A.	Spare Parts (S/Nett)				
1	Front bumper clip <i>new</i>	10	\$5.00	\$50.00	30
	<i>Back</i>		Sub-Total 2	\$50.00	
	<i>30</i>				
	Total for Parts			\$1,266.65	
B.	Labour				
1	To check wiring.			\$90.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$400.00	200
3	Spray painting all affected parts & areas.			\$400.00	200
4	To spray anti-rust undercoating.			\$60.00	✓
	Total Labour			\$950.00	
	Total Repair Cost			\$2,216.65	

430

Yours faithfully,

Adrian L
1/5 03/09/18
02 Aug

Aun Teng
f Premium Carz Services Pte Ltd

whit: 1102.2
1/8: 850 ✓

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No