

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0986/2018/PH  
**Date** : 28-Aug-18

**Vehicle NOT IN workshop. Kindly arrange for survey.**

Your insured Veh No : SGQ 7649 K

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr.Lim Lin Siong  
**Address** : Blk 187 Tanjong Rhu  
: # 08-06  
Singapore 436925  
**Telephone** : HP +65 91004153  
**Type of Claim** : Third Party Claim  
**Policy No.** : 5099304181  
**Vehicle No** : **SFL 357 L**  
**Model Code** : AUDI A3 1.0 TFSI  
**Model / Year** : Apr-17  
**Engine No** : CHZ 146767  
**Chassis No** : WAUZZZ8V6H1020659  
**Mileage** : -  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 25-Aug-18  
**Place of Accident** : Simei Ave(outside CGH)

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SFL 357L .

| S/N                  | Nature of Jobs                                                                                                          | Estimated Charges        |
|----------------------|-------------------------------------------------------------------------------------------------------------------------|--------------------------|
| 1                    | To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. | S/N \$ 360.00 ✓          |
| 2                    | To dismantle and renew front bumper. Re-organise front crash management components .Reinstall all parts removed.        | \$ <del>900.00</del> 500 |
| 3                    | To respray front bumper.                                                                                                | \$ <del>800.00</del> 500 |
| 4                    | To carry out diagnostic check.                                                                                          | S/N \$ 192.00 ✓          |
| TOTAL LABOUR CHARGES |                                                                                                                         | : <u>\$ 2,252.00</u>     |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SFL 357 L

| S/N                         | Parts Description                        | Damage Parts & Prices |         |
|-----------------------------|------------------------------------------|-----------------------|---------|
|                             |                                          | S/NETT                | REMARKS |
| 1                           | FRONT BUMPER <i>Repair</i>               | \$ 1,739.00           | X       |
| 2                           | FIXING PARTS FOR FRONT BUMPER <i>new</i> | \$ 161.00             | X       |
| 3                           | GUIDE SETCION - LH/RH <i>new</i>         | 2 \$ 66.00            | X       |
| 4                           | GRILLE - LOWER CENTRE                    | \$ 140.00             | X       |
| 5                           | CLOSING ELEMENT - LOWER CENTRE           | \$ 460.00             | X       |
| 6                           | COVER TRIM - LH / RH <i>new</i>          | 2 \$ 280.00           | X       |
| 7                           | RADIATOR GRILLE <i>new</i>               | \$ 1,239.00           | X       |
| 8                           | CLOSING ELEMENT <i>new</i>               | \$ 167.00             | X       |
| 9                           | FOAM FILLER PIECE <i>new</i>             | \$ 162.00             | X       |
| 10                          | SIDE REINFORCEMENT                       | \$ 633.00             | X       |
| 11                          | CAR PLATE - FRONT <i>new</i>             | S/N \$ 25.00          | X       |
| 12                          | SUNDRIES ?                               | \$ 300.00             | 7       |
| <b>TOTAL SPARE PARTS</b>    |                                          | <b>: \$ 5,372.00</b>  |         |
| <b>TOTAL LABOUR CHARGES</b> |                                          | <b>: \$ 2,252.00</b>  |         |
| <b>GRAND TOTAL</b>          |                                          | <b>: \$ 7,624.00</b>  |         |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian King*  
Surveyed Date : *30/08/18.*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *Not Authorised, 03 Days*

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant