

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0986/2018/PH
Date : 28-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured Veh No : SGQ 7649 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr.Lim Lin Siong
Address : Blk 187 Tanjong Rhu
: # 08-06
Singapore 436925
Telephone : HP +65 91004153
Type of Claim : Third Party Claim
Policy No. : 5099304181
Vehicle No : **SFL 357 L**
Model Code : AUDI A3 1.0 TFSI
Model / Year : Apr-17
Engine No : CHZ 146767
Chassis No : WAUZZZ8V6H1020659
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Aug-18
Place of Accident : Simei Ave(outside CGH)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFL 357L .

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00
2	To dismantle and renew front bumper. Re-organise front crash management components .Reinstall all parts removed.	\$ 900.00
3	To respray front bumper.	\$ 800.00
4	To carry out diagnostic check.	S/N \$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,252.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFL 357 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,739.00	
2	FIXING PARTS FOR FRONT BUMPER	\$ 161.00	
3	GUIDE SETCION - LH/RH	2 \$ 66.00	
4	GRILLE - LOWER CENTRE	\$ 140.00	
5	CLOSING ELEMENT - LOWER CENTRE	\$ 460.00	
6	COVER TRIM - LH / RH	2 \$ 280.00	
7	RADIATOR GRILLE	\$ 1,239.00	
8	CLOSING ELEMENT	\$ 167.00	
9	FOAM FILLER PIECE	\$ 162.00	
10	SIDE REINFORCEMENT	\$ 633.00	
11	CAR PLATE - FRONT	S/N \$ 25.00	
12	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 5,372.00	
TOTAL LABOUR CHARGES		: \$ 2,252.00	
GRAND TOTAL		: \$ 7,624.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant
