

ASS. REC. BY

REF: CS/CTE18015797/Uvd3 N2

Special Instruction

MV/Venue
meimen

Darius

ASSIGNMENT (Office)

From (Person)

Chong Boon Sen

of

CTE

Date/Time

24/8/18 @ 11:48 am

Estimated Cost

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 5938X

Insured:

SKV 3064A

at Workshop m/s

SOC Leon Motor

Tel:

6747 7858

of

1 Kaki Bkt Ave 6 #01-01

Policy No:

DMPCSN1543491702

Claim No:

SNM18D04156C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/08/2018

CA / REV / REP. / REV 24 HRS

lup

30/8/18 @ 2:30pm - 3pm

H.O.D. Endorsement:

Date/Time

2:01pm @ 24/8/18

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 5938X-X
	SKV 3064A-X

(00/11/13) wof

ASS. REC. BY: +

news.

REF:

CTI

ASSIGNMENT

From:

Date:

30/8/18

Estimated Cost:

OP / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBH 5938X

at Workshop m/s:

SOC LEON MOTOR

of

1 Kaki Bkt Ave 6 # 01-91

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

2:30pm - 3pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

1.3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH 5938X

Yr Regn:

7 / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

LM

Make:

Toyota Dyna

C.C

2982

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

3341

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT FAT 35Y 60K 210979

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/S / S/Rim / STD A/Rim or

Tyre Size:

F:

195-R15

R:

155-R12

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6/6

mm

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

24/8/18

D.O.I.

30/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear a/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/10/18 #3201-25 confirmed with mere. (Red 968.19, 23/9)

RECEIVED 4 OCT 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

4/10 - typist

Report Format :

merimen

Lump Sum / I.B.I. (\$

3201.25

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015797/Uvd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 3064A	Veh. Inspected	GBH 5938X
Policy No.	DMPCSN1543491702	Coverage (\$)	0.00
Claim No.	SNM18D04156C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	29/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/08/2018	Inspection Date	30/08/2018
Survey held at	SOC LEON MOTOR WORKS 1 KAKI BUKIT AVE 6 BLK D #01-91 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Aug 2018		29 Aug 2018 11:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JAMES J ROZARIO , ID: S1255335H		
Main Claimant:	CHYE KIM TRADING , Co. Reg. No.: 53031511D		
Vehicle Reg. No.:	GBH5938X	Date of Loss:	24/08/2018 09:00 - :59
Claim Type:	TP / SNM18D04156C02	Policy/Cover Note No.:	DMPCSN1543491702 (Comprehensive)
Vehicle Reg. No. (Insured):	SKV3064A	Policy No. (Claimant):	5102185656
		Excess:	S\$0.00
Repairer:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 7858		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/09/2018]		
Driver/Custodian (Insured):	GERARD JAMES ROZARIO (28 / Male), NRIC: S9023317C, Tel: +6591737374		
Adj Asg. Remarks:	EST \$3969.44 , ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 1511D

Vehicle Details

Vehicle No.: GBH5938X

Vehicle to be Exported: No

Intended De-registration Date: 30 Aug 2018

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 5MT

Primary Colour: Silver

Manufacturing Year: 2018

Engine No.: 1KD2811110

Chassis No.: JTFAT35Y60K210979

Maximum Power Output: -

Open Market Value: \$27,084.00

Original Registration Date: 18 Jul 2018

First Registration Date: 18 Jul 2018

Transfer Count: 0

Actual ARF Paid: \$1,355.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Jul 2028

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$26,326.00

COE Rebate Amount: \$26,007.00

Total Rebate Amount: \$26,007.00

The information contained herein is correct as at 30 Aug 2018

OK

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE

速良摩哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒奸噴漆
代理保險：車禍
賠償及買賣汽車

M/S CHYE KIM TRADING

DATE: 27/08/2018

DOA: 24/08/2018

REPAIR COST FOR VEHICLE NO. GBH 5938X (TOYOTA DYNA)

	Description		List Price	
1 pc	Tailgate	20/24	\$ 1,712.10	✓
1 pc	Taillamp (lh) 266.02	3/20	\$ 374.45	✓
1 pc	Taillamp bracket (lh)		\$ 178.85	+
1 pc	Toyota sticker	1/25	\$ 185.00	+
1 pc	Rear end panel	R	\$ 591.60	+
1 pc	Side tailgate lock (lh)	2/21	\$ 172.45	✓
1 pc	Stopper bracket (lh)	2/21	\$ 121.10	✓
1 pc	Stopper rubber (lh) 65.00	20/21	\$ 143.70	✓
			\$ 3,479.25	
		Less: 25%	\$ (869.81)	
			\$ 2,609.44	
	1 set Rear reverse sensor 290 cno ✓ S.N			
	Special Nett Items			
1 pc	Dyna sticker	rec	\$ 40.00	✓
1 pc	70km/h sticker	rec	\$ 10.00	✓
1 pc	13 PAX sticker	rec	\$ 10.00	✓
	Labour charges for knocking & replacing parts.		\$ 700.00	600
	Spraypainting		\$ 600.00	450
	TOTAL: 4169.44		\$ 3,969.44	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No financial modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Not Authorized

30/8/18

take photo before repair

4 ch.

3/2 & 3201.25

1-2521.67
252
1891.25

S.N + 200
1450 + 1050

3201.25

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015797/UVD3N2

Date: 09/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1543491702
Claimant Vehicle No :	GBH5938X	Insured Vehicle No :	SKV3064A
Date of Loss:	24/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04156C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH5938X	Engine No:	1KD2811110
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y60K210979
Reg. Date:	18/07/2018 (Man. Year: 2018)	Odometer:	3341 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	155R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,869.44	2,151.25	718.19	25.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	1,050.00	250.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,169.44	3,201.25	968.19	23.22

INSPECTION

Date of Assignment:	29/08/2018	
Date Inspected:	30/08/2018	Inspected At: Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Oct 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH5938X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented/Bent	1,712.10 FL	*1,712.10 FL
2	1		*TAILLAMP (LH)	Broken	374.45 FL	*266.02 FL
3	1		*TAILLAMP BRACKET (LH)	Repair	178.85 FL	*- FL
4	1		*TOYOTA STICKER	Necessary	185.00 FL	*185.00 FL
5	1		*REAR END PANEL	Repair	591.60 FL	*- FL
6	1		*SIDE TAILGATE LOCK (LH)	Bent	172.45 FL	*172.45 FL
7	1		*STOPPER BRACKET (LH)	Bent	121.10 FL	*121.10 FL
8	1		*STOPPER RUBBER (LH)	Torn	143.70 FL	*65.00 FL
9	1		*SET REAR REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
10	1		*DYNA STICKER	Necessary	40.00 FS	*40.00 FS
11	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
12	1		*13 PAX STICKER	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,739.25	2,781.67
- List Item Discount on L Items 25.00/25.00% (\$\$)	869.81	630.42
Total Parts (\$\$)	2,869.44	2,151.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS	New	700.00	600.00
2	SPRAYPAINTING	New	600.00	450.00
Gross Labour Cost (S\$)			1,300.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >