

Surveyor

CWS

Bryen

ASSIGNMENT (Office)

From (Person)

May chua

of

FCI

Date/Time

2d/8/18 @ 9:53am

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 17134

Insured:

8HD 6570R

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMK Autopoint #01-05

Policy No:

Claim No:

D18006423MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

10:19am @ 2d/8/18

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SHA17134-CS	#17016645/Gtbe2
	8HD6570R-X	DOA: 10/8/17
3/9/18	Email preli revised to FCI	

ASSIGNMENT

COR 2024 M-u

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 1/2 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHA 1713U

Yr Regn: 2016, M-u

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue AC: Insured / Std / NI / NA

Sp. Reading: 435633 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDFU596456

G/No: KMHLB4UMGU085591

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: N/S / Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 21/08/2018 D.O.I. 29/08/2018

Survey held at Churni Amk

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or.

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	First Capital SHD 6570R

25/09/18	Yinajur 2/5 8900/- with 8 days of work
27/09/18	Confirmed 1/5 \$ 8,900/- @ 8 days with Bryan (\$ 4,928.64 Red - 36%)

RECEIVED 27 SEP 2018

Date/Time, File Pass to?

27/09/18

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) S + R.S. 50

) Photos 116

) Others 32/11/18

) 481

Report Format :

Lump Sum / I.B.I: (\$ 8,900/- 1/5)

3x15=45

170+45

50

50+50

116

481



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006423MFSH
Our ref: CS/FCI18015800/Dsd3

Date: 3/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 1713U


We thank you for your instruction on 29/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29/8/2018 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$13,828.64
Revised Estimate Amount	: S\$11,669.60
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	28-08-2018	Our Ref No.	D18006423MFSH
Accident Date	26-08-2018	Claim Type.	Third Party
Insured Vehicle	SHD6570R	Third Party Vehicle.	SHA1713U
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06		
Contact Person.	LYNN OR IRENE - 65421726		
Contact No.	65427162/ 0	Fax No.	65426039
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	MAY CHUA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 3 September 2018 4:01 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006423MFSH/1, SHA 1713U
Attachments: SHA 1713U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHA 1713U
Date of survey: 29/8/2018
Number of days : 6 days

Best Regards,

Veron Chen | Case Handler on behalf Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 29 August 2018 10:21 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006423MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 29 August 2018 9:52 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006423MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHA 1713 U
Technician:
Mileage: 435633
Time Printed 29.8.18 5:00 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
13°16'		-3°00' 3°00'
3°50'		-0°19' 5°41'
26°25'		-1°30' 1°30'
4°24'		
17°40'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
1°30'		-3°00' 3°00'
3°53'		-0°19' 5°41'
-0°20'		-1°30' 1°30'
10°41'		
12°11'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
11°46'		-3°00' 3°00'
-0°03'		-3°00' 3°00'
-6°17'		-3°00' 3°00'
26°05'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°45'		-3°30' 2°30'
0°22'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-2°15'		-3°30' 2°30'
-0°21'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°30'		-3°00' 3°00'
0°01'		-3°00' 3°00'
0°21'		-3°00' 3°00'

10 Survey by LFL

LKK Auto Consultants hence notify

DATE : 27.08.2018

• To resurvey before/after spray painting

TEL : 6542 5110
• To display damage, contact us by e-mail

FAX : 6542 6039

562.30

* Supplementary item(s) must be resurveyed in 2015. The amount is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature: _____

Date _____

12293.60
9834.88

Nett 1

Nett ✓

500/-

400 ✓

30/-

 $\frac{7}{2}$

1801

601.

100

1

1

111 77

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4/58900-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015800/Dsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6570R	Veh. Inspected	SHA 1713U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006423MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU085591	Colour	BLUE	
Odometer	435633	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	8 mm	
L/H Front Tyre	205/60 R16	HANKOOK	8 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	8 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2018	Inspection Date	29/08/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1713U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	MOUNTING CRACKED	1,052.20	562.30
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,067.50	1,067.50
1	HEADLAMP (LH)	MOUNTING BROKEN	1,388.00	1,388.00
1	FRONT DOOR MIRROR (LH)	BROKEN	980.50	980.50
1	FRONT WHEEL RIM (LH)	BENT	351.90	351.90
1	FRONT WHEEL HUB CAP (LH)	BENT	150.70	150.70
1	FRONT WHEEL BEARING	DAMAGED	258.50	258.50
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	75.10	-
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,069.55	1,069.55
1	RACK & PINION ASSY	DISTORTED	2,184.00	2,184.00
1	STG TIE END	DISTORTED	69.50	69.50
1	STABILIZER BAR	DISTORTED	252.30	252.30
1	STABILIZER BAR BUSH (LH)	NOT NECESSARY	16.10	-
1	STABILIZER BAR LINK	DISTORTED	81.70	81.70
1	STABILIZER BRACKET	NOT NECESSARY	24.00	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	715.10	715.10
1	KNUCKLE ARM (LH)	DISTORTED	582.95	582.95
1	ENGINE UNDER COVER	NOT NECESSARY	343.10	-
1	ENGINE CROSSMEMBER	DISTORTED	2,236.90	2,236.90
1	ABS SENSOR	NOT NECESSARY	261.50	-
	LESS 20% DISCOUNT		-2,700.66	-2,458.72
			10,802.64	9,834.88
SPECIAL NETT ITEMS				
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	FRONT TYRE (LH)(80%)(DEPRECIATION)(SN)	PUNCTURE	216.00	172.80
			316.00	272.80
LABOUR				
	PANEL BEATING.		900.00	500.00

Report Ref No. CS/FCI18015800/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		900.00	400.00
	WIRING CHARGE.		50.00	30.00
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	180.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			2,710.00	1,170.00
	GRAND TOTAL		13,828.64	11,277.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,900.00

Report Ref No. CS/FC118015800/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.