

ASS. REC. BY:

REF:

CS/FCL18015801/U.r d3ⁿ²

Special Instruction

Surveyor

rwS

Macrus

ASSIGNMENT (Office)

From (Person)

May chuan

of

PCI

Date/Time

29/8/18 9:51am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JX 3634 G

Insured:

SHA 3220 L

at Workshop m/s

Yew Tee Automobile

Tel:

6765 3373

of

Blk G, woodlands Rd 399F

Policy No:

Claim No:

D18004657MFSH

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

08/06/2018

Insp: 25kaki Rd 4 #01-60/61

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(DS)

Date/Time:

10:07am 29/8/18

Person Contacted:

800 yf

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	8JX 3634 G-X
	SHA 3220 L-CC3/TMI/7021678/MHbn2 DOA:9/11/17
31/8/18	Revert prot thm email.

(08/11/13) wef

REF:

ASS. REC. BY: MARCUS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 57X36346at Workshop m/s YELW 7200

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 40

IDAC Accident Report: _____ Consistent? : Yes or No

GLA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes- or No

CA / REV / REP. / 24 HRS

27A 29634

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 57X36346Yr Regn: 3110

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: BMW 323i c.c. 2497Colour: Black A/C: Insured / Std / NI / NASp. Reading: 125710 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAWL32050PP59635

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/40Z R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

2 ALKen

Front

6

R/Bal. _____ mm

Rear

6

R/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 8/6/18D.O.I. 29/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

6/9/18 1/5 x 2600 conf. with Shuyi

Red: 16496.97, 711.

RECEIVED 06 SEP 2018

Date/Time, File Pass to?

☐

Preli. Report

1) typist☒

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.L. (\$) 2600

170
50
50
52
322




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015801/Uz4d3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3220L	Veh. Inspected	SJX 3634G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004657MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/06/2018	Inspection Date	29/08/2018	
Survey held at	25 KAKI BUKIT RD 4 # 01-60			
Repairer	YEW TEE AUTOMOBILE TECH PL (HQ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004657MFSH

Our Ref: CS/FCI18015801/Urd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJX 3634G

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29.08.2018 at the premises of M/s YEW TEE AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,096.97</u>
Revised Estimate Amount	: S\$ <u>2,736.37</u>
"Check" Items Amount	: S\$ <u>545.78</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages
at rear portion.



Yours faithfully
MARCUS
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	11-06-2018	Our Ref No. D18004657MFSH
Accident Date	08-06-2018	Claim Type. Third Party
Insured Vehicle	SHA3220L	Third Party Vehicle. SJX3634G
Survey Location	BLK 6 WOODLANDS ROAD 399F YEW TEE INDUSTRIAL ESTATE	
Contact Person.	VINNIE LIM	
Contact No.	67653373/ 0	Fax No. 67604895
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5989J

Vehicle Details

Vehicle No.: SJX3634G
Vehicle to be Exported: No
Intended De-registration Date: 29 Aug 2018
Vehicle Make: B.M.W.
Vehicle Model: 323i A
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: N52B25AE10897250
Chassis No.: WBAWL32050PP59635
Maximum Power Output: 139.0 kW (186 bhp)
Open Market Value: \$48,853.00
Original Registration Date: 18 Mar 2010
First Registration Date: 18 Mar 2010
Transfer Count: 2
Actual ARF Paid: \$48,853.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Mar 2020
PARF Rebate Amount: \$26,869.00

Intended COE Rebate Details

COE Expiry Date: 17 Mar 2020
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$17,889.00
COE Rebate Amount: \$2,765.00
Total Rebate Amount: \$29,634.00

The information contained herein is correct as at 29 Aug 2018

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Undriven Mar 2018 Mazda 3 @80K 100% ZERO Drive-



Inhouse Loan/\$0 Drive-away/fr
3.25%/no Hidden Fees/FOC
Leather Seat/DVR,call Now
Privilege Group Pte StarAd

PRIME MOTOR & LEASING

(HONG KONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

bmw 323

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 323		Any	Any	2010	Any	Any	Any	Available
	BMW 3 Series	323i Convertible	\$41,688	\$12,640 /yr	04-Jan-2010	2,497 cc	140,000 km	Sports	Available
Superb Condition, Beautiful White With Red Interior, Its The Perfect Lifestyle Car For Work And Leisure. Regular Serviced, Accident Free, Low Mileage, No Repair Needed, Call Now To Arrange For Viewing...									
Posted: 23-Aug-2018 Tags: 2010 BMW 323i, BMW 323i, BMW, 323i, Used BMW									
	BMW 3 Series	323i	\$43,800	\$13,790 /yr	26-Feb-2010	2,497 cc	39,641 km	Luxury	Available
Very Low Mileage Done, In House Loan Or Bank Loan Available! Well Kept. Clean And Neat Interior. View To Believe.									
Hui Hua Credit Pte Ltd									
Posted: 21-Aug-2018 Tags: 2010 BMW 323i, BMW 323i, BMW, 323i, Used BMW									
	BMW 3 Series	323i Convertible	\$47,888	\$12,710 /yr	13-May-2010	2,497 cc	140,000 km	Sports	Available
Fantastic Condition, Beautiful Interior, Its The Perfect Lifestyle Car For Work And Leisure! Regular Serviced, Accident Free, No Repair Needed, Call Now To Arrange For Viewing Anytime Any Where.									
Posted: 18-Aug-2018 Tags: 2010 BMW 323i, BMW 323i, BMW, 323i, Used BMW									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 323, bmw 323 Singapore, used bmw 323 Singapore, used bmw 323, used vehicles Singapore or even buy used bmw 323 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311199C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1808/014
Policy No:	GA059506	Date of Loss:	08/06/2018
Vehicle Reg. No.:	SJX3634G	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHA3220L
Any Injuries?	yes	Contact No:	94561945
Insured/Claimant:	NATASHA NUR BINTE SULAIMAN	Driver:	AZMIN BIN JAILANI
Make/Model:	BMW, 325ci - WBAWB32020PV52459	Vehicle Reg. Date:	18 Mar 2010
Vehicle Colour:	GREY	Engine Number:	N52B25AE10897250
Chassis No:	WBAWL32050PP59635	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	4,381.97
Miscellaneous Items	3,245.00
Labour	810.00
Paintwork Labour	660.00
Towing	0.00
Gross Total(S\$):	9,096.97
GST 7.00%(S\$):	636.79
Nett Amount(S\$):	9,733.76

This claim is handled by: Sky Toh T C

Not Allowed
29/8/18
John, photo attached
30/8/18
2/5 \$2600

LKK Auto Consultants hence notify the Repaire of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaire

Signature:

Date:

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>DD/De</i>	1,166.85	1,166.85	-5.00	1,108.51 ✓
2	1	REAR BUMPER BRACKET LH <i>nu</i>	38.35	38.35	-5.00	36.43 ✓
3	1	REAR BUMPER BRACKET RH <i>nu</i>	38.35	38.35	-5.00	36.43 ✓
4	1	REAR BUMPER REINFORCEMENT <i>DD</i>	424.25	424.25	-5.00	403.04 ✓
5	1	REAR BUMPER CENTRE BRACKET <i>CNE</i>	150.25	150.25	-5.00	142.74 ✓
6	1	REAR TAILLAMP LH <i>1 1</i>	377.85	377.85	-5.00	358.96 ✓
7	1	REAR TAILLAMP RH <i>1 1</i>	377.85	377.85	-5.00	358.96 ✓
8	1	BOOT LID <i>1 1</i>	2,038.85	2,038.85	-5.00	1,936.91 ✓
9	1	REAR END PANEL <i>1 1</i>	0.00	0.00	-5.00	0.00 ✓

Total Parts (\$\$) 4,381.97

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS <i>nu</i>	45.00	45.00	0.00	45.00 ✓
2	4	REAR BUMPER SENSORS <i>shd 2 1/2 x 2 = 430</i>	800.00	3,200.00	0.00	3,200.00 ✓

Sub Total (\$\$) 3,245.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 ✓
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	700.00	700.00	0.00	700.00 ✓

Gross Labour Cost (\$\$) 810.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 ✓
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	600.00	600.00	0.00	600.00 ✓

Gross Labour Cost (\$\$) 660.00

< END OF ESTIMATES >

P-1818.04
 52
 1727.14
 S.N - 475
 labor - 1080
 3282.14




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015801/Urd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877			Date : 10-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3220L	Veh. Inspected	SJX 3634G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004657MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 323i (A)	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAWL32050PP59635	Colour	BLACK	
Odometer	125710	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 ZR18	FALKEN	6 mm	
L/H Front Tyre	225/40 ZR18	FALKEN	6 mm	
R/H Rear Tyre	225/40 ZR18	FALKEN	6 mm	
L/H Rear Tyre	225/40 ZR18	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/06/2018	Inspection Date	29/08/2018	
Survey held at	BLK 25 KAKI BUKIT ROAD 4 #01-60/61			
Repairer	YEW TEE AUTOMOBILE TECH PL (HQ)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 3634G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	1,166.85	1,166.85
1	REAR BUMPER BRACKET LH	NECESSARY	38.35	38.35
1	REAR BUMPER BRACKET RH	NECESSARY	38.35	38.35
1	REAR BUMPER REINFORCEMENT	DENTED	424.25	424.25
1	REAR BUMPER CENTRE BRACKET	CRACKED	150.25	150.25
1	REAR TAILLAMP LH	NOT NECESSARY	377.85	-
1	REAR TAILLAMP RH	NOT NECESSARY	377.85	-
1	BOOT LID	TO REPAIR SEE LABOUR	2,038.85	-
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 5% DISCOUNT		-230.63	-90.90
			4,381.97	1,727.15
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
4	REAR BUMPER SENSORS @\$800.00 (SN)	SHORTED (2 PCS ONLY)	3,200.00	430.00
			3,245.00	475.00
LABOUR				
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		30.00	30.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	50.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF BOOT LID AND REAR END PANEL.		700.00	400.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	60.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		600.00	600.00
			1,470.00	1,080.00
GRAND TOTAL			9,096.97	3,282.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/FCI18015801/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.