

ASSIGNMENT

Surveyor:

WMT

DOI:

17/9/18

Date / Time:

29/08/2018

Registered in Merimen:

29/8/2018

Pre-assign / CCU / FTE

SH8111T



Insured Vehicle No.:

SH8111T

Name of Insured:

C7P2

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 29/08/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Pahim B. DANOO

Driver Tel No.:

93909483

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

M. Lomooi

H. LOMG

X June. of Science Park Rd & Pwly Panjany Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKN 3818J



INSRS:

WSP:

Tel:

Liability:

RMKS:

pne



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time		STAGE	DATE / PIC
2/9/18	SKN 3818J - X;	Non-Reporting ltr (1st):	
	SH8111T - 11/11/18 1500 4242/1122302; 10/8/18	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
3/9/18	Seek liability via merimen	After call ltr to OI:	NA
4/9/18	liability clear via merimen	Documentation Check List:	Handler Typist
	Email wkshop liability clear.	Notification ltr (if non-pickup)	☒
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
29-1-19	LOD IN - FOR MANDATE.	Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION		Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	S\$	(days)	Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email ☐ Call ☐	
Final Liability:	%	100 (Agreed / Assessed)	BOLA S/N No.:	27.	If NO or B 28, Ass. Lia:
Repair Cost:	S\$	4,606.62			
Loss of Rental (LOR):	S\$	(days)			
Loss of Use (LOU):	S\$	300 (\$ 100 x 3 days)			
Loss of Income (LOI):	S\$	(\$ x days)			
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]				
GIA/LTA Search	S\$	-			
Medical:	S\$	-			
Disbursement:	S\$	-	(e.g. Tow/ Independent)		
Legal Cost	S\$	-			
Total:	S\$	4,906.62	Global Sum S\$:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	S\$	4,906.62	Name 1:	PERFORMANCE MOTORS LIMITED	
Payee 2: (Strike if N.A.)	S\$	X	Name 2:	X	
Payee 3: (Strike if N.A.)	S\$	X	Name 3:	X	

Surgeon Paul H

REF:

III

11/8/11 / 1/1/11 (W)

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 2.8 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Kevin

Veh No: SKN 3818J Yr Regn: 2014 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X3 20i C.C. 1997.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 68763 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAWY320500328 674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50 R16 R: 77

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/12/18 Confirm > R > \$4305.25 with 3 working days

(red - \$3716.78 47%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

29 AUG 2018

ESTIMATE

Estimate No. : b1 48234
Date Estimated : 28/08/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lee Jen Pink
463 Pasir Panjang Road
#01-04 The Village

Singapore 118797

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN3818J	0B28674	04/04/2014	X3 xDrive20i	0

DESCRIPTION

To replace rear bumper, carrier, reinforcement & all attachments cause by accident

850 2,550.00

Painting on rear bumper assembly

934 1,038.00

To check electrical wiring systems at the rear section for proper function.

150 177.00

Sundries. *New*

? *new* 150.00

Total Labour 1: 3,915.00

DESCRIPTION

SET TRIM TOWING LUG

QTY 1 PRIC 69.70

VALUE 69.70

Set of mount

1 35.10

35.10

RR BUMPER CARRIER ECE

1 738.05

738.05

MOUNT BUMPER REAR LH

1 192.15

192.15

MOUNT BUMPER REAR RH

1 192.15

192.15

COVERING BOTTOM REAR

1 79.80

79.80

RR BUMPER LH MIDDLE MOUNT

1 142.55

142.55

RR BUMPER RH MIDDLE MOUNT

1 142.55

142.55

COVER TRIM REAR BLACK (PDC)

1 197.35

197.35

RR BUMPER (PRIMED)

1 1,342.35

1,342.35

DEFLECTOR LIP REAR LH

1 12.65

12.65

DECOUPLING RING PDC TORQUE CONVERTE

4 5.05

20.20

BUMPER PDC SENSOR (SCHWARZ)

2 236.85

473.70

Total Parts : 3,638.30

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 48234**
Date Estimated : **28/08/2018**
Prepared By : **Kevin Leong Wai Kit**Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN3818J	0B28674	04/04/2014	X3 xDrive20i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 12/9/18 E 1115 Claim No.

Date & Time 12/9/18 E 1115 Excess \$

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97495244 Approved Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR No Yes

Surveyor's Email tanjiah@lkkauto.com

No. of Working Days Resurveyed 03 days

Labour 1	:	3,915.00
Parts	:	3,638.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	528.73
Grand Total	:	8,082.03

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 48234
Date Estimated : 28/08/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Lee Jen Pink
463 Pasir Panjang Road
#01-04 The Village

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 118797

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKN3818J	0B28674	04/04/2014	X3 xDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET *	1.35	10.00		13.50

Total Labour :	
Total Parts :	13.50
Total Labour & Parts :	13.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020061-X



FINAL REPORT

Estimate No. : b1 48234
Date Estimated : 28/08/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1

REPAIR FOR -
Lee Jen Pink
463 Pasir Panjang Road
#01-04 The Village

- ACCOUNT - 219
India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 118797

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEASE
SKN3818J	0B28674	04/04/2014	X3 xDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00 ✓
To spray paint rear bumper	934.00		934.00 ✓
To check electrical wiring systems at the rear section for proper function.	150.00		150.00 ✓
Sundries.	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER CARRIER ECE ✓	738.05	1.00		738.05 ✓
COVER TRIM REAR BLACK (PDC)	197.35	1.00		197.35 ✓
RR BUMPER (PRIMED)	1,342.35	1.00		1,342.35 ✓
# EXPANDING RIVET *	1.35	10.00		13.50 ✓

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	2,291.25
Total Labour & Parts :	4,305.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,305.25
GST @7%:	301.37
Grand Total :	4,606.62

View Received Message

This mail is associated with :

***SKN3818J (MCT18080823)**
[SH8111T]

TP
LEE JEN PINK
Aug 27 2018 8:00PM

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 03/09/2018 16:23 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SKN3818J - Claim Handler: Zuhaidah Bte Samsuri

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

Print Received Message

This mail is associated with :

***SKN3818J (MCT18080823)**

[SH8111T]

TP

LEE JEN PINK

Aug 27 2018 8:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 01/02/2019 17:18 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4906.62) - SKN3818J - Claim Handler: Zuhaidah Bte Samsuri

Approved:4906.62.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018 Edit Reg		12 Sep 2018 00:00 Edit Adj Rpt	S\$4,305.25 Edit Estimates	S\$4,305.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	LEE JEN PINK, ID: S7488865H								
Vehicle Reg. No.:	SKN3818J	Date of Loss:	27/08/2018 20:00 - :59 [52 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18080823	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH8111T	Policy No. (Claimant):	10117908						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/09/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
- III_SG (01/02/2019): Alert - Adj Mandate Approved (S\$4906.62) - SKN3818J - Claim Handler: Zuhaidah Bt... - III_SG (03/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SKN3818J - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN3818J (MCT18080823)
[SH8111T]
TP
LEE JEN PINK
Aug 27 2018 8:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View	Use Viewer
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/19 09:16	General View	 Load JPG	☒
2	01/02/19 09:16	General View	 Load JPG	☒
3	01/02/19 09:16	General View	 Load JPG	☒
4	01/02/19 09:16	General View	 Load JPG	☒
5	01/02/19 09:16	General View	 Load JPG	☒
6	01/02/19 09:16	General View	 Load JPG	☒
7	01/02/19 09:16	General View	 Load JPG	☒
8	01/02/19 09:16	General View	 Load JPG	☒
9	01/02/19 09:16	General View	 Load JPG	☒
10	01/02/19 09:16	General View	 Load JPG	☒
11	01/02/19 09:16	General View	 Load JPG	☒
12	01/02/19 09:16	General View	 Load JPG	☒
13	01/02/19 09:16	General View	 Load JPG	☒
14	01/02/19 09:16	General View	 Load JPG	☒
15	01/02/19 09:16	General View	 Load JPG	☒
16	01/02/19 09:16	General View	 Load JPG	☒
17	01/02/19 09:16	General View	 Load JPG	☒
18	01/02/19 09:16	General View	 Load JPG	☒
19	01/02/19 09:16	General View	 Load JPG	☒
20	01/02/19 09:16	General View	 Load JPG	☒
21	01/02/19 09:16	General View	 Load JPG	☒
22	01/02/19 09:16	General View	 Load JPG	☒
23	01/02/19 09:16	General View	 Load JPG	☒
24	01/02/19 09:16	General View	 Load JPG	☒
25	01/02/19 09:16	General View	 Load JPG	☒
26	01/02/19 09:16	General View	 Load JPG	☒
27	01/02/19 09:16	General View	 Load JPG	☒
28	01/02/19 09:16	General View	 Load JPG	☒
29	01/02/19 09:16	General View	 Load JPG	☒
30	01/02/19 09:16	General View	 Load JPG	☒
31	01/02/19 09:16	General View	 Load JPG	☒
32	01/02/19 09:16	General View	 Load JPG	☒
33	01/02/19 09:16	General View	 Load JPG	☒
34	01/02/19 09:16	General View	 Load JPG	☒
35	01/02/19 09:16	General View	 Load JPG	☒
36	01/02/19 09:17	Reinspection Photo	 Load JPG	☒
37	01/02/19 09:17	Reinspection Photo	 Load JPG	☒
38	01/02/19 09:17	Reinspection Photo	 Load JPG	☒
39	01/02/19 09:17	Reinspection Photo	 Load JPG	☒
40	01/02/19 09:17	Reinspection Photo	 Load JPG	☒
41	01/02/19 09:17	Reinspection Photo	 Load JPG	☒

42	01/02/19 09:17	Reinspection Photo	1	Load JPG	☒
43	01/02/19 09:17	Reinspection Photo	1	Load JPG	☒
44	01/02/19 09:17	Reinspection Photo	1	Load JPG	☒
45	01/02/19 09:17	Reinspection Photo	1	Load JPG	☒
Documentation					
				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/08/18 19:04	TP ESTIMATE + DOCS	1	Load PDF	
2	29/08/18 19:04	TP GIA REPORT	1	Load PDF	
3	14/09/18 09:25	TP ESTIMATE - MARKED	1	Load PDF	
4	29/01/19 12:27	WORKSHOP INVOICE	1	Load PDF	
5	29/01/19 12:27	LOD	1	Load PDF	
6	13/02/19 10:58	AUTHORISATION TO ACT FORM	1	Load PDF	
7	13/02/19 10:58	DISCHARGE VOUCHER	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	30/08/18 08:53	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18015811/T1JA3N2

Date: 13/02/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SKN3818J Insured Vehicle No: SH8111T
 Date of Loss: 27/08/2018 Nature of Claim: TP Claim No: MCT18080823

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN3818J
 Make & Model: BMW X3, 2.0 xDrive20i (A) Engine No: B7460646N20B20A
 Reg. Date: 02/04/2014 (Man. Year: 2013) Chassis No: WBAWX320500B28674
 Colour: Black Odometer: 68763 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R16 Rear Tyre Size: 245/50 R16
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,801.80	2,371.25	1,430.55	37.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,765.00	1,934.00	1,831.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,566.80	4,305.25	3,261.55	43.10
+ GST 7.00/7.00% (S\$)	529.68	301.37	228.31	43.10
Nett Amount (S\$)	8,096.48	4,606.62	3,489.86	43.10
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		4,906.62		

INSPECTION

Date of Assignment: 12/09/2018
 Date Inspected: 12/09/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2019)
Parts:	M1-SUV	BMW X3 2.0 xDrive20i (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN3818J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*SET TRIM TOWING LUG	Not Necessary	69.70 FS	*- FS
3	1		*SET OF MOUNT	Not Necessary	35.10 FS	*- FS
4	1		*RR BUMPER CARRIER ECE	Bent	738.05 FS	*738.05 FS
5	1		*MOUNT BUMPER REAR LH	Not Necessary	192.15 FS	*- FS
6	1		*MOUNT BUMPER REAR RH	Not Necessary	192.15 FS	*- FS
7	1		*COVERING BOTTOM REAR	Not Necessary	79.80 FS	*- FS
8	1		*RR BUMPER LH MIDDLE MOUNT	Not Necessary	142.55 FS	*- FS
9	1		*RR BUMPER RH MIDDLE MOUNT	Not Necessary	142.55 FS	*- FS
10	1		*COVER TRIM REAR BLACK (PDC)	Cut	197.35 FS	*197.35 FS
11	1		*RR BUMPER (PRIMED)	Deformed	1,342.35 FS	*1,342.35 FS
12	1		*DEFLECTOR LIP REAR LH	Not Necessary	12.65 FS	*- FS
13	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
14	2		*BUMPER PDC SENSOR (SCHWARZ)	Not Necessary	473.70 FS	*- FS
15	10		*EXPANDING RIVET	Necessary	13.50 FS	*13.50 FS
					F=Franchise part. S=SpcNett.	
					Total Parts (\$\$)	3,801.80 2,371.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,CARRIER ,REINFORCEMENT & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	2,550.00	850.00
2	PAINTING ON REAR BUMPER ASSEMBLY	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			3,765.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >