

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1020/2018/GW
Date : 1-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR Wee Qui-Cheng, Perlita
Address : 92 Hillview avenue
#03-01
Singapore 669592
Telephone : HP +65 93870777
Type of Claim : Third Party Claims
Policy No. : 2100510363-01
Vehicle No : **SLQ 1392 E**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Jun-17
Engine No : CVK 034838
Chassis No : WAUZZZF55HA033714
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Aug-18
Place of Accident : 51 Scotts Road Prudential @Scotts S228241 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 1392 E

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle front bumper. Re-organize front crash management components. Reinstall all parts removed.	\$ 1,050.00 500
3	To reapply coating on front radiator grille.	S/N \$ 230.00 ✗
3	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>1,952.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 1392 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER GRILLE <i>Not in</i>	\$ 171.00	+
2	RADIATOR GRILLE <i>Grille</i>	\$ 2,022.00	✓
3	RADIATOR GRILLE COVER <i>Not in</i>	\$ 165.00	+
4	FRONT CAR PLATE <i>New</i>	S/N \$ 25.00	✓
5	SUNDRIES <i>?</i>	\$ 300.00	X.
TOTAL SPARE PARTS		:	\$ 2,683.00
TOTAL LABOUR CHARGES		:	\$ 1,952.00
GRAND TOTAL		:	\$ 4,635.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 04/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 02 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

QUOTATION

BILL TO :

Name : ANDY TEO
 Contact Number :
 Vehicle Make/Model/Colour : AUDI A5 SPORTBACK WHITE
 Vehicle Registration Number : SLQ 1392 E

DATE : 31/8/2018
 QUOTATION : Q 1808065
 VALID : 30 DAYS

DESCRIPTION	AMOUNT (SGD)
Re-application - Front Grill	230.00
Invoice paid for initial application - Date : 5/7/2017 Invoice : 175786 Warranty - TR120174163 Package - Extreme	

ESTIMATE : \$ 230.00

INVOICE

BILL TO :

Name : ANDY TEO
Contact Number : 9387 0777

DATE : 5 July 2017

INVOICE : 175786

Vehicle Make/Model/Colour : AUDI A5 SPORTBACK WHITE

Vehicle Registration Number : SLQ 1392 E

Payment Mode : CASH / NETS / CREDIT

DESCRIPTION	AMOUNT
Extreme Packages	\$ 1,908.00
Discount on Package - 20%	\$ (381.60)
Booking Deposit Paid - Invoice: 175759	\$ (200.00)
Promotion Inclusive Ceramic PRO Umbrella Ceramic PRO Leather	
Warranty Number - 20174163	
<p>✦ Ceramic PRO Care - Newly Applied ✦</p> <p>✓ Do not use Shampoo for the 1st 3 days</p> <p>✓ Keep the surface dry. If surface get wet, Dab the surface dry with a lightly damp Microfiber towel. Do Not use Wiping motion.</p> <p>✓ In event any substances land on the surface, clean up as soon as possible</p> <p>✦ Basic Care for Owners ✦</p> <p>✓ Weekly wash with Quality Shampoo and dry with clean chamois cloth.</p> <p>✓ Remove bird dropping, tree saps as soon as possible. Soften the substances with tissue soaked with water. Gently lift the substances off. Do not rub or use force.</p> <p>✓ Apply Ceramic PRO SPORT after shampoo wash every fortnightly</p> <p>Ceramic PRO Prestige card will be mailed to the address provided on warranty registration.</p> <p>* Please register your warranty online to be effective within 14 days http://www.ceramicpro.com.sg/warranty-register/</p>	
TOTAL :	\$ 1,326.40
TOTAL DUE AFTER 3% DISCOUNT ON FINAL BILL :	1,286.61
Parking Rebate :	\$ (9.00)
Total Paid :	\$ 1,277.61