

ASS. REC. BY: Adrian Ling

REF:

cc3 / AIG18015815 / Atd3 n2

ASSIGNMENT

Mentmen

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

125K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 hrs.

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMD3570B.

Yr Regn:

2018 August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3

C.C

999.

Colour

White.

A/C:

Insured / Std / NI / NA

Sp. Reading

64.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ8V8J1066029.

Gen. Cond:

Good

/ Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16-

R:

205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

29/08/18

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD ALG.

SMD 3570 B *

Part by Part \$3071.76 (Red. 2654.24, 46%)

RECEIVED 03 APR 2019

Date/Time, File Pass to?



Preli. Report



Final Report

1) 3A Typist

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

200

10

Photos

Others

TOTAL

210

Report Format :

OD

Lump Sum / L.A. (\$ 3071.76)



COVER NOTE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder: ZHANG ZHONGQING
 Period of Insurance: 15 Aug 2018 to 14 Aug 2019
 Engine No.: CHZ 938207
 Chassis No.: WAUZZZ8V8J1066029



Vehicle No.: SMD 3570B
 Cover Note No.: 1800098317
 Endorsement No.:
 Issued Date: 14 Aug 2018

ABOUT THE COVER

Make/Model: AUDI A3 Sedan 1.0 TFSI S tronic
 Engine Capacity/Tonnage: 999.00 CC
 Driver Restriction: NA
 Person or Classes of Persons Entitled to Drive*:
 Sum Insured: Market Value
 Off Peak Car: No
 First Year of Registration: 2018
 Insuring with COE/PARF: Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition: 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)
 ZHANG ZHONGQING - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OVERSEA-CHINESE BANKING CORPN LTD

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
 We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0504125211

PREMIUM LEASING - NC

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

Staffany Loh

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number **S7465542D**
 Name
ZHANG ZHONGQING
 Birth Date: **17 Mar 1974**
 Issue Date: **13 Jul 2013**

002201746F

REPUBLIC OF SINGAPORE 

IDENTITY CARD NO. **S7465542D**


 Name
ZHANG ZHONGQING
 张 忠 青
 Race
CHINESE
 Date of birth **17-03-1974** Sex **F**
 Country of birth **CHINA**

S7465542D

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg **13 Jul 2013**


NP 428A

Licence No: S7465542D

4813587



NRIC No: **S7465542D**


 Date of issue
13-12-2012
APT BLK 260A ANG MO KIO STREET 21 #14-145
SINGAPORE 561260
 NRIC No: **S7465542D** Date: **04/06/2017**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0987/2018/PH
Date : 29-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Zhang Zhong Qing
Address : Blk 260A Ang Mo Kio St 21
: # 14-145
Singapore 561260
Telephone : HP +65 81809817
Type of Claim : Own Damage Claim
Policy No. : 1800098317
Vehicle No : **SMD 3570 B**
Model Code : AUDI A3 1.0 TFSI
Model / Year : Aug-18
Engine No : CHZ 938207
Chassis No : WAUZZZ8V8J1066029
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Aug-18
Place of Accident : Blk 260 St 21 Ang Mo Kio carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 35

S/N	Nature of Jobs	S/N	\$
1	To remove and transfer rear parking aid. Check function.		
2	To dismantle and renew rear bumper assy. Inspect rear panels for damage. Re-organise rear crash management components. Reinstall all parts removed.		
3	To respray rear bumper.		
4	To carry out diagnostic check.		
TOTAL LABOUR CHARGES			: \$ 2,172.00

0.0
280.0+
500.0+
550.0+
192.0+
=
1,522.0*
0.0
1,357.6+
164.4+
27.76+
=
1,549.76*
0.0
1,522.0+
1,549.76+
=
3,071.76*
\$
S/N \$ 192.00 ✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 3570 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>sch</i>	\$ 1,697.00	✓ 135760
2	FIXING PARTS FOR REAR BUMPER <i>new</i>	\$ 166.00	x
3	ADAPTER WHEEL HOUSING LINER - RH <i>new</i>	\$ 32.00	x
4	GUIDE SECTION - LH/RH <i>new</i>	2 \$ 28.00	x
5	LOCKING MECHANISM <i>new</i>	2 \$ 50.00	x
6	REAR BUMPER SPOILER <i>new</i>	\$ 206.00	✓ 16440
7	REAR LIGHT REFLECTOR - RH <i>new</i>	\$ 35.00	x
8	SENSOR - REAR INNER/OUTER <i>new</i>	2 \$ 421.00	x
9	SEAL RING - REVERSE SENSOR <i>new</i>	4 \$ 14.00	x
10	REINFORCEMENT BEAM <i>new</i>	\$ 501.00	?
11	BRACKET - LH <i>new</i>	\$ 23.00	x
12	BRACKET - RH <i>new</i>	\$ 24.00	x
13	GUIDE SECTION - RH <i>new</i>	\$ 57.00	x
14	SUNDRIES <i>new</i>	\$ 300.00	? 2776
TOTAL SPARE PARTS		: \$ 3,554.00	
TOTAL LABOUR CHARGES		: \$ 2,172.00	
GRAND TOTAL		: \$ 5,726.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Hong

Surveyed Date

:

29/08/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Authorised Repairs, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0987/2018/PH
Date : 29-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days - ok - jb - 2 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Zhang Zhong Qing
Address : Blk 260A Ang Mo Kio St 21
: # 14-145
Singapore 561260
Telephone : HP +65 81809817
Type of Claim : Own Damage Claim
Policy No. : 1800098317
Vehicle No : **SMD 3570 B**
Model Code : AUDI A3 1.0 TFSI
Model / Year : Aug-18
Engine No : CHZ 938207
Chassis No : WAUZZZ8V8J1066029
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Aug-18
Place of Accident : Blk 260 St 21 Ang Mo Kio carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 3570 B .

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer rear parking aid.Check function.	S/N \$ 280.00	\$ 280.00
2	To dismantle and renew rear bumper assy.Inspect rear panels for damage .Re-organise rear crash management components.Reinstall all parts removed.	\$ 900.00	\$ 500.00
3	To respray rear bumper.	\$ 800.00	\$ 550.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,172.00	\$ 1,522.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 3570 B .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,697.00	\$ 1,357.60
2	FIXING PARTS FOR REAR BUMPER	\$ 166.00	
3	ADAPTER WHEEL HOUSING LINER - RH	\$ 32.00	
4	GUIDE SECTION - LH/RH	2 \$ 28.00	
5	LOCKING MECHANISM	2 \$ 50.00	
6	REAR BUMPER SPOILER	\$ 206.00	\$ 164.40
7	REAR LIGHT REFLECTOR - RH	\$ 35.00	
8	SENSOR - REAR INNER/OUTER	2 \$ 421.00	
9	SEAL RING - REVERSE SENSOR	4 \$ 14.00	
10	REINFORCEMENT BEAM	\$ 501.00	
11	BRACKET - LH	\$ 23.00	
12	BRACKET - RH	\$ 24.00	
13	GUIDE SECTION - RH	\$ 57.00	
14	SUNDRIES	\$ 300.00	\$ 27.76
TOTAL SPARE PARTS		\$ 3,554.00	\$ 1,549.76
TOTAL LABOUR CHARGES		\$ 2,172.00	\$ 1,522.00
GRAND TOTAL		\$ 5,726.00	\$ 3,071.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMD 3570 B

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PAOD/0987/2018/MAS

1 April 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SMD 3570 B, Audi A3 Sedan 1.0 S-Tro TFSI

With reference to the above-mentioned vehicle, no. **SMD 3570 B**, claimant, **Ms. Zhang Zhongqing**, please find the related document per attached.

1. A copy of the Original invoice no. 85013624 – S\$2,644.78
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SMD 3570 B

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Aug 2018		30 Aug 2018 08:27 Edit Adj Rpt	S\$3,071.76 Edit Estimates	S\$3,071.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ZHANG ZHONG QING, ID: S7465542D, Tel: +6581809817, Email: zhangzq222@icloud.com								
Vehicle Reg. No.:	SMD3570B	Date of Loss:	24/08/2018 16:00 - :59 [9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4074209158SG	Policy/Cover Note No.:	1800098317 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UB1) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/09/2018]								
Driver/Custodian:	ZHANG ZHONG QING (44 / Female), NRIC: S7465542D, Tel: +6581809817 Email: zhangzq222@icloud.com								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (30/08/2018): SMD3570B / OD / 24/08/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD3570B (4074209158SG)
OD
Aug 24 2018 4:50PM
[ZHANG ZHONG QING]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer	
Photos/Images														3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	21/03/19 17:30	General View										1	Load JPG	☒		
2	21/03/19 17:30	General View										1	Load JPG	☒		
3	21/03/19 17:30	General View										1	Load JPG	☒		
4	21/03/19 17:30	General View										1	Load JPG	☒		
5	21/03/19 17:30	General View										1	Load JPG	☒		
6	21/03/19 17:30	General View										1	Load JPG	☒		
7	21/03/19 17:30	General View										1	Load JPG	☒		
Documentation														1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	30/08/18 15:56	Certificate of Insurance										1	Load PDF			
2	30/08/18 15:56	Driver's Driving License										1	Load PDF			
3	30/08/18 15:56	ESTIMATE										1	Load PDF			
4	30/08/18 15:56	Singapore Accident Statement										1	Load PDF			
5	10/04/19 09:54	WORKSHOP INVOICE										1	Load PDF			
6	10/04/19 09:54	DISCHARGE VOUCHER										1	Load PDF			

Linked Accident Report Documents

			View	Use Viewer	
Assessment Reports			1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	25/08/18 09:27	Accident Statement	1	Load HTM	
Photos/Images			3 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	25/08/18 09:23	Accident Photo	1	Load JPG	☒
2	25/08/18 09:23	Accident Photo	1	Load JPG	☒
3	25/08/18 09:23	Accident Photo	1	Load JPG	☒
4	25/08/18 09:23	Accident Photo	1	Load JPG	☒
5	25/08/18 09:23	Accident Photo	1	Load JPG	☒
6	25/08/18 09:23	Accident Photo	1	Load JPG	☒
7	25/08/18 09:23	Accident Photo	1	Load JPG	☒
8	25/08/18 09:23	Accident Photo	1	Load JPG	☒
9	25/08/18 09:23	Accident Photo	1	Load JPG	☒
10	25/08/18 09:23	Accident Photo	1	Load JPG	☒
11	25/08/18 09:23	Accident Photo	1	Load JPG	☒
12	25/08/18 09:23	Accident Photo	1	Load JPG	☒
13	25/08/18 09:23	Accident Photo	1	Load JPG	☒
14	25/08/18 09:23	Accident Photo	1	Load JPG	☒
15	25/08/18 09:23	Accident Photo	1	Load JPG	☒
16	25/08/18 09:23	Accident Photo	1	Load JPG	☒
Documentation			1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	25/08/18 09:16	Sketch Plan	1	Load JPG	☒
2	25/08/18 09:16	Sketch Plan #2	1	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18015815/ATD3N2

Date: 10/04/2019

REFERENCE

Insured/Claimant: ZHANG ZHONG QING Policy No: 1800098317
Date of Loss: 24/08/2018 Nature of Claim: OD Claim No: 4074209158SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD3570B
Make & Model: AUDI A3, 999cc TFSI S-TRONIC (A) Engine No: CHZ938207
Reg. Date: 15/08/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V8J1066029
Colour: White Odometer: 64 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$125,000.00
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,554.00	1,549.76	2,004.24	56.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,172.00	1,522.00	650.00	29.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,726.00	3,071.76	2,654.24	46.35
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	5,126.00	2,471.76	2,654.24	51.78
+ GST 7.00/7.00% (\$\$)	358.82	173.02	185.80	51.78
Nett Amount (\$\$)	5,484.82	2,644.78	2,840.04	51.78

INSPECTION

Date of Assignment: 30/08/2018
Date Inspected: 29/08/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,697.00 FS	*1,357.60 FS
2	1		*FIXING PARTS FOR REAR BUMPER	Not Necessary	166.00 FS	*- FS
3	1		*ADAPTER WHEEL HOUSING LINER-RH	Not Necessary	32.00 FS	*- FS
4	2		*GUIDE SECTION -LH/RH	Not Necessary	28.00 FS	*- FS
5	2		*LOCKING MECHANISM	Not Necessary	50.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Bent	206.00 FS	*164.40 FS
7	1		*REAR LIGHT REFLECTOR -RH	Not Necessary	35.00 FS	*- FS
8	2		*SENSOR-REAR INNER/OUTER	Not Necessary	421.00 FS	*- FS
9	4		*SEAL RING-REVERSE SENSOR	Not Necessary	14.00 FS	*- FS
10	1		*REINFORCEMENT BEAM	Not Necessary	501.00 FS	*- FS
11	1		*BRACKET-LH	Not Necessary	23.00 FS	*- FS
12	1		*BRACKET-RH	Not Necessary	24.00 FS	*- FS
13	1		*GUIDE SECTION -RH	Not Necessary	57.00 FS	*- FS
14	1		*SUNDRIES	Necessary	300.00 FS	*27.76 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,554.00	1,549.76
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY .INSPECT REAR PANELS FOR DAMAGE .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	900.00	500.00
3	TO RESPRAY REAR BUMPER	New	800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,172.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >