

(08/11/13)

Driver: KalvinREF: NS/INC180158 23/Klqd3n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop no/s _____

of _____

Insured: FBI 2711SPolicy No. 5067163441-03 (2/8/17-20/8/18)Claims No. NS/1008115-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 35662 Yr Regn: 8 Dec 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/Tr / Prime Mover /

Truck / Trailer or

Make: Hyundai 240 c.c. 1685Colour: Blue A/C: Ins Std / NI / NASp. Reading: 178512 T/Radio: Ins Std / NI / NA

Eng/No: _____

No: KMH LB414MH 4096735Gen. Cond: Good / Pr / Poor / BurntSteering: Ins / Jammed / Leaked / Burnt orBrake: Ins / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / Rim orTyre Size: F: 205/60R16R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front: _____ Rear: _____

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 20/8/18 D.O.I. 29/8/18Survey held at (DHE (Loyang))

Des. of Damages: Frt / Rear / O/S / N/S / W/C / Rooftop or

as R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SHD 35662 - X</u>
	<u>FBI 2711S - 03 / FCI 18015454 / R124d3 DOA: 20/8/18 P/P</u>
<u>30/8/18</u>	<u>Endred P/P \$3030.12 / 2Vg. (Ref 83183.76, 51%)</u>
	<u>RECEIVED 31 AUG 2018</u>

Date/Time, File Pass to?

☐ : Prel. Report1/3/18 Amir☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 3030.12

160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18015823/K1qd3

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 30-08-2018



189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBJ 2711S	Veh. Inspected	SHD 3566Z
Policy No.	5067163441-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/08/2018	Inspection Date	29/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="20/08/2018 11:08"/>
Vehicle No.(For Motor)	<input type="text" value="FBJ2711S"/>	Certificate Number	<input type="text"/>
<input type="button" value="Search"/>			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5067163441-03		SALEHUDIN BIN SULAIMAN	S78046271	GMC	Third Party, Fire & Theft	FBJ2711S	FBJ2711S	21/08/2017	20/08/2018

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1009117-002	CITYCAB PTE LTD	SHB 3522K	FBD 6962P	25/08/2018	\$ 8,764.46	\$ 3,600.00
2	MT/1009537-002	COMFORT TRANSPORTATION PTE LTD	SHC 8512B	SJZ 7050D	26/08/2018	\$ 1,570.48	\$ 550.00
3	MT/1009539-001	COMFORT TRANSPORTATION PTE LTD	SHD 4312H	FY 5397U	29/08/2018	\$ 2,536.82	\$ 1,250.00
4	MT/1009542-001	COMFORT TRANSPORTATION PTE LTD	SHA 2422C	YM 6553S	28/08/2018	\$ 4,277.40	\$ 2,100.00
5	MT/1009545-001	COMFORT TRANSPORTATION PTE LTD	SH 7662B	SJZ 7836D	17/08/2018	\$ 4,676.44	\$ 2,400.00
6	MT/1008115-002	COMFORT TRANSPORTATION PTE LTD	SHD 3566Z	FBJ 2711S	20/08/2018	\$ 6,213.88	\$ 3,030.12
7	MT/1007488-003	CITYCAB PTE LTD	SHB 3363C	SJR 9003U	16/8/2018	\$ 1,320.48	\$ 800.00

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/08/2018 16:24
Date Of Accident	20/08/2018 21:15
Exact Location Of Accident	CHANGI NORTH RISE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3566Z
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	ONG THIAN KWEE
NRIC No	S1291182C
Date Of Birth	24/12/1958
Occupation	OUTDOOR
Date Of Driving Pass	12/07/1977
Driving Experience	41 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90023003
Fax Number	
Contact Number	
Email Address	CHRISONG.SIN@GMAIL.COM

Address	137 #05-2014 MARSILING ROAD
Postcode	730137
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	WOODLANDS W NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ2711S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	SALEHUDIN BIN SULAIMAN
NRIC/Passport Number	S7804627I
Contact Number	91698447
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NOT SURE
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	SALEHUDIN BIN SULAIMAN
------	------------------------

Approximate Age

Injuries Sustain

LEG

Injured person in which vehicle?

FBJ2711S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?


YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report - T/20180821/2006

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG NO 199003821R

Policyholder's Signature

Date & Time

Driver's Signature

Date & Time

Reporting Centre Personnel's Signature

Date & Time

[Signature]
21/8/18

Sketch Plan Pg. 2



**SINGAPORE
POLICE FORCE**



T/20180821/2006

1 of 3

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

Report No. T/20180821/2006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/08/2018 01:06		Vide Report No.: G/20180820/0217		Station Diary No.: 16	
Informant's Particulars					
Name of Informant: ONG THIAN KWEE			Address: APT BLK 137 MARSILING ROAD #05-2014 SINGAPORE 730137		
ID Type / ID No.: NRIC NO / S1291182C			Contact No.: Home/Office:		Mobile: 90023003
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 59	Date of Birth: 24/12/1958	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3,4A,4		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/08/2018 21:15	Type of Location: Straight Road
Location: Along Road 1 CHANGI NORTH RISE OUTSIDE 28 CHANGI NORTH RISE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ2711S	Motorcycle	HONDA	NC750X	White	No Damage	0
SHD3566Z	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	No Damage	0

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20180821/2006

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

2 of 3

Report No. T/20180821/2006

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	SALEHUDIN BIN SULAIMAN	ID No.	S7804627!
Related Vehicle	FBJ2711S (Motorcycle)	Contact No.	91698447
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	ONG THIAN KWEE	ID No.	S1291182C
Related Vehicle	SHD3566Z (Car)	Contact No.	90023003
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4A,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/08/2018 at about 2118hrs, I was driving my Comfort Delgro taxi SHD3566Z along Changi North Rise towards the direction of Changi North Street 1. I was looking for unit number 28 to pick up a passenger. As I drove along slowly at about 20-30km/h, I passed unit 26 on my right. At the time, there were no vehicles around and behind me. I continued to move forward slowly and saw unit 28 on my right. I was about to make a right turn into the company when I heard a motorcycle sound on my right side braking. I suddenly saw a motorcycle on my right side window, and saw it dropping on the floor.

I immediately alighted to assist the rider. His leg was stuck underneath his own motorcycle. Together with the help of 2 security guard from nearby, we manage to lift up the bike to free him. The motorcycle had hit into my rear right passenger door, causing just some scratches. I think the motorcycle managed to stop just in time, if not my door will be dented. I then called for the police and ambulance to scene. We left our vehicles in the same position until the police came. Subsequently the police and ambulance came. The police interviewed both of us and also took away my in-vehicle camera SD card.



**SINGAPORE
POLICE FORCE**



T/20180821/2006

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

3 of 3

Report No. T/20180821/2006



CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 3 MUHAMMAD AFIF BIN MOHD ROSDI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 21/08/2018 01:06
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMED SUFIAN BIN SUDIN Contact No.: 65476367	Classification Of Case:
Authentication Stamp NP168 	





COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD3566Z

DATE: 29. Aug. 2018

MAKE : HYUNDAI

MODEL : i40

DOA: 20. Aug. 2018

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Door (RH) <i>AK</i>			\$2,256.40
1	Rear Door (RH) <i>X 1/2</i>			\$2,201.10
1	Rear Bumper <i>X 1/2</i>			\$603.60
SUB TOTAL				\$5,061.10
LESS 20%				\$1,012.22
DISCOUNTED TOTAL				\$4,048.88
1	RHF Comfort Logo <i>AK</i>			\$75.00
1	RHR APP sticker <i>AK</i>			\$80.00
				Nett
				Nett
				\$155.00
Labour Charge				
1	Panel Beating			\$800.00 <i>400</i>
1	Spray Painting Charge			\$750.00 <i>600</i>
1	Tuff Kote			\$50.00 <i>20</i>
1	Wiring Charge			\$50.00 <i>X 1/2</i>
2	Transfer of Door			\$360.00 <i>50</i>
				\$180.00
TOTAL LABOUR				\$2,010.00
ESTIMATE TOTAL				\$6,213.88
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary demand must be resurveyed and is subject to final approval from Insurance Company

Signature: _____

ESTIMATE TOTAL

Kai Lin LKK

29/8/18

Before Part p.L.

Larry Ng

Date/Time: 28.08.2018 12:16

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305205390

CUSTOMER

COMPANY: COMFORT TRANSPORTATION PTE LTD

7/MS: 7010045

CUSTOMER NO.: 383 SIN MING DRIVE
ADDRESS: Singapore SINGAPORE 575717

65508755 (O)

L (R)

(P)

SCOUNT CARD NO.

REGN NO.:

SHD3566Z

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

28.08.2018 09:25

YR OF MANU

08.12.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMHU096735

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 20.08.2018

NATURE: 3P 20.08.2018


S/NO

LABOR CODE

DESCRIPTION

FRONT

NTUC - Right Centre
LKE/Kahn -



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD3566Z LARRY

Vehicle No.: SHD3566Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.08.2018

REPAIR ESTIMATE

Time: 18:15:29

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305205390
REGN NO : SHD3566Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.12.2016
DATE/TIME IN : 28.08.2018 09:25
ACCIDENT DATE : 20.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0592-G	140VC PANEL ASSY-FR DR RH	1	2,256.40	20.00	1,805.12
0002 28-01-0103-0003-A	(140)FRT DOOR LOGO SONATA	1	75.00		75.00
0003 28-01-0103-2013-A	140V3 APP LOGO REAR DOOR	1	80.00		80.00

SUB-TOTAL : 1,960.12

JOB NATURE

0000 L	PANEL BEATING	400.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0003 L	TRANSFER OF DOOR	50.00

SUB-TOTAL : 1,070.00

TOTAL : 3,030.12

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO

COMFORTDELGRO ENGINEERING

Our Job Ref No. : 305205390
Date : 30. Aug. 2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD3566Z

Date of Accident: 20. Aug. 2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC FBJ2711S
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$1,960.12
(b) Labour Charges	\$1,070.00
Total for Part-By-Part Repair Cost	\$3,030.12
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less:	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : K. G. Loh

Date : 30/8/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18015823/K1qd3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 07-09-2018	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBJ 2711S	Veh. Inspected	SHD 3566Z	
Policy No.	5067163441-03	Coverage (\$)	0.00	
Claim No.	MT/1008115-002	Excess (\$)	0.00	
Assign From		Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMHU096735	Colour	BLUE	
Odometer	178512	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	MAXXIS	7 mm	
L/H Front Tyre	205/60 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/60 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/60 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2018	Inspection Date	29/08/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3566Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR (RH)	DENTED	2,256.40	2,256.40
1	REAR DOOR (RH)	TO REPAIR SEE LABOUR	2,201.10	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	603.60	-
	LESS 20% DISCOUNT		-1,012.22	-451.28
			4,048.88	1,805.12
<u>SPECIAL NETT ITEMS</u>				
1	RHF COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	RHR APP STICKER (SN)	NECESSARY	80.00	80.00
			155.00	155.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR (RH) AND REAR BUMPER.		800.00	400.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	TUFF KOTE.		50.00	20.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TRANSFER OF DOOR.		360.00	50.00
			2,010.00	1,070.00
GRAND TOTAL			6,213.88	3,030.12
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,030.12

Report Ref No. NS/INC18015823/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.