

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9569L**AAD1808-228***Not Notarized
11 Sept @ 1250/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9569L

KL1LA69RJBB121994

CHEVROLET

EPICA 2.0

27.8.2018

AIG

PART			LIST	
1	1	Front Door RH	\$	B 1,133.00 ✓
2	1	Front Door Glass Guide RH Chrome Moulding	\$	SL 60.00
3	1	Front Door Outer Moulding	\$	SL 220.00
4	1	Front Door Outer Handle	\$	SL 125.00
5	1	Front Door Handle Support	\$	SL 3.00
6	1	Front Door outer handle inner seal	\$	SL 89.15
7	1	Front Door outer key lock	\$	N 25.00
8	1	Front Door Hinge Upper	\$	N 65.00
9	1	Front Door Hinge Lower	\$	N 65.00
10	1	Front Door inner lock	\$	N 586.00
11	1	Front Door Inner Lock Latch RH	\$	SL 206.00
12	1	Front Door Check / Arrestor	\$	SL 67.50
13	1	Front Door Weatherstrip RH	\$	SL 138.79
14	1	Front Door glass channel weatherstrip	\$	SL 160.00
15	1	Front Door inner trim board	\$	SL 455.69
16	1	Front Door window glass	\$	SL 456.12
17	1	Front Door Power Window Motor (Master) RH	\$	SL 284.97
18	1	Front Door power window motor switch	\$	SL 145.00
19	1	Front Door Window Regulator Gear RH	\$	N 84.58
20	1	Front Door Outer Pillar Panel RH	\$	N 715.00
21	1	Front Door Pillar Inner Panel RH	\$	N 850.00
22	1	Front Door Center Pillar Panel RH	\$	N 698.15
23	1	Front Side View Mirror Assy RH	\$	SL 1,191.00
24	1	Rear Door RH (Panel A-RR DR LH)	\$	N 1,133.00

TOTAL	\$	8,956.95
10%	\$	895.70
	\$	8,061.26

Trans-cab Auto Services Pte Ltd

AAD1808-228

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9569L

Special Nett

1	Front door sticker 'Trans-cab'	\$	<i>na</i> 80.00 <i>60.00</i>
1	Rear door sticker '6555-3333'	\$	<i>na</i> 80.00 X

TOTAL	\$	783.30
--------------	-----------	---------------

TOTAL PARTS	\$	16,917.10
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
---	----	-------------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>2000</i> 3,000.00
---	----	----------------------

Putty and spray painting of the affected portion.	\$	<i>2000</i> 3,000.00
---	----	----------------------

To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
---	----	--------------------

To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 X
--	----	--------------------

To rust-proofing of the affected areas.	\$	170.00 <i>300</i>
---	----	-------------------

To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>600</i>
--	----	-------------------

TOTAL	\$	6,900.00
--------------	-----------	-----------------

Over All Total	\$	25,577.10
-----------------------	-----------	------------------

Repair Days (Lump Sum)*10 DAYS*
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: