

29th Aug 2018

Quotation No.: Q18-OPS-0850

AXA Insurance Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Dear Sir/Mdm

Estimated Cost of Repair job for SBS6505Y (Accident on 23/08/18, along Pasir Ris Green x Pasir Ris Dr 8 involving SBS6505Y & YP8514B)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labour to remove glass debit & install new side glass on rear LHS last panel	3 day	\$880.00	\$2,640.00 1760
2	Supply skilled painter & paint material to repair, putty, grinding & spraypaint rear LHS dome	2 day	\$880.00	\$1,760.00 1320
3	Supply skilled painter & paint material to repair, putty, grinding & spraypaint rear LHS engine panel	2 day	\$880.00	\$1,760.00 880
4	Supply skilled electrician to reinstall & relaying CCTV camera (round)	1 day	\$880.00	\$880.00
5	Rear LHS glass panel	1 pc	\$2330.12	\$2330.12
6	CCTV Camera Round	1 pc	\$900.00	\$900.00
Sub-total				\$10,270.12
GST				\$718.90
Total				\$10,989.02

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Lead Time : 8 Working day
Price quoted subject to 7% GST

Yours faithfully


Tien Yong Shun
Operation Executive

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalirick
30/8/18 1015 hrs.
4 Pys.
4/5
After Repair

LexBuild International Pte. Ltd.
2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.
Tel: (65) 6456 3533, Fax: (65) 6456 3353
Website: www.LexBuild.com, Email: sales@LexBuild.com


bizSAFE
S.T. 401 R
ROC / CR GST Reg. No. 200004370R