

INS. CASE OWNER:

CC 4, LPO 180 15851, K 30312

LKK:

IDAC:

SURVIVOR

Kenneth

DOI:

ASSIGNMENT

30/8/18

Date / Time:

29/8/18

Registered in Merimen:

Pre-assign / CCU / FTE

SKW 6322E



Insured Vehicle No.:

Name of Insured:

DU XIAN PENG

Insured Tel No.:

HP:

98800698

Excess Sec II :SS

D.O.A.:

29/8/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

13/18/18/VPO51020834

Policy No.:

217VPO5052125

Make / Model:

7 HARPER

Place of Accident:

TPE 7 LOYANG

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKC5874R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Alan's
United

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

Date/ Time	STAGE	DATE / PIC
4/9	Non-Reporting ltr (1st):	
2/9	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
22-08-19	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time: 2/9	Sent By: [Signature]
--------------------	----------------	----------------------

FINALIZATION	Date/Time:	Confirm with:	Confirm by: KSC
--------------	------------	---------------	-----------------

Repair Cost:	4x SS 4,900	(5 days) Reduction:	41 %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
--------------	-------------	-----------------------	------	---

FINAL SETTLEMENT	Date/Time: 02.10.19	Confirm with: ALAN	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
------------------	---------------------	--------------------	---

Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27	If NO or B 28, Ass. Lia:
------------------	-------	-----------------------------------	----	--------------------------

Repair Cost:	w/lost SS 5,243.00	01 REAR ENDED TP	
--------------	--------------------	------------------	--

Loss of Rental (LOR):	SS 800.00	(8 days) > *100	
-----------------------	-----------	-------------------	--

Loss of Use (LOU):	SS -	(\$ x days)	
--------------------	------	---------------	--

Loss of Income (LOI):	SS -	(\$ x days)	
-----------------------	------	---------------	--

LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
--	---	--	--

GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 6,045.00	Global Sum SS:	

FINAL PAYMENT	Date/Time: 02-10-19	Confirm with: KENNY	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
---------------	---------------------	---------------------	---

Payee 1:	SS 6,045.00	Name 1: ALAN'S UNITED AUTO PTE. LTD.	
Payee 2: (Strike if N.A.)	SS -	Name 2:	
Payee 3: (Strike if N.A.)	SS -	Name 3:	

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: *150

(08/11/13) WOI

ASS. REC. BY:

REF:

LPC

ASSIGNMENT

From:

Date:

30/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKC 5874R

at Workshop m/s

Alan's United

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LPC

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKC 5874R

Yr Regn:

09 11

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Clario

C.C

1591

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

141650

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH1DH 41CMC U 248521

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

J

mm

R/Bal.

J

mm

L/Bal.

J

mm

L/Bal.

J

mm

D.O.A.

29/8/18

D.O.I.

30/8/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/8

File pass to Graham Nivitt

1/5 = 4.900 (RED = 3,448.56 41%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/LPC18015851/Kua3

Date: 03.09.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKC 5874R

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 30.08.2018 at the premises of M/s Alan's United Auto Pte Ltd - Sin Ming have the following to report:-

Workshop Estimate Amount	: S\$	8,348.56
Revised Estimate Amount	: S\$	5,546.08
"Check" Items Amount	: S\$	951.84
Total (Including Check Items)	: S\$	6,497.92

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

QBE Insurance (Singapore) Pte Ltd

A member of the worldwide QBE Insurance Group - Unique Entity No. 198401363C

1 Raffles Quay, #29-10 South Tower, Singapore 048583
Tel: 65-6224 6633 Fax: 65-6533 3270
GST Registration No.: M200644018
www.qbe.com.sg

**Certificate of Insurance**

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULE, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No. **8-V0017266-MVA**Account Name **I INSURANCE SG AGENCY**MCI Type **MX1**1 Index Mark and Registration Number of Vehicle or Chassis No: **SKC5874R**2 Name of Policyholder **PETER ONG**3 Effective date of Commencement of Insurance for the purpose of the Regulations **13/03/2018**4 Date of Expiry **12/03/2019**

5 Person or Classes of Person entitled to drive*

(a) The Policyholder

The Policyholder may also drive a motor car not belonging to him/her and not hired to him/her under a hire purchase agreement.

(b) Any person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from the driving the Motor Vehicle

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage

6 Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

7 Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risk and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia) are not to be included under these headings

I/WE HEREBY CERTIFY that the Policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Hire Purchase : **SING INVESTMENTS & FINANCE LIMITED**

QBE Insurance (Singapore) Pte Ltd

Date of Issue: **22/02/2018**
Authorized Signature

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05842

Vehicle Insured : SKW6322E

Accident Date : 29-Aug-2018

Date : 29-Aug-2018

Our Ref : 218148 (LONPAC) / CHAN

PAGE : 1

PETER ONG
BLK 167B PUNGGOL EAST
#06-401
Singapore 822167

*Not Authorized
1/1 up 8?
Resurvey After Paint
5 days*

ESTIMATED COST OF REPAIR FOR HYUNDAI ELANTRA 1.6A SKC5874R

1 pc	Boot lid		R 1,197.50	✓
1 pc	Boot lid rubber		DIS 86.40	50Wm
1 pc	Boot lid inner lock		RM 161.10	✓
1 pc	Boot lid inner trim		CM 183.50	✓
2 pcs	Boot lid hinge	@ S\$117.20	R 234.40	x
1 pc	Boot lid logo		RM 37.20	✓
1 pc	Boot lid "HYUNDAI" emblem		RM 49.20	✓
1 pc	Boot lid "ELANTRA" emblem		RM 52.80	✓
2 pcs	Boot lid lamp	mgcm @ S\$325.80	651.60	✓
2 pcs	Boot lid license plate lamp	@ S\$ 39.70	79.40	4
1 pc	Boot lid open sensor		115.20	7✓
2 pcs	Taillamp	mgcm @ S\$402.60	805.20	✓
2 pcs	Taillamp corner panel	@ S\$197.80	395.60	x sk
1 pc	Rear end panel		R 422.90	✓
1 pc	End panel top garnish		DIS 81.80	✓
1 pc	Rear floor panel		R 881.80	x
1 pc	Rear bumper fascia		R 480.30	✓
2 pcs	Rear bumper side retainer	@ S\$ 32.90	DIS 65.80	✓
1 pc	Rear bumper reinforcement		336.80	✓
2 pcs	Bumper reinforcement bracket	@ S\$ 72.30	144.60	✓
2 pcs	Reinforcement top bracket	@ S\$ 26.10	52.20	✓
3 pcs	Reinforcement lower bracket	@ S\$ 24.80	74.40	✓
2 pcs	Rear bumper reflector	@ S\$ 35.50	71.00	✓
			6,660.70	
Less 20% :			1,332.14	

5,328.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKW6322E

Page : 2

1 pc Rear bumper reverse sensor(set)
1 pc Rear reverse camera

200sn
NU 300.00 sn
shan 300.00 sn ✓

To remove roof lining, front and rear seats, trim board and carpet

120.00 *601*

To apply undersealing

100.00 *601*

To putty and spray replaced parts

1,000.00 *800*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

700
1,200.00

Total : S\$ 8,348.56

Singapore Dollars Eight Thousand Three Hundred and Forty Eight and Cents Fifty Six Only

LKK Auto Consultants to certify
the Repairer of the work done:

- To resurvey before painting and polishing
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items and parts are surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 29 August, 2018 3:19 PM
To: Catherine Chong (LKK Auto)
Cc: MT_Claim_SG
Subject: FW: ATTACHED SKC5874R REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRI SURVEY
Attachments: SKM_284e18082915120.pdf

Dear Catherine,

For your necessary action.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

29.08.2018 3:22pm
Kenny veh in
Kenny
30/08/2018

From: kennychan@alanutd.com [mailto:kennychan@alanutd.com]
Sent: Wednesday, 29 August, 2018 3:11 PM
To: GERALD POH WEE BIN
Subject: RE: ATTACHED SKC5874R REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRI SURVEY

Dear Gerald

Enclosed ticked surveyor name for the arrangement of conduct pre repair survey ,thank you .

Regards
Kenny
Alan's United Auto pte Ltd
64538686

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Wednesday, August 29, 2018 2:24 PM
To: kennychan@alanutd.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: ATTACHED SKC5874R REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRI SURVEY

WITHOUT PREJUDICE

Dear Kenny,

Attached list of surveyors for your necessary action.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: kennychan@alanutd.com [mailto:kennychan@alanutd.com]

Sent: Wednesday, 29 August, 2018 1:39 PM

To: GERALD POH WEE BIN

Subject: ATTACHED SKC5874R REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRI SURVEY

Dear Gerald

Attached our client vehicle SKC5874R repair estimate ,GIA report to request joint expert survey list for us to choose surveyor to conduct pre survey for t. p. claim your insured vehicle SKW6322E accident on 29-08-2018 thank you .

Regards

Kenny

Alan's United Auto Pte Ltd

64538686

Mei Kwan (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 3 September, 2018 12:10 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO); Admin A
Subject: Our Ref: 17/18/18/VP05/020864 RE: ATTACHED SKC5874R REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRI SURVEY
Attachments: SKW6322E 290818.PDF
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan/Thin Thin

Attached is our Insured's GIA report for your handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 3 September, 2018 11:23 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO); Admin A
Subject: RE: ATTACHED SKC5874R REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRI SURVEY

WITHOUT PREJUDICE

LPC ref: TBA
LKK REF: CC4/LPC18015851/Kua3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SKC 5874R

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- TP GIA report
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Enclosed ticked surveyor name for the arrangement of conduct pre repair survey ,thank you .

Regards
Kenny
Alan's United Auto pte Ltd
64538686

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: Wednesday, August 29, 2018 2:24 PM
To: kennychan@alanutd.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: ATTACHED SKC5874R REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRI SURVEY

WITHOUT PREJUDICE

Dear Kenny,

Attached list of surveyors for your necessary action.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: kennychan@alanutd.com [<mailto:kennychan@alanutd.com>]
Sent: Wednesday, 29 August, 2018 1:39 PM
To: GERALD POH WEE BIN
Subject: ATTACHED SKC5874R REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRI SURVEY

Dear Gerald

Attached our client vehicle SKC5874R repair estimate ,GIA report to request joint expert survey list for us to choose surveyor to conduct pre survey for t. p. claim your insured vehicle SKW6322E accident on 29-08-2018 thank you .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18015851/Kea3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 25-10-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 6322E	Veh. Inspected	SKC 5874R	
Policy No.	Z17VP05052125	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020864	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHDH41CMCU248521	Colour	METALLIC GREY	
Odometer	141650	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	8 mm	
L/H Front Tyre	205/55 R16	PIRELLI	8 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	8 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2018	Inspection Date	30/08/2018	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 5874R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	BENT	1,197.50	1,197.50
1	BOOT LID INNER LOCK	DENTED	161.10	161.10
1	BOOT LID INNER TRIM	CRACKED	183.50	183.50
2	BOOT LID HINGE @\$117.20	TO REPAIR SEE LABOUR	234.40	-
1	BOOT LID LOGO	NECESSARY	37.20	37.20
1	BOOT LID 'HYUNDAI' EMBLEM	NECESSARY	49.20	49.20
1	BOOT LID 'ELANTRA' EMBLEM	NECESSARY	52.80	52.80
2	BOOT LID LAMP @\$325.80	CRACKED	651.60	651.60
2	BOOT LID LICENSE PLATE LAMP @\$39.70	N/S CRACKED	79.40	39.70
1	BOOT LID OPEN SENSOR	CUT	115.20	115.20
2	TAILLAMP @\$402.60	MTG CRACKED	805.20	805.20
2	TAILLAMP CORNER PANEL @\$197.80	SERVICEABLE	395.60	-
1	REAR END PANEL	BENT	422.90	422.90
1	END PANEL TOP GARNISH	DISTORTED	81.80	81.80
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	881.80	-
1	REAR BUMPER FASCIA	BENT	480.30	480.30
2	REAR BUMPER SIDE RETAINER @\$32.90	DISTORTED	65.80	65.80
1	REAR BUMPER REINFORCEMENT	BENT	336.80	336.80
2	BUMPER REINFORCEMENT BRACKET @\$72.30	BENT	144.60	144.60
2	REINFORCEMENT TOP BRACKET @\$26.10	NOT NECESSARY	52.20	-
3	REINFORCEMENT LOWER BRACKET @\$24.80	NECESSARY	74.40	74.40
2	REAR BUMPER REFLECTOR @\$35.50	NECESSARY	71.00	71.00
	LESS 20% DISCOUNT		-1,314.86	-994.12
			5,259.44	3,976.48
1	BOOT LID RUBBER (50%) (SN)	DISTORTED / DENTED	86.40	43.20
	LESS 20% DISCOUNT		-17.28	-
			69.12	43.20

Report Ref No. CC4/LPC18015851/Kea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	DENTED	300.00	200.00
1	REAR REVERSE CAMERA (SN)	SHORTED	300.00	300.00
			600.00	500.00
	LABOUR			
	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET.		120.00	60.00
	TO APPLY UNDERSEALING.		100.00	60.00
	TO PUTTY AND SPRAY REPLACED PARTS.		1,000.00	800.00
	TO REMOVE,CUT -OUT DAMAGED PARTS ,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF BOOT LID HINGE AND REAR FLOOR PANEL.		1,200.00	700.00
			2,420.00	1,620.00
	GRAND TOTAL		8,348.56	6,139.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,900.00

Report Ref No. CC4/LPC18015851/Kea3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.