

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD1803-233***Not Authorized
C/Sing @ 9950ph*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 724T

VF1ABL15AUC281169

RENAULT

LATITUDE

28.8.2018

AXA**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bulvert</i>	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>DIT</i>	181.75	✓
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i>	394.68	X
4	1	BUMPER RETAINER FRT LH	\$	<i>DIT</i>	151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i>	123.88	X
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i>	150.77	X
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i>	123.88	X
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i>	472.83	X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i>	266.80	X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i>	207.21	✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i>	207.21	X
12	1	BUMPER BEAM FRT	\$	<i>SL</i>	914.08	X
13	1	TOW COVER FRT	\$	<i>SL</i>	28.61	X
14	1	RADIATOR GRILLE	\$	<i>mgm</i>	1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>na</i>	225.36	✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i>	1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i>	615.90	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>K</i>	89.79	X
19	1	FRONT BRACE PANEL	\$	<i>K</i>	177.22	X
20	1	HORN	\$	<i>SL</i>	314.17	X
21	1	HORN BRACKET	\$	<i>K</i>	40.45	X
22	1	HEADLAMP LH	\$	<i>Bar</i>	1,184.43	✓
23	1	HEADLAMP RH	\$	<i>mgm</i>	1,184.43	✓
24	1	HEADLAMP PANEL FRT LH	\$	<i>SL</i>	152.15	✓
25	1	HEADLAMP PANEL FRT RH	\$	<i>K</i>	152.15	X
26	1	BONNET	\$	<i>SL</i>	1,941.63	✓
27	1	BONNET INSULATOR	\$	<i>SL</i>	405.73	X
28	1	BONNET STRUT LH	\$	<i>SL</i>	88.61	X

Trans-cab Auto Services Pte Ltd**AAD1803-233**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T

29	1	BONNET STRUT RH	\$	S ₂	88.61	X
30	1	BONNET HINGE LH	\$	B ₁	348.31	—
31	1	BONNET HINGE RH	\$	B ₁	348.31	—
32	1	BONNET LOCK	\$	K	305.48	X
33	1	BONNET CABLE	\$	S ₂	119.19	X
34	1	BONNET CABLE COVER	\$	S ₂	161.03	X
35	1	BONNET SEAL OUTER	\$	S ₂	92.36	X
36	1	BONNET SEAL INNER	\$	S ₂	157.28	X
37	1	FENDER PANEL FRT LH	\$	B ₁	783.83	✓
38	1	WHEELARCH FRT LH	\$	S ₂	278.84	} X
39	1	FENDER BRACKET LOWER LH	\$	S ₂	15.79	
40	1	FENDER INSULATOR LH	\$	S ₂	130.84	
41	1	FENDER INSULATOR RH	\$	S ₂	130.84	
42	1	WIPER RESERVOIR	\$	S ₂	348.25	
43	1	WIPER RESERVOIR NECK	\$	S ₂	136.11	
44	1	WIPER RESERVOIR MOTOR	\$	S ₂	270.06	
45	1	AIR CLEANER LOWER	\$	S ₂	271.26	
46	1	AIR CLEANER HOSE	\$	S ₂	76.14	
47	1	BASE BATTERY TRAY	\$	S ₂	363.40	
48	1	AIR CLEANER BOX	\$	S ₂	464.20	
49	1	TURBO DUCT	\$	S ₂	1,027.80	
50	1	A/C HEATER VALVE	\$	S ₂	484.50	
51	1	SUBFRAME OUTER FRT	\$	S ₂	2,652.45	
52	1	SUBFRAME BRACKET OUTER LH	\$	S ₂	92.36	
53	1	ENGINE UNDERTRAY	\$	S ₂	564.98	
54	1	A/C CONDENSER	\$	S ₂	2,020.37	
55	1	A/C CONDENSER GARNISH LH UPPER	\$	S ₂	39.67	
56	1	A/C CONDENSER GARNISH RH UPPER	\$	S ₂	39.67	
57	1	A/C CONDENSER GARNISH LH	\$	S ₂	58.81	
58	1	A/C CONDENSER GARNISH RH	\$	S ₂	59.60	
59	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	S ₂	208.39	
60	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S ₂	658.72	
61	1	A/C PIPE COMPRESSOR	\$	S ₂	334.29	
62	1	A/C PIPE	\$	S ₂	658.72	
63	1	A/C COMRPRESSOR	\$	S ₂	2,684.61	
77	1	AIR COOLER	\$	S ₂	792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	S ₂	1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	S ₂	375.14	

Trans-cab Auto Services Pte Ltd**AAD1803-233**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T

80	1	TRANSMISSION COOLER	\$	Sm	1,219.30	}
81	1	TRANSMISSION COOLER PAD	\$	Sm	17.96	
82	1	RADIATOR	\$	Sm	1,202.20	
83	2	RADIATOR STUD UPPER	\$	Sm	14.41	
84	2	RADIATOR BUSH UPPER	\$	Sm	50.12	
85	2	RADIATOR MTG LOWER	\$	Sm	55.85	
86	1	RADAIOR FAN COWLING	\$	Sm	820.54	
87	1	RADIATOR FAN MOTOR LH	\$	Sm	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	Sm	1,479.46	
89	1	RADIATOR TANK	\$	Sm	324.62	
90	1	RADIATOR HOSE UPPER	\$	Sm	240.56	
91	1	RADIATOR HOSE LOWER	\$	Sm	491.18	
92	1	RADIATOR TANK HOSE	\$	Sm	61.18	
93	1	AUTO COMPUTER	\$	Sm	5,032.17	
94	1	INJECTION COMPUTER	\$	Sm	4,706.30	
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sm	5,154.52	
96	1	STEERING PUMP ELECTRIC L70Y	\$	Sm	2,306.90	
97	1	STEERING PINION RACK L70Y	\$	Sm	4,413.11	
98	1	DOOR PANEL FRT LH	\$	nn	2,844.66	
99	1	LOWER ARM LH L70Y	\$	Sm	685.76	
100	1	KUNCKLE ARM LH L70Y	\$	Sm	846.98	
101	1	ABSORBER FRT LH L70Y	\$	Sm	360.54	
102	1	AIR CLEANER BOX	\$	Sm	464.20	
103	1	AIR CLEANER HOSE	\$	Sm	175.85	
104	1	DOOR HARNESS WIRE LH	\$	Sm	2,670.00	
105	1	DOOR MIRROR ASSY LH	\$	Sm	1,483.40	
106	1	DOOR PANEL FRT LH	\$	nn	2,844.66	
TOTAL			\$		70,862.14	
10%			\$		7,086.21	
			\$		63,775.92	

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	—
2	1SET	BUMPER CLIP FRT	\$	nn	66.00	—
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	X

Trans-cab Auto Services Pte Ltd**AAD1803-233**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T

6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	}
7	1	TOW COVER FRT	\$	na	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
13	1	Windscreen moulding	\$	na	100.00	
14	1SET	Front licence plate with holder	\$	na	80.00	
15	1	Front left tyre	\$	na	330.00	
16	1	Front left tyre rim	\$	na	380.00	}
17	1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	
18	1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	

TOTAL	\$	1,402.50
TOTAL PARTS	\$	65,178.42

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 5,400.00 *600*

Towing Fees.

\$ 120.00 *50*

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 *X*

Putty and spray painting of the affected portion.

\$ 6,000.00 *800*

To rust-proofing of the affected areas.

\$ 170.00 *90*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 *X*

To check steering geometry and computer wheel alignment

\$ na 220.00 *X*

Trans-cab Auto Services Pte Ltd**AAD1803-233**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T

To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To lift-up engine with gear box and refit.	\$	440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 X
To remove and refit air bag system and reset.	\$	480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 1001
To replace, refix and top up coolant for radiator	\$	170.00 501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X

LKK Auto Consultants hence notify

Water Seepage Test following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 16,400.00**Over All Total \$ 81,578.42****Repair Days (LUMP SUM)****20 DAYS**

4 days