

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Not Authorised
U/Sing & ?
McQueen After Paint
5 days

Date: 29/08/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: HONDA CIVIC / SJR9599S	
1 pc	rear boot lid <i>Br ✓</i>	
1 pc	rear boot lock <i>In -</i>	
1 pc	rear boot lock catch <i>?</i>	
2 pcs	rear boot lamp assy <i>Old M nls ?</i>	@
2 pcs	rear boot hinges <i>Rx</i>	@
1 pc	rear boot weather strip <i>?</i>	
1 pc	rear logo emblem <i>Mc -</i>	
1 pc	rear "CIVIC" emblem <i>Mc -</i>	
1 pc	rear "1.8" emblem <i>Mc -</i>	
1 pc	rear "i-VTEC" emblem <i>Mc -</i>	
1 pc	rear bumper <i>Br -</i>	
2 pcs	rear bumper side retainer <i>Dist -</i>	@
8 pcs	rear bumper clips <i>Mc -</i>	@
1 pc	rear end panel <i>?</i>	
1 pc	rear end panel garnish <i>?</i>	
2 pcs	rear tail lamp assy <i>Old M nls ?</i>	@
2 pcs	rear tail lamp lower bracket <i>?</i>	@
1 pc	rear spare tyre top board <i>Sn x</i>	
1 pc	rear exhaust silencer <i>Rx</i>	
	Sub-total	0.00
	Less %	0.00
	Sub-total	0.00
1 set	reverse sensor <i>Old 2005 s.nett</i>	
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	750.00 ?
	sub-total	750.00

	balance brought forward.	750.00
	To check wiring system.	201 40.00
	To spray painting on affected areas.	601 800.00
	To apply water proof sealant on affected areas.	201 601 90.00
	To apply rust proofing.	601 110.00
	To install reverse sensors.	501 80.00
	Total	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: