

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Not Ashanti
C/Sing 83450h
P/Sing After Paint
5 days

Date: 29/08/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: HONDA CIVIC / SJR9599S		
1 pc	rear boot lid <i>At ✓ 760.00</i>	830.60
1 pc	rear boot lock <i>Th- 164</i>	286.50
1 pc	rear boot lock catch <i>?</i>	82.30 <i>X</i>
2 pcs	rear boot lamp assy <i>o/s m 224.50 @ 284.10</i>	568.20
2 pcs	rear boot hinges <i>Rx</i>	387.40
1 pc	rear boot weather strip <i>?</i>	186.30 <i>50h</i>
1 pc	rear logo emblem <i>mc-</i>	22.60
1 pc	rear "CIVIC" emblem <i>mc-</i>	49.70
1 pc	rear "1.8" emblem <i>mc-</i>	53.80
1 pc	rear "i-VTEC" emblem <i>mc-</i>	55.20
1 pc	rear bumper <i>Br- 738.00</i>	863.10
2 pcs	rear bumper side retainer <i>o/s-</i>	105.60
8 pcs	rear bumper clips <i>mc-</i>	20.40
1 pc	rear end panel <i>7 400.50</i>	483.70
1 pc	rear end panel garnish <i>7 112.40</i>	818.80
2 pcs	rear tail lamp assy <i>o/s m 308.10 @ 397.30</i>	794.60
2 pcs	rear tail lamp lower bracket <i>?</i>	85.40 <i>X</i>
1 pc	rear spare tyre top board <i>mc X</i>	285.00
1 pc	rear exhaust silencer <i>mc X</i>	485.90
Sub-total		6,346.80
Less 20%		1,269.36
Sub-total		5,077.44 0.00
1 set	reverse sensor <i>o/s 2005 s.nett</i>	
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		750.00 <i>600h</i>
sub-total		750.00

balance brought forward.	750.00
To check wiring system.	201 40.00
To spray painting on affected areas	600 600.00
To apply water proof sealant on affected areas.	201 61 90.00
To apply rust proofing.	601 110.00
To install reverse sensors	501 80.00
Total	