

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

30-Aug-18

## ESTIMATE REPAIR BILL FOR MERCEDES W212 REGN NO: SHD 1919 C

1 pc	Rear bumper	\$	1,105.60
1 pc	Rear bumper lower garnish	\$	165.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$70.00	\$	140.00
			<hr/>
			\$ 1,410.60
Less 10%			\$ 141.06
			<hr/>
			\$ 1,269.54

### S/NETT

1 set	Rear bumper clips	\$	48.00
Sundry			
			\$ <del>50.00</del> X
To dismantle / replace reverse sensor to new bumper and reset to the same			\$ <del>120.00</del> 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$ <del>180.00</del> X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of same, etc.			\$ <del>600.00</del> 200
To putty and spray painting on rear bumper, rear bumper lower garnish			\$ <del>500.00</del> 360
To apply rustproofing on the repaired and replaced panels.			\$ <del>120.00</del> X
			<hr/>
			\$ 2,887.54

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Kahr Ukk

30/8/18 1645hrs

2 Pys.

U/S

After Repair photo