

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18015861/NPA3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00001090

Claimant
Vehicle No : SG1104R **Insured Vehicle No :** SKW5696H

Date of Loss: 18/08/2018 **Nature of Claim:** TP **Claim No:** 1201800010433

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SG1104R

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D AT TURBO ABS (A)

Engine No: 902926C1105545

Reg. Date: 02/06/2016 (Man. Year: 2015)

Chassis No: WEB62808323130486

Colour: White

Odometer: 205037 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 **Rear Tyre Size:** 275/70 R22.5
Front Left Side: Firenza 5 mm **Rear Left Side:** Continental 7 mm
Front Right Side: Firenza 5 mm **Rear Right Side:** Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,492.00	830.00	662.00	44.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,492.00	830.00	662.00	44.37
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 30/08/2018

Date Inspected: 30/08/2018 **Inspected At:**

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Nov 2019)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D AT TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG1104R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR RH REAR PORTION	New	1,060.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	432.00	300.00
Gross Labour Cost (\$\$)			1,492.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >