LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Josey Loh Date: 31 Aug 2018

Preliminary Advice

Insured Vehicle No : FBM1794T

TP Vehicle No : YN9476G Accident Date : 28/08/2018

Make : MITSUBISHI CANTER Assignment Date : 30/08/2018

Date of Inspection : 30/08/2018 Est. Duration of Repair : 2 days

Inspection At : Cheng Motor Work Co. (HQ)

1 KAKI BUKIT AVE 6 #01-83

Singapore 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesO/S front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,593.20
Revised Amount	:S\$	1,135.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,135.25

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.