

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185/6 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

FWD Insurance Singapore Pte. Ltd.

30/8/2018

6 Temasek Boulevard

#18-01 Suntec Tower Four

Singapore 038986

Attn: motor claims Dept

Estimate Cost of repair vehicle no: YN 9476G

Front Signal lamp R/h

car 266.00 —

Front side lamp

11 222.00 x

Front side garnish

12 506.00 x

Front bumper side

car 341.00 —

Front step garnish

11 613.00 x

25%

\$1948.00

Less 10%

194.80

\$1753.20

To check wiring

40.00 20

Labour for knocking, replaced of Parts

300.00 280

To spray paint on front door, side garnish

500.00 380

Total \$2593.20

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorised
2/8/18
tel. 62563561
2 days. After 11 days
the price after 11 days
p/p 9