



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLU9042S

Date of Accident : 24 August 2018

Not Allowed

LKK

30/8/18

Take photo After repair

P/P \$810

2dy.

Mr Zainal Bin Tahir

Date : 30 August 2018

Estimate To Repair SLA7201T - Mitsubishi Lancer EX 1.6 AT LED TAIL LAMP

Chassis No : JMYSRCY1AGU004027

S/No	Quantity	Description	Amount
NETT ITEMS			
01	1 pc	rear bumper	\$ 669.00
02	1 pc	rear bumper reinforcement	\$ 173.00
03	2 pc	rear bumper side retainer @ \$13.00	\$ 26.00
04	1 pc	rear bumper side holder	\$ 23.00
05	6 pc	rear bumper clips @ \$4.00	\$ 24.00
06	1 pc	rear bumper tow cover	\$ 18.00
07	1 pc	rear license plate lamp	\$ 30.00
Less 10 %			\$ 96.30
			\$ 866.70
SPECIAL NETT ITEMS			
08	1 pc	rear bumper parking sensor	\$ <i>SVC</i> 450.00
09	1 pc	rear license plate	\$ <i>75</i> 60.00
10	1 pc	reverse camera	\$ <i>SVC</i> 450.00
			\$ 960.00
LABOUR & MISC. CHARGES			
01		To reinstall of rear bumper sensor and reverse camera.	\$ 180.00
02		To check electrical lighting concerned.	\$ 60.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
04		Putty and spray painting of the affected portion.	\$ 550.00
			\$ 1,290.00
Total			\$ 3,116.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: