

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

longpac

Owner : Mohammad Farouqshk
Bin Iskandar Dzulkarnain

Accident Date : 21 Aug 2018

Vehicle No : FBL 893 C

Vehicle Model : Yamaha FZN150

Not Affected
2/SS
4 di
70kg 2000 1100 1200
29/8/18

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
1	Front fender	\$ <i>12</i> 75.00 <i>X</i>
2	Fork inner tubes	\$ <i>12</i> 370.00 <i>X</i>
2	Fork outer tubes	\$ <i>12</i> 390.00 <i>X</i>
1	Fork under bracket	\$ <i>11</i> 232.00 <i>X</i>
1	Front rim shaft	\$ <i>41</i> 42.00 <i>—</i>
1	Front brake disc	\$ <i>17</i> 150.00 <i>X</i>
1	Front sport rim	\$ <i>17</i> 320.00 <i>X</i>
1	Headlamp	\$ <i>17</i> 185.00 <i>X</i>
1	Front signal -L/H	\$ <i>62</i> 60.00 <i>—</i>
1	Front side cowling -L/H	\$ <i>62</i> 135.00 <i>—</i>
1	Side mirror	\$ <i>62</i> 80.00 <i>—</i>
1	Handle bar	\$ <i>13</i> 85.00 <i>—</i>
1	Handle bar end	\$ <i>62</i> 28.00 <i>—</i>
1	Clutch lever	\$ <i>62</i> 28.00 <i>✓</i>
1	Hand grip (1 set)	\$ <i>17</i> 80.00 <i>X</i>
1	Meter assy	\$ <i>62</i> 425.00 <i>—</i>
1	Fuel tank side cover	\$ <i>62</i> 235.00 <i>—</i>
1	Front footrest -L/H	\$ <i>11</i> 35.00 <i>X</i>
1	Front footrest bracket	\$ <i>31</i> 45.00 <i>—</i>
1	Gear pedal	\$ <i>11</i> 48.00 <i>—</i>
1	Rear footrest -L/H	\$ <i>62</i> 35.00 <i>—</i>
1	Rear footrest bracket	\$ <i>31</i> 60.00 <i>—</i>
1	Rear tailboard	\$ <i>62</i> 155.00 <i>—</i>
2	Rear signals	\$ <i>17</i> 110.00 <i>X</i>
1	Rear fender	<i>negot/\$</i> <i>21</i> 70.00 <i>—</i>
1	Side stand	\$ <i>31</i> 75.00 <i>—</i>
1	Main stand	\$ <i>12</i> 90.00 <i>X</i>
1	Rear fender reflector	\$ <i>17</i> 50.00 <i>X</i>
1	Rear rim	\$ <i>12</i> 280.00 <i>X</i>
		\$ 3,973.00
	Less 10%	\$ 397.30
		\$ 3,575.70

Special Nett Items

1	Number plate (1 set)	\$	54	28.00	20
2	Fork oils	\$	24	30.00	—
2	Fork oil seals	\$	24	56.00	—
1	Steering cone (1 set)	\$	11	90.00	2
1	Rear box	\$	64	250.00	1A
1	Rear box bracket	\$	1	100.00	2
1	ERP IU	\$	51	175.00	2
1	Helmet	\$	64	120.00	20
		\$		849.00	

S/No. Labour

1	To provide towing service.	\$		50.00	35
2	To check wiring and reset headlamp focusing.	\$	11	80.00	2
3	To provide labour.	\$		380.00	280
		\$		510.00	

Grand Total

\$ 4,934.70

Dollars: Four Thousand Nine Hundred Thirty-Four And Seventy Cents Only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: