



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17015460/Bqbs2-1

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 11-09-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 8882P	Veh. Inspected	SGL 3126E
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020040	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	30/08/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. M5	c.c	4999
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	WBSNB92030CU18111	Colour	GREEN
Odometer	148076	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35R20	MICHELIN	6 mm
L/H Front Tyre	255/35R20	MICHELIN	6 mm
R/H Rear Tyre	295/30R20	PIRELLI	6 mm
L/H Rear Tyre	295/30R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/08/2017	Inspection Date	11/08/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------